



-2-

1949. A SLIGHT PLUS DENSITY BAND PARALLEL TO AND 2.6" FROM THE OUTBOARD EDGE APPEARS IN FRAME 1244 AND CONTINUES TO FRAME 1347 WHERE THE BAND CHANGES TO MULTIPLE PLUS DENSITY STREAKS THROUGH THE REST OF THE MISSION. THE MOST PREDOMINANT STREAK IS PRESENT 2.2" FROM THE OUTBOARD EDGE. SLIGHT FOG THAT IS EVIDENCE OF INTERNAL REFLECTION FROM THE CAMERA FORMAT MASK APPEARS ALONG THE SUPPLY EDGE AND THE OUTBOARD TAKE-UP CORNER OF THE FORMAT THROUGHOUT THE MISSION. A WAVERING EMULSION SCRATCH APPROXIMATELY PARALLEL TO THE MAJOR AXIS AND 3.2" TO 4" FROM THE OUTBOARD EDGE IS PRESENT IN FRAMES 1490 TO 1492 AND 1494 TO 1497. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 0301/0302, 0682/0683, 1501/1502, 2110/2111, 2116/2117, 2128/2129, AND THROUGH THE FORMAT OF FRAME 1237. A MANUFACTURING SPLICE WITH ASSOCIATED PINHOLES AND FOG EXISTS IN FRAME 1897.

D. BOTH SIDES OF THE MISSION CONTAIN VERY MINOR PROCESSING STREAKS. THE DATA CHAMBER MISLABELS THE MISSION AS 8111. THE FILM; HOWEVER, WAS TITLED CORRECTLY AS 8110. THE COUNTER IN THE DATA CHAMBER DID NOT CHANGE BETWEEN FRAMES TITLED 0001 AND 0002. EACH SIDE IS TITLED CORRECTLY FROM 0001 TO 2320.

E. NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS OCCURRED DURING THE MISSION.

3. POSITIVE:

- A. THE PI SUITABILITY IS GOOD.
- B. THE PRINTING AND PROCESSING IS GOOD.
- C. CLOUDS DEGRADED OR OBSCURED 45 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--