

OUT57222

multis

P 1920
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND ND
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2 AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 5957.

1965 NOV 19 21 37Z

22 NOV 1965

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	TID	✓
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI)

1. CAMERA B 7 WAS USED IN MISSION 8056 FLOWN ON 16 NOVEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.
2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD EXCEPT WHERE DEGRADED BY SMEAR POSSIBLY CAUSED BY VIBRATIONS IN THE CAMERA.

B. 9R SIDE: TWO ROLLS OF MINUS DENSITY DOTS, LOCATED 0.6" FROM THE INBOARD EDGE, 2.5" FROM THE OUTBOARD EDGE, AND 1.6" APART, OCCUR THROUGHOUT THE MISSION. AN EMERGENCY CUT WAS MADE ACROSS FRAME 1322 DURING PROCESSING. THE CUT WAS REPAIRED WITH CLEAR MYLAR TAPE AND A HEAT SPLICE. MANY PLUS AND MINUS DENSITY STREAKS PARALLEL TO THE MAJOR AXIS, ARE PRESENT FROM FRAME 1322 TO THE END OF THE MISSION. WAVERING, IRREGULAR PLUS DENSITY STREAKS OCCUR ON EVERY FRAME BETWEEN 1399 AND 2413. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 496/497 AND THROUGH FRAME 1182. MANUFACTURING SPLICES ARE PRESENT ON FRAMES 1041 AND 1660.

Advanced copy
Sanitized

Declass Review by NGA

SECRET

EXCLUDED FROM AUTOMATIC
 DOWNGRADING AND
 DECLASSIFICATION

C. 9L SIDE: WAVERING PLUS DENSITY STREAKS OCCUR INTERMITTENTLY NEAR THE INBOARD EDGE DURING THE FIRST 500 FRAMES AND FROM FRAME 1086 TO 1101. NUMEROUS PLUS AND MINUS DENSITY STREAKS PARALLEL TO THE MAJOR AXIS OCCUR INTERMITTENTLY THROUGHOUT THE MISSION. AN AREA OF FOG LOCATED NEAR THE OUTBOARD EDGE AND IN THE TAKE-UP CORNER OF THE FRAME IS PRESENT ON FRAMES 120, 249 AND 341. HEAT SPLICES ARE LOCATED THROUGH FRAME 1083 AND BETWEEN FRAMES 1122/1123. A MANUFACTURING SPLICE IS PRESENT ON FRAME 560.

D. BOTH SIDES: EDGE FOG IS PRESENT ALONG BOTH EDGES. ROLLER CHATTER OCCURS ALONG BOTH EDGES BUT IS MINOR AND INTERMITTENT ON THE OUTBOARD EDGE. A FEW PINHOLES AND EMULSION BLISTERS ARE NOTED DURING THE MISSION. THE LAST TITLED FRAME IS 2507.

E. THERE ARE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS EXCEPT AS NOTED ON THE 9R SIDE.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY SMEAR. THE PI'S SPECIFICALLY MENTIONED THE PRESENCE OF SMEAR IN THE 1R POSITION.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURED OR DEGRADED APPROXIMATELY 25 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/