

SECRET

OUT57060

1965 NOV 4 22 40Z

multi

P 042217Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4030 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 5801.

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 7 WAS USED IN MISSION 3052 FLOWN ON 2 NOVEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

5 NOV 1965

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD IN THE VERTICAL POSITIONS. HOWEVER, THE 1R AND 1L APPEAR TO BE SLIGHTLY DEGRADED.

B. 9R SIDE: EDGE STATIC OCCURS ALONG THE OUTBOARD EDGE THROUGHOUT THE MISSION. MANUFACTURING SPLICES ARE PRESENT ON FRAME 232 AND 2150. CUTS MADE DURING PROCESSING AND REPAIRED WITH HEAT SPLICES ARE LOCATED ON FRAME 1328, BETWEEN FRAMES 1358/1359 AND 1703/1704. SIX MINUS DENSITY STREAKS, ONE INCH APART AND PARALLEL TO THE MAJOR AXIS, BEGIN AT THE HEAD OF THE MISSION AND ARE CONTINUOUS TO THE HEAT SPLICE ON FRAME 1358. THE FIRST STREAK IS LOCATED 1.1" FROM THE OUTBOARD EDGE. BEGINNING ON FRAME 1359 AND THROUGH THE REMAINDER OF THE MISSION ONLY FOUR MINUS DENSITY STREAKS OCCUR, THE FIRST LOCATED 2.3" FROM THE INBOARD EDGE. SEVERAL PLUS DENSITY STREAKS ARE NOTED NEAR THE END OF THE MISSION. THESE PLUS

DISTRIBUTION		
Cy No.	Office	Action
1	File	
	OS	
	ADMIN	
	SEC DR	
	PL & CS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
	STID	✓
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy Sanitized

Declass Review by NGA

SECRET

AND MINUS STREAKS APPEAR TO BE PROCESSOR INDUCED. AN INTERMITTENT AND IRREGULAR PLUS DENSITY STREAK LOCATED 2.7" FROM THE OUTBOARD EDGE AND RUNNING ROUGHLY PARALLEL TO THE MAJOR AXIS, OCCURS DURING THE FIRST HALF OF THE MISSION.

C. 9L SIDE: SEVERAL LONGITUDINAL PLUS DENSITY STREAKS ARE LOCATED 4.3" TO 7.0" FROM THE INBOARD EDGE AND ARE PRESENT ON FRAMES 1 THROUGH 18. ON FRAME 18 THEY DECREASE IN NUMBER AND THE LAST WAS NOTED ON FRAME 153. FRAMES 1681 THROUGH 1920 CONTAIN A BASE SCRATCH LOCATED 3.0" FROM THE OUTBOARD EDGE. AN IRREGULAR PLUS DENSITY STREAK PROBABLY ASSOCIATED WITH THE ROLLER CHATTER IS PRESENT ON FRAMES 2240 THROUGH 2307. THE LACQUER IS SMEARED ON THE TITLE EDGE ON FRAMES 711 THROUGH 916. TITLE FLAKING OCCURRED ON FRAME 240 AND FRAMES 1373 THROUGH 1386. THE TITLING IS SMEARED ON FRAMES 719 AND 720. MINUS DENSITY COMETS APPEAR INTERMITTENTLY THROUGHOUT. NOTE FRAMES 897, 1617 AND 2057. LONGITUDINAL ABRASIONS ARE PRESENT ON THE EMULSION OF FRAME 1201. MANUFACTURER'S SPLICES ARE PRESENT ON FRAMES 176 AND 2592 WITH ASSOCIATED EDGE FOG ON THE ADJACENT FRAMES. HEAT SPLICES ARE LOCATED BETWEEN FRAMES 1325/1324, 1532/1533 AND 1541/1542.

D. BOTH SIDES: THE VERTICAL DOT INDICATOR IS BLOOMED. EDGE FOG AND ROLLER CHATTER ARE PRESENT THROUGHOUT. PINHOLES AND EMULSION LIFTS APPEAR INTERMITTENTLY THROUGHOUT. THE FRAMES ARE TITLED 0001 TO 2721. THE CLOCK COUNTER BEGAN AT 0001 AND THE SECOND FRAME WAS 0003. THE TITLED FRAMES WERE LIKEWISE WITH THE SECOND FRAME BEING TITLED 0003.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS FAIR TO GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE AND OBSCURE APPROXIMATELY 60 PERCENT OF
THE MISSION.

S E C R E T

/END OF MESSAGE/