

13 Nov 70

- ✓ 1) Transport motor failure. Done
- ✓ 2) Adjust ball detent Done
- ✓ 3) Get rid of 250 VAC on Done with
circuit board for teller tape
- ✓ 4) Mechanical steps on elevating slide
mechanism $3/4$ tilt to step (Comp. 18 Nov.)
- ✓ 5) Capture screws holding 70 mm
guides on table.
Will bottom screws and fix (Comp. 18 Nov. to try to fix)
- ✓ 6) Remove sharp corners from tilt Done
switch.
- ✓ 7) Larger diameter knurl on optics and
rod hold-down. (Comp. 18 Nov.)
- STAT ✓ 8) Morgan will send 180° protractor. Not here
[] will supply these for Morgan.
Will supply for Morgan but not Dave.
- ✓ 9) Serial numbers will be near Done
fans on outside A (tilt)
- ✓ 10) UV certification will be supplied.

(Comp. 20 Nov.)

✓ 11) Lower cover locks will be changed for the better. ^{Some previous cases to me} Investigating - think have answer (Comp. 17 Nov)

? 12) Schematic will not be of back cover, but will be in maintenance manual. ^{AT may need schematic} _{STAT}

Still on file 13) focus mechanism drifts downward ^{locking into place (comp. chuter) - working on with supplier} 19 Nov. Possibility of delivery problem - will appear in manual. _{STAT}

? 14) X-Y cable & Y drive cable ^{interfere with carriage motion.} _{Looking at problem - (Comp. 17 Nov.)}

? 15) Lifting of optics without cranking ^{is too difficult, child may require too much force.} _(Comp. 17 Nov.)

✓ 16) Optics mount (focus ~~mount~~ mechanism) will not go thru focus range for 2x Rhomboid. _{Looking into - (Comp. 17 Nov.)}

STAT 17) will explore $3 \pm \frac{1}{2}$ " spec for Y manual horizontal motion to assure smooth operation. _{Looking into - feel they have a tolerance}
 _{Micropitch down (Comp. 17 Nov.)}

STAT 18) will investigate the differential between the X, Y, & diagonal ~~movement~~ motorized movement. The present _{management}
 _{Improved satisfactory} _{management} _{considers this mfg spec.}

STAT

on cost.
Claim must have separate
feedback systems for both \times and y .
The z axis is not
system is unacceptable.

STAT

control during
of both steering
during control of
Nov 68

(9) [] ~~with~~ is currently investigating
the play in y -locking action.
1/16" Current play is unacceptable
to sponsor. Clutch will be
shooting for rock solid - control of y movement is less

✓ (20) Clearance will be increased
between manual elevation crank
and side of table. Presently it Done
is less than 0.125 inches.

2 1/4 turns (21) Dead rotation will be reduced
in rate control. Will adjust
to 1 turn (Comp. 17 Nov)

✓ (22) Interference between optics
and controls on rear deck will
be eliminated downstream.

? (23) In consideration of ~~downstream~~ ^{for down} ~~locking up~~ ^{locking up} clutches to ~~provide~~ ^{provide} positive lock without friction
locks being applied. Explore this
possibility - no extra cost or
change of scope allowed.

Added Cost involved because of
equipment changes (Will advise re dev)

? 24) The focus mechanism must meet motion requirements as per paragraph 3.5.1 of the ~~FE~~ technical requirements. It does not, at this time (see item 16). ~~It will do~~ (Comp. & Dev)

✓ 25) Rhomboids not best of design - mount ~~that can~~ ~~be~~ ~~done~~ by ~~controlling~~ ~~each~~ (Comp. & Dev)