

50X1-HUM

Page Denied

INFORMATION REPORT INFORMATION REPORT

CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

S-E-C-R-E-T
NO FOREIGN DISSEM 50X1-HUM

COUNTRY	USSR	REPORT	
SUBJECT	Wiring Diagrams and Calibration Charts for the Soviet RBP-4 Radar Gunsight (MUSHROOM)	DATE DISTR.	5 March 1964
		NO. PAGES	1 50X1-HUM
		REFERENCES	
DATE OF INFO.			
PLACE & DATE ACQ.			

THIS IS UNEVALUATED INFORMATION. SOURCE GRADINGS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.

a copy of an English-language Soviet manual entitled Set of Diagrams: Supplement to Operating Instructions of RBP-4 Radar Bombsight
The album contains 16 insets, all of which were classified SECRET by the Soviets. Insets 1 through 11 contain wiring diagrams; insets 12 through 16 consist of calibration charts.

Distribution of Attachment for Retention:

- Army: 2 copies
- Army/FSTC: 3 copies
- Navy: 4 copies
- Navy/STIC: 3 copies
- Air: 4 copies
- Air/FTD: 6 copies (1 previously forwarded)
- SAC: 1 copy
- NSA: 6 copies
- OSI: 2 copies
- ORR: 2 copies

5
4
3
2
1

S-E-C-R-E-T
NO FOREIGN DISSEM

GROUP 1
Excluded from automatic
downgrading and
declassification

STATE	DIA	ARMY	NAVY	AIR	NSA	XXX NIC		50X1-HUM
								50X1-HUM

(Note: Field distribution indicated by "#".)

INFORMATION REPORT INFORMATION REPORT

50X1-HUM


SECRET
NO FOREIGN DISSEM



SET OF DIAGRAMS
SUPPLEMENT TO OPERATING INSTRUCTIONS
OF RBP-4 RADAR BOMBSIGHT

(English Language)

SECRET
NO FOREIGN DISSEM



50X1-HUM

50X1-HUM

SECRET

50X1-HUM

SET OF DIAGRAMS

(Supplement to Operating Instructions
of РБП-4 Radar Bombsight)

SECRET

NO FOREIGN DISSEM

CONTENTS

(All insets are secret)

WIRING DIAGRAMS OF UNITS

Inset No. 1

- Fig. 59. Wiring diagram of unit P1.
- Fig. 60. Wiring diagram of PYU panel in unit P2.

Inset No. 2

- Fig. 61. Wiring diagram of unit P2.

Inset No. 3

- Fig. 62. Wiring diagram of unit P3.

Inset No. 4

- Fig. 63. Wiring diagram of panel No. 1 in unit P3.
- Fig. 64. Wiring diagram of panel No. 2 in unit P3.
- Fig. 65. Wiring diagram of panel No. 3 in unit P3.

Inset No. 5

- Fig. 66. Wiring diagram of unit P4.

Inset No. 6

- Fig. 67. Wiring diagram of YU panel in unit P4.
- Fig. 68. Wiring diagram of AU panel in unit P4.
- Fig. 69. Wiring diagram of sweep panel in unit P4.
- Fig. 70. Wiring diagram of video-amplification panel in unit P4.

Inset No. 7

- Fig. 71. Wiring diagram of unit P5.
- Fig. 72. Wiring diagram of unit P6.

Inset No. 8

- Fig. 73. Wiring diagram of unit P7.

Inset No. 9

- Fig. 74. Wiring diagram of panel No. 1 in unit P7.
- Fig. 75. Wiring diagram of panel No. 2 in unit P7.
- Fig. 76. Wiring diagram of panel No. 3 in unit P7.
- Fig. 77. Wiring diagram of unit P8.
- Fig. 78. Wiring diagram of unit P9.

Inset No. 10

- Fig. 79. Wiring diagram of unit P10.
- Fig. 80. Wiring diagram of unit P11.
- Fig. 81. Wiring diagram of unit P12.
- Fig. 82. Wiring diagram of modulator valves panel in unit P12.

Inset No. 11

- Fig. 83. Wiring diagram of unit P13.
- Fig. 84. Wiring diagram of unit P14.
- Fig. 85. Wiring diagram of internal connections in unit P15.
- Fig. 86. Wiring diagram of external connections in unit P15.

CALIBRATION CHARTS OF UNITS

Inset No. 12

- Fig. 87. Calibration chart of unit P1.
- Fig. 88. Calibration chart of resistors in unit P2.
- Fig. 89. Calibration chart of voltages in unit P2.
- Fig. 90. Calibration chart of PYU panel in unit P2.

- Fig. 91. Calibration chart of resistors in unit P3.
- Fig. 92. Calibration chart of voltages in unit P3.
- Fig. 93. Calibration chart of pulses in unit P3.

Inset No. 13

- Fig. 94. Calibration chart of resistors in unit P4.

Inset No. 14

- Fig. 95. Calibration chart of voltages in unit P4.
- Fig. 96. Calibration chart of pulses in unit P4.
- Fig. 97. Calibration chart of YU panel in unit P4.

Inset No. 15

- Fig. 98. Calibration chart of AU panel in unit P4.
- Fig. 99. Calibration chart of units P5/1 and P5/2.
- Fig. 100. Calibration chart of unit P6.
- Fig. 101. Calibration chart of resistors in unit P7.
- Fig. 102. Calibration chart of voltages in unit P7.
- Fig. 103. Calibration chart of pulses in unit P7.
- Fig. 104. Calibration chart of unit P8.
- Fig. 105. Calibration chart of unit P9.
- Fig. 106. Calibration chart of unit P10.
- Fig. 107. Calibration chart of unit P11.


Inset No. 16

- Fig. 108. Calibration chart of resistors in unit P12.
- Fig. 109. Calibration chart of voltages in unit P12.
- Fig. 110. Calibration chart of modulator valves panel resistors in unit P12.

This album contains 22 pages and 16 insets on 16 sheets

Inset No. 1. Secret

WIRING DIAGRAMS OF UNITS



59. WIRING DIAGRAM OF UNIT P1






FIG. 60. WIRING DIAGRAM OF UNIT P3

SECRET



SECRET

NO FOREIGN DISSEM

Inset No. 2. Secret




FIG. 61. WIRING DIAGRAM OF UNIT P2

SECRET

NO FOREIGN DISSEM





FIG. 61. WIRING DIAGRAM OF UNIT P2

SECRET

NO FOREIGN DISSEM



SECRET

NO FOREIGN DISSEM




FIG. 64. WIRING DIAGRAM OF PANEL No. 2 IN UNIT P3




FIG. 65. WIRING DIAGRAM OF PANEL No. 3 IN UNIT P3

SECRET




FIG. 63. WIRING DIAGRAM OF PANEL No. 1 IN UNIT P3




FIG. 64. WIRING DIAGRAM OF PANEL No. 2




FIG. 65. WIRING DIAGRAM OF PANEL No. 3

SECRET

Draw No. 5, Secret





FIG. 56. WIRING DIAGRAM OF UNIT PA

SECRET



SECRET

Inset No. 6. Secret




FIG. 67. WIRING DIAGRAM OF YTH PANEL IN UNIT P4

SECRET

NO FOREIGN DISSEM





FIG. 67. WIRING DIAGRAM OF VPI PANEL IN UNIT P4

SECRET

NO FOREIGN DISSEM



SECRET

NO FOREIGN DISSEM




FIG. 69. WIRING DIAGRAM OF SLEEP PANEL IN UNIT P4




FIG. 70. WIRING DIAGRAM OF VIDEO-AMPLIFICATION PANEL IN UNIT P4







FIG. 72. WIRING DIAGRAM OF UNIT P6

SECRET



Declassified in Part - Sanitized Copy Approved for Release 2014/02/19 : CIA-RDP80T00246A071500320001-2



SECRET






FIG. 7A. WIRING DIAGRAM OF UNIT 7.

SECRET

NO FOREIGN DISSEM



SECRET

NO FOREIGN DISSEM




FIG. 74. WIRING DIAGRAM OF PANEL No. 1 IN UNIT P7




FIG. 75. WIRING DIAGRAM OF PANEL No. 2 IN UNIT P7




FIG. 76. WIRING DIAGRAM OF PANEL No. 3 IN UNIT P7

SECRET

NO FOREIGN DISSEM




FIG. 77. WIRING DIAGRAM OF UNIT PR

SECRET

NO FOREIGN DISSEM




FIG. 78. WIRING DIAGRAM OF UNIT P9

SECRET

NO FOREIGN DISSEM

Inset No. 10. Secret




FIG. 79. WIRING DIAGRAM OF UNIT P10








FIG. 80. WIRING DIAGRAM OF UNIT P11.

SECRET

NO FOREIGN DISSEM

FIG. 78. WIRING DIAGRAM OF UNIT P9



SECRET




FIG. 81. WIRING DIAGRAM OF UNIT P12.

SECRET






FIG. 82. WIRING DIAGRAM OF MODULATOR VALVES PANEL IN UNIT P12



13. WIRING DIAGRAM OF UNIT P13.



Inset No. 11. Secret




FIG. 83. WIRING DIAGRAM OF UNIT P13.




FIG. 84. WIRING DIAGRAM OF UNIT P14.

SECRET

NO FOREIGN DISSEM

INTERNAL CONNECTIONS DIAGRAM




FIG. 85. WIRING DIAGRAM OF INTERNAL CONNECTIONS IN UNIT P15.

SECRET

NO FOREIGN DISSEM

EXTERNAL CONNECTIONS DIAGRAM




FIG. 86. WIRING DIAGRAM OF EXTERNAL CONNECTIONS IN UNIT P15.

CALIBRATION CHARTS OF UNITS

Inset No 12 Secret

contacts of plug-nector III - 6 in which resistor is being measured	Rating values. Resistance	Measurement conditions
body	0	
body	25 ohms \pm 20%	
4-	DO	Extreme upper position
4-	DO	Extreme lower position
6-	500 ohms \pm 15%	Tilt 0°
7-	310 ohms \pm 15%	Tilt 0°
7-	280 ohms \pm 15%	Tilt 0°
10-	100 ohms \pm 15%	Position of unit along course line
body	50 ohms \pm 15%	do
10-body	50 ohms \pm 15%	do
11-2	0	do
12-2	0	Position of unit in sector 157° - 203°
14-2	0	do
18-body	DO	Position of unit in sector 90° - 270°

CALIBRATION CHART OF UNIT P1 MEASUREMENTS ARE TO BE EFFECTED BY ABO-5 INSTRUMENT




FIG. 88. CALIBRATION CHART OF RESISTORS IN UNIT P2

Instructions. 1. Resistors are to be measured with respect to body, besides points indicated in Table.
2. Resistors are to be measured with blocks being disconnected and valves taken out.
3. Resistor marked with 0* sign means resistor 0.5 ohm.
4. DO means resistor \geq 50 megohms.
5. DO is to be measured by megohmmeter for 250 V.
6. All other measurements are to be made with the help of ABO-5 instrument.
7. Resistor marked with sign** is to be measured by means of M-246 microohmmeter between terminal and body.
8. Measurements indicated by sign *** are to be effected by pressing plunger of electromagnet of corresponding klystron until contacts of contact group become disengaged.




FIG. 89. CALIBRATION CHART OF VOLTAGES IN UNIT P2.

Instructions. 1. Measurements are to be effected while cutting in high voltage but with


FIG. 90. CALIBRATION CHART OF IVTR PANEL IN UNIT P2

Instructions. 1. Measurements of resistors is to be effected with respect to body with valve being taken out.
2. Permissible tolerance of resistance value is \pm 10%.
3. Voltage tolerance for all points of calibration chart, unless specified otherwise, \pm 20%.
4. Measurements are to be effected by means of

SECRET

500 ohms $\pm 15\%$	Tilt 0°
310 ohms $\pm 15\%$	Tilt 0°
280 ohms $\pm 15\%$	Tilt 0°
100 ohms $\pm 15\%$	Position of unit along course line
50 ohms $\pm 15\%$	do
50 ohms $\pm 15\%$	do
0	Position of unit in sector 157° - 203°
0	do
0	Position of unit in sector 90° - 270°

FIG. 87. CALIBRATION CHART OF UNIT P1 MEASUREMENTS ARE TO BE EFFECTED BY ABO-5 INSTRUMENT



1	W2-1 - W2-2	15 ± 1.5 megohms
2	W2-1 - W2-3	0
3	W2-1 - W2-4	0.75 ± 0.14 megohms (with lead-in W2-4)
4	W2-1 - W2-5	0.75 ± 0.14 megohms (with lead-in W2-5)
5	W2-2 - W2-3	0
6	W2-2 - W2-4	approximately 7 ohms
7	W2-2 - W2-5	4.7 ± 0.5 megohms
8	W2-3 - W2-4	4.7 ± 0.5 megohms
9	W2-3 - W2-5	6 - 30 ohms (channel I)
10	W2-4 - W2-5	6 - 30 ohms (channel II)
11	W2-1 - W2-2	3.2 ± 0.3 ohms
12	W2-1 - W2-3	3.2 ± 0.3 ohms




FIG. 88. CALIBRATION CHART OF RESISTORS IN UNIT P2

Instructions. 1. Resistors are to be measured with respect to body, besides points indicated in Table.
2. Resistors are to be measured with blocks being disconnected and valves taken out.
3. Resistor marked with 0* sign means resistor < 0.5 ohm.
4. ∞ means resistor > 50 megohms.
5. ∞ is to be measured by megohmmeter for 250 V.
6. All other measurements are to be made with the help of ABO-5 instrument.
7. Resistor marked with sign** is to be measured by means of M-246 microhmmeter between terminal and body.
8. Measurements indicated by sign *** are to be effected by pressing plunger of electromagnet of corresponding klystron until contacts of contact group become disengaged.





FIG. 89. CALIBRATION CHART OF VOLTAGES IN UNIT P2
Instructions. 1. Measurements are to be effected while cutting in high voltage but with P2-12 fuse being taken out from P12 unit.
2. All voltages are given in volts.
3. Measurements on P2-1 and P2-2 are to be effected while cutting in high voltage but with P2-12 fuse being taken out from P12 unit.
4. Measurements from bottom side are given for reference.

FIG. 90. CALIBRATION CHART OF IVIIV PANEL IN UNIT P2

Instructions. 1. Measurement of resistors is to be effected with respect to body with valve being taken out.
2. Permissible tolerance of resistance value is $\pm 10\%$.
3. Voltage tolerance for all points of calibration chart, unless specified otherwise, $\pm 20\%$.
4. Measurements are to be effected by means of ABO-5 instrument.



CALIBRATION CHARTS OF UNITS

No.	Nos of contacts of plug-connector W1-6 between which resistance is being measured	Rating values. Resistance	Measurement conditions
1	1-body	0	
2	2-body	25 ohms \pm 20%	
3	3-4	DO	Extreme upper position
4	3-4	DO	Extreme lower position
5	5-6	500 ohms \pm 15%	Tilt 0°
6	5-7	310 ohms \pm 15%	Tilt 0°
7	6-7	280 ohms \pm 15%	Tilt 0°
8	9-10	100 ohms \pm 15%	Position of unit along course line
9	9-body	50 ohms \pm 15%	do
10	10-body	50 ohms \pm 15%	do
11	11-2	0	do
12	12-2	0	Position of unit in sector 157° - 203°
13	14-2	0	do
14	18-body	DO	Position of unit in sector 90° - 270°

FIG. 87. CALIBRATION CHART OF UNIT P1 MEASUREMENTS ARE TO BE EFFECTED BY ABO-5 INSTRUMENT




FIG. 88. CALIBRATION CHART OF UNIT P1. Instructions. 1. Resistance measurements are to be effected with respect to body, besides points of contact. 2. Resistors are to be measured with valves taken out. 3. Resistor marked with 0° means resistor > 50 ohms. 4. No is to be measured by M-246 microammeter between. 5. All other measurements of ABO-5 instrument. 6. Resistor marked with 0° means resistor > 50 ohms. 7. Measurements indicated by pressing plunger of electromagnet contacts of contact group.





FIG. 89. CALIBRATION CHART OF VOLTAGES IN UNIT P2. Instructions. 1. Measurements are to be effected while cutting in high voltage but with (in 12-1, 12-2, 12-3, 12-4, 12-5, 12-6, 12-7, 12-8, 12-9, 12-10, 12-11, 12-12, 12-13, 12-14, 12-15, 12-16, 12-17, 12-18, 12-19, 12-20, 12-21, 12-22, 12-23, 12-24, 12-25, 12-26, 12-27, 12-28, 12-29, 12-30, 12-31, 12-32, 12-33, 12-34, 12-35, 12-36, 12-37, 12-38, 12-39, 12-40, 12-41, 12-42, 12-43, 12-44, 12-45, 12-46, 12-47, 12-48, 12-49, 12-50, 12-51, 12-52, 12-53, 12-54, 12-55, 12-56, 12-57, 12-58, 12-59, 12-60, 12-61, 12-62, 12-63, 12-64, 12-65, 12-66, 12-67, 12-68, 12-69, 12-70, 12-71, 12-72, 12-73, 12-74, 12-75, 12-76, 12-77, 12-78, 12-79, 12-80, 12-81, 12-82, 12-83, 12-84, 12-85, 12-86, 12-87, 12-88, 12-89, 12-90, 12-91, 12-92, 12-93, 12-94, 12-95, 12-96, 12-97, 12-98, 12-99, 12-100).

FIG. 90. CALIBRATION CHART OF UNIT P2. Instructions. 1. Measurement of voltage is to be effected with respect to body with being taken out. 2. Permissible tolerance of resistance \pm 10%. 3. Voltage tolerance for all points of contact, unless specified otherwise, \pm 20%. 4. Measurements are to be effected by ABO-5 instrument.


SECRET



SECRET


NO FOREIGN DISSEM

FIG. 91. CALIBRATION CHART OF RESISTORS IN UNIT P4
Instructions. 1. Resistor ratings are given with respect to body.
2. Measurements are to be effected when the switch is set to OPERATION position (PABOTA).
3. Permissible tolerance of resistor value is $\pm 10\%$.
4. Measurements are to be effected by means of ABO-5 instrument or by like one with valves being taken out.
5. Resistor marked with sign * is measured by M-246 microohmmeter between terminal and body.
6. While measuring resistor marked with sign ** connect negative conductor to valve pin and positive one-to body.




SECRET

NO FOREIGN DISSEM




No.	Valve number	Number of pulses	Shape and amplitude of pulses	Conditions for measurement	No.	Valve number	Number of pulses	Shape and amplitude of pulses	Conditions for measurement	No.	Valve number	Number of pulses	Shape and amplitude of pulses	Conditions for measurement	No.	Valve number	Number of pulses	Shape and amplitude of pulses	Conditions for measurement
1	ПЗ-1	1			12	ПЗ-5	1			23	ПЗ-7	5		Delay 140 km.	34	ПЗ-10	1,6		Range delay 30 km.
2	ПЗ-1	2			13	ПЗ-2	1		During bench check	24	ПЗ-8	1		Step-delay zero	35	ПЗ-10	3		Range delay 2 km.
3	ПЗ-1	5			14	ПЗ-5	2		During complex check (for reference)	25	ПЗ-8	1		Step-delay is on	36	ПЗ-10	3		Range delay 30 km.
4	ПЗ-1	6			15	ПЗ-5	4,5		Delay 20 km.	26	ПЗ-8	5		Step-delay zero	37	ПЗ-11	5		Range delay 2 km.
5	ПЗ-2	3			16	ПЗ-5	4,5		Delay 60 km.	27	ПЗ-8	5		Step-delay is on	38	ПЗ-11	5		Range delay 30 km.
6	ПЗ-2	6			17	ПЗ-5	4,5		Delay 140 km.	28	ПЗ-9	1		Step-delay zero	39	ПЗ-12	1		Range delay 2 km.
7	ПЗ-1	1			18	ПЗ-6	1,6		Delay 20 km.	29	ПЗ-9	1		Step delay is on	40	ПЗ-12	1		Range delay 30 km.
8	ПЗ-3	3		Range scale 10 km.	19	ПЗ-6	1,6		Delay 60 km.	30	ПЗ-9	2			41	ПЗ-11	3		
9	ПЗ-4	1			20	ПЗ-6	1,6		Delay 140 km.						42	ПЗ-12	5		
10	ПЗ-4	5			21	ПЗ-7	5		Delay 20 km.	32	ПЗ-9	6							
11	ПЗ-5	4			22	ПЗ-7	5		Delay 40 km.	33	ПЗ-10	1,6		Range delay 2 km.	43	ПЗ-39			Adjusting potentiometer R3-101


FIG. 93. CALIBRATION CHART OF PULSES IN UNIT P3
Instructions. 1. Changeover switch on unit P3 is in OPERATION (РАБОТА) position.
2. Set the SWEEP DELAY IN KM changeover switch (ЗАДЕРЖКА РАЗВЕРТКИ КМ) to 0 position; band switch - to 10 km; RANGE potentiometer (ДАЛЬНОСТЬ) to 2 km; altitude potentiometer is in extreme left position; marker switch to COMPUTATION (ВЫЧИСЛ.).
3. Shape and amplitude of pulses are to be checked by oscillograph type 41H "Вольфрам".
4. Shapes and amplitudes of pulses given above are approximate.




SECRET



SECRET









FIG. 96. CALIBRATION CHART OF PULSES IN UNIT P4
Instructions. 1. Shape and amplitude of pulses are to be checked by means of oscillograph 4И "Вольфрам".
2. The above indicated shapes and amplitudes of pulses are approximate.



Inset No. 15. Secret





FIG. 99. CALIBRATION CHART OF P5/1 AND P5/2 UNITS

Instructions. 1. All resistors, besides specified, have tolerance of $\pm 10\%$.


2. All resistors and voltages, besides specified, are to be measured with respect to body under absence of video signal.

3. While measuring resistors, valves J5-1, JH5-1, JH5-2 and JH5-3 are to be taken out.

4. Measurements are to be effected by means of ABO-5 instrument.

5. Measurements marked with** sign are to be effected while rotating R5-4 BRIGHTNESS (RPKOCIB) potentiometer (measurement corresponds to operation in complex at a range of 200 km.).

6. Measurements marked with*** sign are to be effected by megohmmeter for 500 V.



Contact No. in plug connector	Resistors	Conditions for measurement	Contact No. in plug connector	Resistors	Conditions for measurement
1-body	0		27-body	51 Ω	"Markers" tumbler switch in "Sight" position
2-body	520 Ω		28-body	0	
3-4	2 Ω		29-body	51 Ω	
5-body	96 kΩ		30-body	∞	
6-body	0		31-body	∞	
7-body	∞		32-33	0	
8-body	0		34-32	∞	
9-body	210 kΩ		34-32	0	
10-body	∞		34-32	0	
11-17	∞	Tumbler switch "Course" set to "OFF" (BHKJIB/EHU) position and valve switches are to be taken out.	35-body	520 Ω	Upon pressing button "Power On".
12-body	∞		35-body	0	Clearance tumbler switch is in 1 position
13-body	∞		35-body	0	Clearance tumbler switch is in 1 position
14-body	1 mΩ		36	0	Not to be measured
15-body	∞		37-body	0	
16-body	1 kΩ**	Set R6-5 potentiometer to the right.	38-body	0	
18-19	0	Set tumbler switch "Antenna" to the upward position.	39-body	3 Ω**	With "Altitude delay" adjusting potentiometer
20-2	0		40-body	6.8 kΩ	With "Range" adjusting potentiometer
21-body	∞		41-2	14 kΩ	Valve JH5-2 is to be taken out.
22-body	0		41-2	0	Upon pressing down "Transmitter On" button
23-body	59.5 kΩ	"Brightness of range markers" adjusting potentiometer	42-2	0	
24-body	15.1 kΩ	Upon pressing "Antenna" switch downwards tumbler switch	43-45	0*** = 500 Ω	With "115 V Control" adjusting potentiometer
25-body	0				
26-2	0				
27-body	36.5 kΩ	"Markers" tumbler switch to "Computation" position			

FIG. 100. CALIBRATION CHART OF UNIT P6


Instructions. 1. Prior to measurements all tumbler switches should be set to "OFF" (BHKJIB/EHU) position and valve switches and potentiometers are to be set to extreme left position.

2. Resistance at nodal points is to be measured with respect to pins of JH5-1 plug connectors.

3. Figures in circles correspond to pins of plug connectors.

SECRET

NO FOREIGN DISSEM




5. Measurements marked with** sign are to be effected while rotating R5-4 BRIGHTNESS (ЯРКОСТЬ) potentiometer (measurement corresponds to operation in complex at a range of 200 km.).

6. Measurements marked with*** sign are to be effected by megohmmeter for 500 V.

Contact No. in plug-connector	Resistors	Conditions for measurement	Contact No. in plug-connector	Resistors	Conditions for measurement
1-body	0		27-body	51 Ω	"Markers" tumbler switch in "Bright" position
2-body	520 Ω		28-body	0	
3-4	2 Ω		29-body	51 Ω	
5-body	9.6 k Ω		30-body	∞	
6-body	0		31-body	∞	
7-body	∞		32-33	0	
8-body	0		34-32	∞	
9-body	210 k Ω		34-32	0	Upon pressing Button "Power On".
10-body	∞		35-body	520 Ω	Clearness tumbler switch is in I position
11-17	∞	Tumbler switch "Course Line" On and Off JH6-3 valve is to be taken out.	35-body	0	Clearness tumbler switch is in II position
12-body	∞		36	0	Not to be measured
13-body	∞		37-body	0	
14-body	1 m Ω		38-body	0	
15-body	∞		39-body	3 Ω ***	With "Altitude delay" adjusting potentiometer
16-body	1 k Ω **	Set R6-65 potentiometer to the right.	40-body	12 k Ω	With "Range" adjusting potentiometer
18-19	0	Set tumbler switch "tilt" to the Upward position.	41-2	6.8 k Ω	Valve JH6-2 is to be taken out.
20-2	0		41-2	0	Upon pressing down "Transmitter On" button
21-body	∞		42-2	0	
22-body	0		43-45	0***	With "115 V Control" adjusting potentiometer
23-body	59.5 k Ω	"Brightness of range markers" adjusting potentiometer		500 Ω	
24-body	15.1 k Ω	Upon pressing "Antenna tilt downwards" tumbler switch			
25-body	0				
26-2	0	"Markers" tumbler switch to "Computation" position			
27-body	36.5 k Ω				


FIG. 109. CALIBRATION CHART OF UNIT P6

- Instructions. 1. Prior to measurements all tumbler switches should be set to "OFF" (ВЫКЛ) position and wafer switches and potentiometers are to be set to extreme left position.
- Resistance at nodal points is to be measured with respect to pins of W6-1 plug connectors.
- Figures in circles correspond to pins of plug connectors.
- Resistance with tolerance of $\pm 1\%$ is to be measured on Wheatstone bridge with an accuracy of not less than 0.5%.
- The rest of the resistors are to be measured by means of ABO-5 instrument.
- Resistor values marked with* sign are approximate and are to be determined by selection through W6-2 instrument; resistor marked with** sign is approximate; resistor marked with*** sign is to be measured by means of M-246 microohmmeter between terminal and body.
- Resistor tolerances, unless specified otherwise, are $\pm 10\%$.




SECRET

4	1-7	Roller K115-1		To be achieved by turning L5-1 coil around axis
		Not on cam	On cam	
		220 ohms	∞	



W6-1



W6-2

W6-1



CHART OF RESISTORS




CHART OF VOLTAGES




FIG. 98. CALIBRATION CHART OF A114 PANEL IN UNIT P4

1. Resistors are to be measured with respect to body.
2. Permissible variation from resistor values is $\pm 10\%$.
3. Voltage tolerance for all points of 3KK (calibration chart), unless specified otherwise, is $\pm 20\%$.
4. Measurements are to be effected by means of ABO-5 instrument or by similar one.
5. Tolerance for filament voltage is $\pm 10\%$.
6. All points, besides those marked with * sign, are measured with respect to body.

SECRET

NO FOREIGN DISSEM




FIG. 101. CALIBRATION CHART OF RESISTORS IN UNIT P7
Instructions. 1. Resistor values are indicated with respect to body and are to be measured with an accuracy of $\pm 10\%$.
2. Resistor values marked with * sign are to be selected while tuning the unit and are indicated approximately.
3. Measurements are to be effected by means of ABO-5 instrument or by similar one.
4. Resistors marked with ** sign are to be measured by M-246 microohmmeter between terminal and body.




FIG. 102. CALIBRATION CHART OF VOLTAGES IN UNIT P7

1. Voltages are to be measured when the unit has been tuned with the adjustment devices being in the following positions: CALIBRATION (КАЛИБРОВКА) switch is set to RANGE (ДАЛЬНОСТЬ) position; SPEED GENERATOR (ГЕНЕРАТОР СКОРОСТИ) switch is in "OFF" position; POSITION (ПОЛОЖЕНИЕ) knob is in extreme left position; GROUND SPEED (ПУТЕВАЯ СКОРОСТЬ) knob is at 600 km.; SEARCH-HOMING (ПОИСК-НАВЕДЕНИЕ) switch is in HOMING (НАВЕДЕНИЕ) position; ПИД knob is at 0.
2. Sight marker is to be set onto 4 km.
3. Range scale on operator's panel (under complex checking) is to be set to 10 - 70 km.

4. Filament voltage of valves Л7-11, Л7-13, Л7-14, Л7-15, Л7-1, Л7-4, Л7-5 and Л7-6 is to be measured between filament lugs of each valve.
5. All other measurements are to be effected with respect to body.
6. Measurements are to be effected by means of АВО-5 instrument or by similar one.
7. Tolerance for filament voltage is $\pm 10\%$.
8. Voltage tolerance for all points of 9KK (calibration chart) where no special tolerance is indicated, is $\pm 20\%$.

SECRET

NO FOREIGN DISSEM

No.	Valve No.	Shape and amplitude of pulses	Note	No.	Valve No.	Shape and amplitude of pulses	Note	No.	Valve No.	Shape and amplitude of pulses	Note
1	17-1		"Calibration" switch is in any position	11	17-6		"Calibration" switch is to be set to "Range" position	21	17-16		"Calibration" switch is to be set to "Speed" position. "Speed Generator" tumbler switch is in "OFF" position and "Position" knob is in extreme clockwise position.
2	17-1		do	12	17-9		"Calibration" switch is to be set to "Range" position. "Search-Homing" tumbler switch is to be set to "Homing" position.	22	17-17		"Calibration" switch is to be set to "Operation" position. "Speed Generator" tumbler switch is in "OFF" position and "Position" knob is in extreme counter-clockwise position.
3	17-2		do	13	17-9		do	23	17-17		"Calibration" switch is to be set to "Operation" position. "Speed Generator" tumbler switch is in "OFF" position. "Position" knob is in extreme clockwise position. Range from ONE sight is approximately 10 km.
4	17-2		do	14	17-15		"Calibration" switch is to be set to "Speed" position. "Speed Generator" tumbler switch - to "OFF" position and "Position" knob is to be set in extreme position counter-clockwise.	24	17-18		"Calibration" switch is to be set to "Range" position
5	17-2		do	15	17-15		do	25	17-18		do
6	17-3		do	16	17-14		do	26	17-19		do
7	17-4		do	17	17-15		"Calibration" switch is to be set to "Speed" position. "Speed Generator" tumbler switch is set to "OFF" position and "Position" knob is to be set to extreme counter-clockwise position.	27	17-4		do
8	17-4		do	18	17-15		do	28	17-20		"Calibration" switch is to be set to "Range" position. "Search-Homing" tumbler switch is set to "Homing" position.
9	17-5		"Calibration" switch is to be set to "Range" position	19	17-16		do	29	17-20		do
10	17-5		do	20	17-16		"Calibration" switch is to be set to "Speed" position. "Speed Generator" tumbler switch is in "OFF" position and "Position" knob is in extreme clockwise position.	30	17-23		do

FIG. 103. CALIBRATION CHART OF PULSES IN UNIT P7

1. Shape and amplitude of pulses are to be checked by means of oscillograph, type 41W "Вольтграм".

2. Shapes and amplitudes of pulses indicated above are approximate.

3. Pulse marked with * sign is indicated while starting from unit P12 (on stand it is checked by amplitude which is to be not less than 22 V).

4. R7-140 potentiometer - extreme counter-clockwise position.

SECRET

NO FOREIGN DISSEM




Fig. 104. CALIBRATION CHART OF UNIT P8

Instructions.

1. All resistors have tolerance of $\pm 10\%$ unless specified otherwise.
2. All resistors and voltages are to be measured with respect to body, unless specified otherwise (provided the video signal is absent).
3. Take out valves while measuring resistors.
4. Measurements are to be effected by ABO-5 instrument or by similar one.
5. All measurements of resistors in circuits correspond to extreme clockwise position of knobs of R8-4, R8-6, R8-8, R8-11 and R8-13 potentiometers unless specified otherwise.
6. While measuring resistors, with P8-1 and P8-2 relays being switched on, cut in 27 V onto 2nd and 19th pins of W8-1 plug connector.
7. Measurements marked with * sign are to be effected while rotating R8-9 BRIGHTNESS (ЯРКОСТЬ) potentiometer at scale of 200 km. and under starting frequency of 535.
8. All measurements of resistors marked with ** sign are to be effected while KИР-3 roller is on cam.
9. Measurements marked with *** sign are to be effected by means of megohmmeter for 500 V.
10. Resistor value 0 indicated in items 11 and 18 is approximate (from 0 to several units of ohm).

No.	Measurement points	Resistor values	Conditions for measurement
1	W8-1/2 - W8-1/10	110 ohms	
2	W8-1/3 - W8-1/5	227 kΩ	
3	W8-1/25 - W8-1/26	3.7 ohms $\pm 20\%$	
4	W8-1/10 - R, lug W8-1	0	
5	W8-1/8 - contact W8-5	0	
6	W8-1/16 - contact W8-6	0	
7	W8-1/10	4 ohms	R8-16 potentiometer - in extreme clockwise position
	W8-2 W8-3 W8-1 W8-4	54 ohms	R8-16 potentiometer - in extreme counter-clockwise position
**	3rd lug	240 ohms	R8-4 potentiometer - in extreme clockwise position
8	W8-1/1 - L8-4	0	R8-4 potentiometer - in extreme counter-clockwise position
9	W8-1/1 - W8-1/21	220 ohms	KИР-3 roller is on cam
10	W8-1/22 - W8-1/24 W8-1/1	∞	KИР-3 roller is not on cam
11	W8-1/22 - W8-1/24 W8-1/1	5.8 ohms $\pm 20\%$ 5.8 ohms $\pm 20\%$	Cut in 27 V onto 2nd contact of W8-1 (+) and body (-)
		Relay P8-1 and P8-2 dead	For switching on relay P8-1 and P8-2 cut in 27 V onto 2nd (+) and 19th (-) contacts of W8-1
12	W8-1/17 - W8-1/18	50 ohms	
13	W8-1/11 - W8-1/12	60 ohms	
**	W8-1/1 - 1st lug L8-3	240 ohms	R8-13 potentiometer is counter-clockwise
14	W8-1/13 - W8-1/20	420 ohms 900 ohms	R8-2 potentiometer is clockwise R8-2 potentiometer is counter-clockwise
15	W8-1/14 - W8-1/15	195 ohms 445 ohms	R8-1 potentiometer is clockwise R8-1 potentiometer is counter-clockwise
16	W8-1/6 - W8-1/9	235 ohms 195 ohms $\pm 10\%$	B8-1 tumbler switch is "ON"
		∞	B8-1 tumbler switch is "OFF"
**	W8-1/1 - 6th lug	240 ohms	R8-11 potentiometer is clockwise
17	L8-4	0	R8-11 potentiometer is counter-clockwise
	5th lug	70 ohms	R8-11 potentiometer is clockwise
18	W8-1/1 - L8-4	1 R8-11 counter-clockwise 75 ohms	R8-13 potentiometer is counter-clockwise

Nos of J19-1 pins	Resistance in ohms	Specific conditions for measurements	Note
1-body	0		
2-body	∞		Valves J119-1, J119-2 and J119-3 are removed
3-body	1.5 - 5.5 k Ω	While rotating "Speed zero" potentiometer	
4-body	0	"Calibration" switch is to be set to "Speed zero" position	
5-body	17.8 k Ω	R9-24, R9-21, R9-13 and R9-6 potentiometers are in extreme left position	
	18.3 k Ω	R9-24, R9-21, R9-13 and R9-6 potentiometers are in extreme right position	
6-body	5 - 25 k Ω	"Calibration" switch is set to "Range zero" position while rotating R9-17 potentiometer	
7-26	20 - 40 k Ω	While rotating "Range scale" potentiometer	
8-body	∞		
10-body	18 - 19 k Ω	While rotating R9-12 potentiometer and the rest of potentiometers being in extreme left position	
11-13	20 - 24 k Ω	While rotating R9-34 potentiometer	
12-15	0 - 20 k Ω	While rotating R9-23 potentiometer	
14-24	0	"Speed generator" tumbler switch is in "ON" position and "Calibration" switch is set to "Operation" position	Valve J119-4 is removed
15-19	6 k Ω	"Calibration" switch is set to "Operation" position	Permissible deviation in resistor values is $\pm 10\%$, unless specified otherwise
16-2	0	"Antenna tilt" tumbler switch is set to "up" position	
17-2	0	"Antenna tilt" tumbler switch is set to "Down" position	
18-body	∞	"Search-Homing" tumbler switch is set to "Search" position	
18-body	0	"Search-Homing" tumbler switch is in "Homing" position	
20-body	0	"Calibration" switch is set to "Operation" position	
21-body	16.7 k Ω	"Speed generator" tumbler switch is set to "OFF" position	
15-body	6 k Ω	"Calibration" switch is set to "Speed" position	

FIG. 105. CALIBRATION CHART OF UNIT P9
Resistance between earth terminal and body should not exceed 600 $\mu\Omega$ (measurements are to be effected by M-246 microohmmeter).







FIG. 106. CALIBRATION CHART OF UNIT P10
Instructions. 1. Resistors are to be measured with respect to body unless specified otherwise.
2. Tolerances in measuring resistors are $\pm 10\%$ unless specified otherwise.
3. Measurements are to be effected by means of ABO-5 instrument and by megohmmeter for 500 V.
4. Resistor is to be measured by M-246 microohmmeter between terminal and body.







SECRET

NO FOREIGN DISSEM

FIG. 108. CALIBRATION CHART OF RESISTORS IN UNIT P12

Instructions. 1. Resistors are measured between point under control and body of unit (besides Table).
2. Resistors are to be measured when terminal blocks and plug connectors are disconnected and valves are taken out.
3. Sign ∞ means resistance not over 50 megohms.
4. Resistor marked with ∞ sign is to be measured by megohmmeter for 500 V.
5. All other measurements are to be effected by means of ABO-5 instrument.
6. Resistor marked with * sign is to be measured by means of Wheatstone bridge with an accuracy of 1%.
7. Resistor marked with ** sign is to be measured by means of M-246 microhmometer between terminal and body.




FIG. 110. CALIBRATION CHART OF MODULATOR VALVES PANEL RESISTORS IN UNIT P12.

No.	Numbers of contacts between which resistors are measured	Resistor control value
1	KT12-1 - 10W12-1	about 1 ohm
2	10W12-1 - 10W12-1	520 ± 32 Ω
3	KT12-1 - 2KT12-1	27 ± 3 Ω
4	KT12-1 - 4KT12-1	27 ± 3 Ω
5	KT12-4 - 3KT12-2	27 ± 3 Ω
6	KT12-4 - 3KT12-2	27 Ω
7	KT12-5 - 2KT12-2	27 Ω
8	KT12-5 - 1KT12-2	0
9	KT12-6 - 1KT12-3	0
10	KT12-7 - 1KT12-4	0
11	KT12-8 - 4KT12-4	0
12	KT12-9 - 1KT12-5	4.5 kΩ ± 450 Ω
13	KT12-10 - 4KT12-5	0

SECRET

NO FOREIGN DISSEM






FIG. 108. CALIBRATION CHART OF RESISTORS IN UNIT P12
Instructions. 1. Resistors are measured between point under control and body of unit (besides Table).
2. Resistors are to be measured when terminal blocks and plug connectors are disconnected and valves are taken out.
3. Sign ∞ means resistance not over 50 megohms.
4. Resistor marked with ∞ sign is to be measured by megohmmeter for 500 V.
5. All other measurements are to be effected by means of ABO-5 instrument.
6. Resistor marked with * sign is to be measured by means of Wheatstone bridge with an accuracy of 1%.
7. Resistor marked with ** sign is to be measured by means of M-246 microohmmeter between terminal and body.



SECRET



SECRET

Page Denied