There were no runway markers or search- lights available. Signal flares were used during daytime in connection with flight operations. One green flare fired from a pistol indicated the beginning of f50Xtt operations; one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. if enough repair facilities were available, about 200 fighter anc50X1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes oculd be accomplished with the available equipment. Aircraft had to be taken to Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. Th Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE ARMY DISTRIBUTION DISTRIBUTION DISTRIBUTION DISTRIBUTION DISTRIBUTION DISTRIBUTION DISTRIBUTION	SUBJECT Keeskemet Airfield NO. OF PAGES / R SOXI NO. OF PAGES / R NO. OF ENGLS. UNITED BELOW DATE OF INFORMATION SOXI THIS IS UNEVALUATED INFORMATION SOXI THIS IS UNEVALUATED				LINTELLIGENC	t. 1		
SUBJECT Keckemet Airfield NO. OF PAGES / R NO. OF ENCLS. SUPPLEMENT TO SOXY SOXY THIS IS UNEVALUATED INFORMATION 1. Keckemet airfield was Hungarian Air Force and the German Air Force. The Hungarian Air Force before the last war. Hungarian Air Force before the last war. Hungarian Air Force mad the German Air Force. The Hungarian Air Force before the last war. Hungarian Air Force and the German Air Force. The Hungarian Air Force before the last war. Hungarian Air Force and the German Air Force. The airfield in October 1968. The surrounding area of the airfield is located Soxy about one kilometer south of the airfield, he railway spure led to the field. The aircraft normally were parked in the hangars available at the airfield The aircraft normally were parked in the hangare. There were no air raid alert practices! The only radio transmitter installations the two was available in all buildings. There was only an outside line to Keoskemet. Aicquate power (110 octs) was supplied by the Keoskemet pwar house. The airfield had no emergency power station of its own. Lights available. Signal flares were used by the Keoskemet pwar house. The airfield had no emergency power station of its own. Air such as a complished and the radio truck where were and by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 octs) was supplied by the Keoskemet power house. The airfield had no emergency power station of its own. Air such as a complished with the available equipment. Aircraft had to be taken to 'Sackes February 107 and order to prevent accidents during landing operations, one green flare fired from a piscal indicated the beginning of footic operations, one white clare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations, and routine and intenance, such as engine, wing, landing gear, and propelier changes ould be accomplished with the available equipment. Aircraft had	SUBJECT Keenkemet Airfield NO. OF PAGES /R NO. OF ENCLS. USE OF INFORMATION DATE ACQUIRED THIS IS UNEVALUATED INFORMATION SOX1 THIS IS UNEVALUATED INFORMATION THIS IS UNEVALUATED INFORMATION THIS IS UNEXAL UNITED TO THE THIS IS UNEXAL UNITED TO THE THIS SOX1 INFORMATION SOX1 THIS IS UNEXAL UNITED TO THE THIS IS UNEXAL UNITED TO THE THIS SOX1 THIS IS UNEXAL UNITED TO THIS SOX1 THIS IS UNEXAL UNIT			INFOR	WAIION	REPORT		
PLACE ACQUIRED DATE ACQUIRED DATE INFORMATION INFORMATION SUPPLEMENT TO 50X1 REPORT NO. SUPPLEMENT TO 50X1 REPORT NO. THIS IS UNEVALUATED INFORMATION 50X1 IMagerian Air Force before the last war. During the war, it was used by both the flungarian Air Force and the German Air Force. The Hingarian Air Force took over the airfield in October 1943. The surrounding area of the airfield in October 1943. The surrounding area of the airfield in October 1943. The surrounding area of the airfield is not play tiggy. Restscent - Decessable highway. The Kockeast - Scalnok railroad is located 50X1 about one kilometer south of the airfield. No railway spure lad to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield The aircraft normally were parked in the hangars. There were no air raid alert practices! 3. The only raids transmitter installations the tower buildings and the radio truck. Telephone fasilities for the airfield were available in all buildings. There was only an outiful histor to Kent Al communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (ulo volts) was supplied by the Keeskemet power house. The airfield had no energency power station of its own. Interest and the state of the same of the state of the communications with higher indicated the end of light operations. One green flare fired from a pistol indicated the beginning of f50Xt operations, one white flare indicated the end of light operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter and fourther and fou	PLACE ACQUIRED DATE ACQUIRED DATE ACQUIRED DATE SUPLEMENT TO SOX1 REPORT NO. SOX1 THIS IS UNEVALUATED INFORMATION SOX1 Hungarian Air Force before the last war. During the war, it was used by both the Hungarian Air Force and the German Air Force. The Hungarian Air Force bodo over the airfield in October 1948. The surrounding area of the airfield is level land without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield is accessible only by the fixed about one kilomoter south of the airfield. No railway spure led to the field oxide both one kilomoter south of the airfield. The aircraft normally were parked in the hangars. There were no air raid alert practices: There were no aircraft blast-pens or underground hangars available at the airfield the communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line hetwen this airfield and other headquarters. Adequate power (110 volts) was supplied by the Keeskenset power house. The airfiel approximations with higher headquarters in Budapest were made by teletype, since there was not special telephone line hetwen this airfield and other headquarters. Adequate power (110 volts) was supplied by the Keeskenset power house. The airfiel approximations. One green flare fired from a pistol Indicated the beginning of f5000 goverations, one white flare indicated the end of flight operations. One green flare fired from a pistol indicated the beginning of f5000 goverations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations, and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to 'Seekershenver affect for major repair facilities, however, were available for radios, instruments, and armament. Bach âircraft was supposed to have been equipped with tw	COUNTRY	Hungary		•		DATE DISTR. & Au	
DATE OF INFORMATION 1. Keeskemet airfield was Hungarian Air Force before the last war. During the war, it was used by the 80%1 Hungarian Air Force and the German Air Force. The Hungarian Air Force book over the airfield in October 1948. The surrounding area of the airfield is level land without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield accessible only by thou keekscent - Bekesceake highway. The Keeskemet - Scolnok rallrand is located 50%1 about one kilometer south of the airfield. No rallway spurs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield The aircraft normally were parked in the hangars. There were no air raid alert practices 5.50% 5. The only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outsjale line to Keeskemet. All communications with higher headquarters in budapest were made by teletype, since there was no special telephone line between this airfield and on energinely pewer station of its one apiston indicated the beigning operations. One green flare fired from a piston indicated the beigning of flowing operations. One green flare fired from a piston indicated the beigning of flowing operations. One green fare fired from a piston indicated the beigning of flowing poperations. One green fare fired from a piston indicated the beigning of flowing poperations. One green fare fired from a piston indicated the beigning of flowing operations. One green fare fired from a piston indicated the beigning of flowing poperations. One green fired fired from a piston indicated the beigning of flowing operations. One green fare fired from a piston indicated the beigning of flowing poperations. One green fired fired from a piston indicated the beigning operations. One green fired fired from a piston indicated the beigning operations. One green fired fired from	DATE OF INFORMATION 1.	SUBJECT	Kecskemet Airf	ield			NO. OF PAGES /	e 50x1
THIS IS UNEVALUATED INFORMATION 1. Keeskemet airfield was burned to be a seen a seen to be a seen a seen to be a seen and propeller changes ould be a seen seen the and to see the seen to be a seen as a seen to be a seen and propeller changes ould be a seen seen seen as a seen to be a seen to be a seen	THIS IS UNEVALUATED INFORMATION 1. Keeskemet airfield was used by the 50x1 THIS IS UNEVALUATED INFORMATION 50x1 THIS IS UNEXA THE AUX AND THIS ISSUED TO THE AUX AND THIS ISSUED TO THE AUX AND THE SEARCH THE AUX AND THE SEARCH THE SAN THE AUX AND THE SEARCH THE AUX AND THE SEARCH THE SAN THE SEA	PLACE ACQUIRED)		g .			2
THIS IS UNEVALUATED INFORMATION 50x1 1. Kecskemet airfield was hungarian Air Force before the last war. During the war, it was used by both the Hungarian Air Force and the German Air Force. The Hungarian Air Force before the last war. The Hungarian Air Force and the German Air Force. The Hungarian Air Force took over the airfield in October 1940. The surrounding area of the sirfield is level land without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The sirfield is accessible only by though about one kilometer south of the airfield. So railway spurs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield The aircraft normally were parked in the hangars. There were no air raid alert practices 50X1 3. The only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Keeskemet. All communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 voits) was supplied by the Keeskemet power house. The airfield had no emergency power station of its own. There were no runway markers or searchlights available. Signal flares were used during daytime in connection with fligh operations. One green flare fired from a pistol indicated the beginning of f50Xt operations one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter anafoxyl ground assault aircraft hould operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of So	THIS IS UNEVALUATED INFORMATION 50x1 1.		D		i .			50X1
Keeskemet airfield was Used by the 50X1	Recekemet airfield was used by the 50X1 Hungarian Air Force before the last war. During the war, it was used by toth the Hungarian Air Force and the German Air Force. The Hungarian Air Force took over the airfield in October 1948. The surrounding area of the airfield is level land without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield is accessible only by thook Keeskemet - Belesseaba highway. The Keeskemet - Scolnok railroad is located 50X1 about one kilometer south of the airfield. No railway spurs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield The aircraft normally were parked in the hangars. There were no air raid elert practices 50X1 3. The only radio transmitter installations were the ones located 50X1 the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Keeskemet. A communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line petween this airfield and other headquarters. Adequate power (110 volts) was supplied by the Keeskemet power house. The airfiel had no emergency power station of its own. There were no runway markers or searchlights available. Signal flares were used during daytime in connection with fligh operations. One green flare fired from a pistol indicated the beginning of f50X1 operations, one white flare indicated the end of flight operations properly proper facilities were available, about 200 fighter and 50X1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintennance, such as engine, wing, landing gear, and propeller changes ould be accomplished with the available equipment. Aircraft had to be taken to a Stekesfehorvar fof major repair work. Major repair facilities, however, were available for railors, interments, and aramament. Bach aircraft was supposed to hav	DATE OF	INFORMATION	4				50X1
Hungarian Air Force before the last war. During the war, it was used by both the Hungarian Air Force and the German Air Force. The Hungarian Force to do over the airfield in October 1948. The surrounding area of the airfield if level land without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield is accessible only by \$50x1 Kecskemet - Bekescsaba highway. The Kecskemet - Scolnok railroad is located 50x1 about one kilometer south of the airfield. No railway spurs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield The aircraft normally were parked in the hangars. There were no air raid alert practices 50x1 50x1 50x1 70x1	Hungarian Air Force before the last war. During the war, it was used by both the Hungarian Air Force and the German Air Force. The Hungarian Air Force both over the airfield in October 1948. The surrounding area of the airfield if level land without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield is accessible only by \$15000 Meckemet - Bekesosaba highway. The Kecskemet - Scolnok railroad is located \$5000 me kilometer south of the airfield. No railway spurs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield The aircraft normally were parked in the hangars. There were no air raid alert practices 5000 3. The only radio transmitter installations were the ones located \$5000 mere available in all buildings. There was only an outside line to Kecskemet. All communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Kecskemet power house. The airfiel had no emergency power station of its own. There were no runway markers or searchlights available. Signal flares were overed during daytime in connection with flight operations. One green flare fired from a pistol indicated the beginning of f5000 operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter anafogong ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft and to be taken to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no t	THES DOCUMEN OF THE UNIT AND 794, OF LATION OF IT PRONIBITED I	ST COMPAINS IMPORMATION AFFE CO STATES, WITHIN THE MEANING THE U.S. CODE, AS AMERICAD THE COMPENTS TO OR RECEIPT BY SY LAW. THE REPRODUCTION OF	CTIME THE NATIONAL O GOFTITLE 18, SECTION ITS TRANSMISSION OR AN UNAUTHORIZED FER THIS FORM IS FRONIS	Brenet 40 705 Reve- Bon Is 1780.	THIS IS	UNÉVALUATED INFORMA	ATION 50X1
Hungarian Air Force and the German Air Force. The Hungarian Air Force and the German Air Force of the airfield if level land without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield is accessible only by the factor of the airfield is accessible only by the factor about one kilometer south of the airfield. No railway spurs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield The aircraft normally were parked in the hangars. There were no air raid alert practices 50X1 The only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Keckemet. Al communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Keckemet power house. This airfield had no emergency power station of its own. There were no runway markers or searchlights available. Signal flares were used during daytime in connection with fligh operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. [If enough repair facilities were available, aloning operations.] [If enough repair facilities were available, aloning operations for the day. Red flares were fired in order to prevent accidents during landing operations.] [If enough repair facilities were available, aloning operations.] [If enough repair facilities were available, aloning sear, and prompeller changes could be accomplished with the available equipment. Aircraft had to be taken to a Seekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine	Hungarian Air Force and the German Air Force. The Hungarian Air Force to the sirfield in October 1948. The surrounding area of the sirfield if level land without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield is accessible only by \$\frac{t}{50}\text{M}\$. Keeskemet - Bekesesaba highway. The Keeskemet - \$\frac{t}{50}\text{look}\$ about one kilometer south of the airfield. No railway surs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield. The aircraft normally were parked in the hangars. There were no air raid alert practices 50X1 3. The only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Keekemet. A communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Keeksemet power. The airfiels had no emergency power station of its own. There were no runway markers or searchlights available. Signal flares were used during daytime in connection with fligi operations. One green flare fired from a pistol indicated the beginning of f50Xl operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter anc coxidence and routine maintenance, such as engine, wing, landing gear, and propeller changes ould be accomplished with the available equipment. Aircraft had to be taken to \$\frac{1}{2}\$ Sekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each direct sets of tools. The frame. The III-10, Yak-11, Yak-2 and Ziln aircraft had confired the force and one for the frame. The III-10, Yak-11 was sup			Wl			· · · · · · · · · · · · · · · · · · ·	
without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield is accessible only by the 50x1 kecskemet - Bekescasaba highway. The Kecskemet - Szclnok railroad is located 50x1 about one kilometer south of the airfield. No railway spurs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield The aircraft normally were parked in the hangars. There were no air raid alert practices 50x1 50x2 50x1 50x2 50x1 50x2 50x1 50x2 50x2 50x2 50x2 50x2 50x2 50x2 50x2 50x3 50x2 50x3 50x2 50x3 50x3 50x4 50x3 50x4 60x4 6	without obstructions. The airfield could be extended in an east and northeastern direction for approximately 1000 meters. The airfield is accessible only by thom. Kecskemet - Bekescasha highway. The Kecskemet - Szolnok railroad is located 50x1 about one kilometer south of the airfield. No railway spurs led to the field. 2. There were no aircraft blast-pens or underground hangars available at the airfield. The aircraft normally were parked in the hangars. There were no air raid alert practices 50x1 50x1 50x1 The only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Kecskemet. A communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Kecskemet power house. The airfield had no emergency power station of its own. In the were no runway markers or searchlights available. Signal flares were used during daytime in connection with flight operations, one green flare fired from a pistol indicated the beginning of f50x1 operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. [if enough repair facilities were available, about 200 fighter antogox1 ground assault aircraft oould operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to 1.5 Seekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-1, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools		Hungarian Air	Force befor Force and t	e the last war he German A ir	r. During th Force. The	e war, it was used l Hungarian Air Force	by both the took over
The aircraft normally were parked in the hangars. There were no air raid alert practices 50X1 50X1 50X1 50X1 50X1 50X1 50X1 The only radio transmitter installations were the ones located 50X1 the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Keckemet. Al communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Keckemet power house. The airfiel had no emergency power station of its own. There were no runway markers or search-lights available. Signal flares were used during daytime in connection with fligh operations. One green flare fired from a pistol indicated the beginning of fi50Xth operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter and50X1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to the Szekesfehervar fof major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had notool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation. CLASSIFICATION SECRET DISTRIBUTION DISTRIBUTION DISTRIBUTION DISTRIBUTION DISTRIBUTION DISTRIBUTION	The aircraft normally were parked in the hangars. There were no air raid alert practices 50X1 The only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Kecskemet. All communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Kecskemet power house. The airfiel had no emergency power station of its own. There were no runway markers or search-lights available. Signal flares were used during daytime in connection with fligh operations. One green flare fired from a pistol indicated the beginning of f50X1 operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. if enough repair facilities were available, about 200 flighter anc50X1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to its Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had notol kits. The tools for the line, yak-9 and Yak-9 and Yain aircraft had complete sets of tools. There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE Value DISTRIBUTION DISTRIBUTION DISTRIBUTION DISTRIBUTION		without obstruction for	ctions. The approximate	e airfield cou ly 1000 meters	ald be extend . The airf	led in an east and no eld is acce ssible on	ortheastern
The only radio transmitter installations were the ones located 50X1 the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outspide line to Kecskemet. All communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Kecskemet power house. The airfiel had no emergency power station of its own. There were no runway markers or search-lights available. Signal flares were used during daytime in connection with fligh operations. One green flare fired from a pistol indicated the beginning of f50X1 operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter and 50X1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to in Szekesfehervar for major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The II-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for II-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation.	The only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outspice line to Kecskemet. At communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Kecskemet power house. The airfiel had no emergency power station of its own. There were no runway markers or search-lights available. Signal flares were used during daytime in connection with flight operations. One green flare fired from a pistol indicated the beginning of f50X1 operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter and 50X1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The II-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation.	2.	The aircraft no	aircraft bloormally were	ast-pens or un e parked in th	nderground he	ngars available at t There were no air re	the airfield aid alert
the only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Kecskemet. Al communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Kecskemet power house. The airfiel had no emergency power station of its own. There were no runway markers or search-lights available. Signal flares were used during daytime in connection with fligh operations. One green flare fired from a pistol indicated the beginning of f50Xtb operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter anc60x1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to a Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each direraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czecheslovakian manufacture. There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE X NAWY AND EVALUATION SECRET	the only radio transmitter installations the tower building and the radio truck. Telephone facilities for the airfield were available in all buildings. There was only an outside line to Kecskemet. At communications with higher headquarters in Budapest were made by teletype, since there was no special telephone line between this airfield and other headquarters. Adequate power (110 volts) was supplied by the Kecskemet power house. The airfield had no emergency power station of its own. There were no runway markers or search-lights available. Signal flares were used during daytime in connection with flight operations, one green flare fired from a pistol indicated the beginning of f50X1 operations; one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. If enough repair facilities were available, about 200 fighter and fox1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to a Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE X NAVY ANN ANN ANN ANN ANN ANN ANN		practiced					
lights available. Signal flares were used during daytime in connection with fligh operations. One green flare fired from a pistol indicated the beginning of f.50X1t operations, one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. if enough repair facilities were available, about 200 fighter anc.50X1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-9 and Zlin aircraft had complete sets of tools. Th Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation.	lights available. Signal flares were used during daytime in connection with flight operations. One green flare fired from a pistol indicated the beginning of f.50X11 operations; one white flare indicated the end of flight operations for the day. Red flares were fired in order to prevent accidents during landing operations. if enough repair facilities were available, about 200 fighter and 50X1 ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to a Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and 21in aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the 21in of Czechoslovakian manufacture. There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE X NAWY DISTRIBUTION ARMY X NAWY DISTRIBUTION DISTRIBUTION			ding and the	e radio truck.	Telephone	were the ones I	Located 50X1
ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to it Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-Il aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE X NAVY DISTRIBUTION DISTRIBUTION DISTRIBUTION	ground assault aircraft could operate from this airfield. Only minor repairs and routine maintenance, such as engine, wing, landing gear, and propeller changes could be accomplished with the available equipment. Aircraft had to be taken to in Szekesfehervar for major repair work. Major repair facilities, however, were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation.	3.	were available communications there was no sp Adequate power	with highe pecial telep (110 volts)	r headquarters phone line bet) was supplied	s in Budapest tween this aid by the Kecs own.	outside line to Kee were made by telety rfield and other hea kemet power house.	rskemet. Al ype, since adquarters. The airfield
were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE X NAVY DISTRIBUTION ARMY X AIR EV X DISTRIBUTION	were available for radios, instruments, and armament. Each aircraft was supposed to have been equipped with two sets of tools, one for the engine and one for the frame. The IL-10, Yak-11, Yak-9 and Zlin aircraft had complete sets of tools. The Arado-96 aircraft had no tool kits. The tools for IL-10, Yak-9 and Yak-11 aircraft were of Soviet manufacture and those for the Zlin of Czechoslovakian manufacture. There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE X NAVY DISTRIBUTION ARMY X AIR EV X DISTRIBUTION	3.	were available communications there was no space and no emergence lights available operations. Or operations, one Red flares were	with higher pecial teleptocal tel	r headquarters phone line bet) was supplied ation of its flares were to are fired from re indicated to	s in Budapest tween this ai d by the Kees own. There were ased during d a pistol in the end of fl ent accidents	coutside line to Kee were made by telety rfield and other hea kemet power house. no runway markers caytime in connection dicated the beginning ight operations for during landing open	oskemet. All pe, since adquarters. The airfield or search with flight of f.50X1t the day.
There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE X NAVY X DISTRIBUTION ARMY X AIR EV X DISTRIBUTION	There was a shortage of special tools at this installation. CLASSIFICATION SECRET STATE X NAVY X DISTRIBUTION ARMY X AIR EV X DISTRIBUTION	3.	were available communications there was no space and no emergence lights available operations. One Red flares were ground assault and routine mai could be accomp	with higher pecial telep (110 volts cy power state) le. Signal ne green flate white flate fired in femough repaircraft cointenance, polished with	r headquarters phone line het) was supplied ation of its flares were to are fired from re indicated to order to preven pair facilities build operate fi such as engine the available	s in Budapest tween this ai d by the Kecs own. There were a a pistol in the end of fl ent accidents es were avail from this air e, wing, land the equipment.	coutside line to Keek were made by telety rfield and other heak met power house. In orunway markers a aytime in connection disated the beginning ight operations for during landing openable, about 200 fightield. Only minor ing gear, and propel Aircraft had to be	oskemet. All ppe, since adquarters. The airfield or searcher with flighing of f.50X1t the day. Tations. The airfield of the day. The airfield of the day of the day. The airfield of the day of the day. The airfield of the day of th
STATE X NAVY X DISTRIBUTION ARMY X AIR EV X 0.00 X E-R / Y	STATE X NAVY X DISTRIBUTION ARMY X AIR EV X 0.00 X E.R. (1)	3.	were available communications there was no space and ano emergence lights available operations. On operations, one Red flares were ground assault and routine mai could be accompto Szekesfe were available to have been enframe. The IL-Arado-96 aircre	with higher pecial telepecial tel	r headquarters phone line her) was supplied ation of its flares were to are fired from re indicated to pair facilities such as engine to the available major repair instruments, two sets of Yak-9 and 21 tool kits. The	s in Budapest tween this ai d by the Kecs own. There were used during d a a pistol in the end of fl ent accidents es were avail from this air e, wing, land the equipment. work. Major and armamen tools, one f in aircraft the tools for	outside line to Kee, were made by telety rfield and other heakemet power house. one runway markers of aytime in connection dicated the beginning ight operations for during landing operable, about 200 fightield. Only minor ming gear, and propel Aircraft had to be repair facilities, t. Each aircraft we or the engine and on had complete sets of IL-10, Yak-9 and Yak	oskemet. Allype, since adquarters. The airfield or searcher with flighing of f.50x1t the day. The aircraft changes at taken however, as supposed the for the chall aircraft chairs.
STATE X NAVY X DISTRIBUTION ARMY X AIR EV X 100 X E-R / Y	STATE X NAVY X DISTRIBUTION ARMY X AIR EV X 100 A X E A 1 Y	3.	were available communications there was no space and ano emergent lights available operations. On operations, one Red flares were available to have been ed frame. The IL-Arado-96 aircrawere of Soviet	with higher pecial telep (110 volts cy power state of the pecial telep (110 volts cy power state of the pecial representation of the pecial telephone representation representatio	r headquarters phone line her) was supplied ation of its flares were to are fired from re indicated to order to preve ould operate fould operate in the availabl major repair instruments, in two sets of Yak-9 and Zi tool kits. The	s in Budapest tween this aid by the Kecsown. There were used during do a pistol in the end of flent accidents es were availation from this air e, wing, land the equipment. Work. Major and armament tools, one fin aircraft the tools for or the Zlin o	outside line to Keek were made by telety rfield and other heak kemet power house. one runway markers caytime in connection disated the beginning ight operations for during landing operable, about 200 fightield. Only minor ring gear, and propel Aircraft had to be repair facilities, t. Each aircraft we or the engine and or had complete sets of IL-10, Yak-9 and Yak f Czechoslovakian me	oskemet. Allype, since adquarters. The airfield or searcher with flighing of f.50x1t the day. The aircraft changes at taken however, as supposed the for the chall aircraft chairs.
ARMY X AIR EV X /// X ER/Y	ARMY X AIR EV X (100 X ER / V		were available communications there was no space and ano emergent lights available operations. On operations, one Red flares were available to have been ed frame. The IL-Arado-96 aircrawere of Soviet	with higher pecial telep (110 volts cy power state of the pecial telep (110 volts cy power state of the pecial representation of the pecial telephone representation representatio	r headquarters phone line her) was supplied ation of its flares were to are fired from re indicated to order to preve ould operate fould operate in the availabl major repair instruments, in two sets of Yak-9 and Zi tool kits. The	s in Budapest tween this aid by the Kecsown. There were used during do a pistol in the end of flent accidents es were availation from this air e, wing, land the equipment. Work. Major and armament tools, one fin aircraft the tools for or the Zlin o	outside line to Keek were made by telety rfield and other heak kemet power house. one runway markers caytime in connection disated the beginning ight operations for during landing operable, about 200 fightield. Only minor ring gear, and propel Aircraft had to be repair facilities, t. Each aircraft we or the engine and or had complete sets of IL-10, Yak-9 and Yak f Czechoslovakian me	oskemet. Allype, since adquarters. The airfield or searcher with flighing of f.50x1t the day. The aircraft changes at taken however, as supposed the for the chall aircraft chairs.
			were available communications there was no spadequate power had no emergent lights available operations. Or operations, one Red flares were ground assault and routine mai could be accompto a Szekesfe were available to have been enframe. The IL-Arado-96 airors were of Soviet There was a should be accompted to the second statement of the second statement of the second seco	with higher pecial telep (110 volts of the pecial telep (110 volts of the pecial telep (110 volts of the pecial telep of the pecial telepool telepo	r headquarters phone line bet) was supplied ation of its flares were are fired from re indicated to order to preven ould operate fired as engine n the available major repair instruments, n two sets of yak-9 and 21 tool kits. The cecial tools a	s in Budapest tween this aid by the Kecs own. There were assed during of a pistol in the end of flucture that accidents as were available equipment. Work. Major, and armamen tools, one fin aircraft actions for the Zlin out this insta	outside line to Keek were made by telety rfield and other heak kemet power house. one runway markers caytime in connection disated the beginning ight operations for during landing operable, about 200 fightield. Only minor ring gear, and propel Aircraft had to be repair facilities, t. Each aircraft we or the engine and or had complete sets of IL-10, Yak-9 and Yak f Czechoslovakian me	oskemet. Allype, since adquarters. The airfield or searcher with flighing of f.50x1t the day. The aircraft changes at taken however, as supposed the for the chall aircraft chairs.

- 4. There was no antiaircraft artillery available at Kecskemet but there were two Mazini antiaircraft machine guns stored in the guard-house. The guard personnel were supposed to operate these machine guns in case of air attack. In such a case, one machine gun would be installed at Point #65 / Enclosure (B) and the other on top of the building, Point #50, / Enclosure (B). These machine guns were moved to the above sites almost every day during January, February, March, April and May of 1950 because of Yugoslav aircraft flying over this airfield. One Yugoslav aircraft flew over the airfield about once a month during this period. The aircraft came when the sky was overcast, only during the daytime, from the direction of Szelnok. It flew over the airfield in a north-south direction at approximately 500 meters altitude, then rose again to about 1000 meters and disappeared southward. The antiaircraft machine guns never opened fire on the Yugoslav aircraft, probably because the warning by telephone from Szelnok arrived too late. The Yak-9 aircraft on this airfield took off in order to intercept the foreign aircraft but usually it took the Yak-9s about ten to fifteen minutes to become airborne after the Yugoslav plane appeared over the airfield. They took off individually, and gave chase in "V" formation.
- 5. There was enough supply of fuel and oil to permit normal flight operations, although each squadron was rationed. The fuel and oil arrived by rail from the USSR to Kecskemet railroad station, and then was brought to the airfield in fuel trucks and barrels. The aircraft were serviced from two fuel trucks, each with a capacity of 3,600 liters. One contained 95 octane gas and other 87 octane. The pumps were operated electrically. Two oil and water trucks (GMC) were available for servicing the aircraft. These trucks also had electrically operated pumps. Ample water supply was available at the airfield from the city of Kecskemet.
- 6. Kecskemet is an "all year around" flying base. During winter the snow is from 5 10 cm deep. The lowest temperature was 20°C. Even during the rainy season, (September and November) the field is operational due to the sandy composition of the soil. The prevailing winds blow from southeast to northwest, and less frequently from northwest to southeast. The wind speed usually was about 5 10 m/sec; maximum speed was about 15 m/sec.
- 7. The airfield was under military administration. The first aircraft arrived there in May 1949 from the USSR. At that time, two Hungarian Air Force training squadrons were stationed there, training with UT-2 aircraft. In July 1949 about eight Arado-96 aircraft were received from Osechoslovakia and used for training by the two squadrons. In August 1949 most of the personnel of the two training squadrons were transferred to Ssolnok school for theoretical training. In August 1949 a number of Yak-9 and IL-10 aircraft arrived at the airfield from USSR. These aircraft were not used, however, until November 1949 when Soviet instructors arrived to train the Hungarian Air Force pilots who had ME-109 and "Stuka" aircraft experience. This training lasted until February 1950 when the Soviet instructors departed. From March until July 1950, the pilot students who finished the theoretical training at Ssolnok were given practical flying training by the former ME-109 and "Stuka" pilots, with Yak-9 and IL-10 aircraft. About 35 of these students remained at Ssolnok as instructors. In July, the graduating pilots were formed into two new fighter regiments and two new ground attack regiments. One fighter regiment and one ground attack regiment were sent to Vesspren Airfield. These units took Yak-9's and IL-10's with them, leaving only the defective Yak-9 aircraft at Keeskemet. From July 1950 to December 1950, there was no flying activity at the airfield. Only a guard unit, five fighter and five ground attack pilots remained. In December 1950, twelve fighter instructors and twelve ground attack instructors arrived from Ssolnok. These instructors were part of the 35 instructors who went to Ssolnok in August 1949.
- S. There was one Fighter Training Regiment and one Ground Attack Training Regiment.

 There was, however, only one squadron in each of these regiments. The number of the fighter training squadron was 1/2,

 Ground Attack Training Squadron No. was 1/1,

 The fighter training Squadron had a strength or about 110 which included

 50×1

12 pilot - instructors, 12 chief mechanics (officers), 25 students; the rest were mechanics, helpers (enlisted men), armament, electrical, radio, instrument, specialists, parachute riggers, firemen, and administrative personnel. This squadron was composed of three flights. Each flight composed of one flight leader, three pilot - instructors, the other 26 persons being maintenance personnel. This squadron was equipped with five Yak-9, two Yak-9B, four Yak-11 and one Zlin aircraft. The ground attack training squadron was about 130 strong. This number included the 18 pilot-instructors, 18 chief mechanics (officers), 25 pilot students, the balance being composed of mechanics helpers (enlisted men), armament, electrical, radio, instrument specialists, parachute riggers, etc., foremen and administration personnel. This squadron was equipped with three IL-10 nine IL-10B, and one Zlin aircraft. This squadron had three flights organized similarly to the fighter flights. The airfield Commanding Officer was Capt Josef Mezolaky, whose official title was "Repter Paraucsnok" (airfield Commander). The following four officers were Capt Mezolaky's deputies: Capt Josef Zabransky, his official title being "Repter Politikai Tiszt" (Airfield Political Officer); Major Iaszlo Kazal, was the airfield's Chief of Personnel; his official title was "Repter Torzs Parancsnok" (Airfield Corps Commander); Major Tibor Szucs, was the Commanding Officer of the Ground Attack Training Regiments; Capt. Janos Szentivanyi, was the Commanding Officer of the fighter training regiment.

The training at this airfield consisted mainly of flying instruction with the Yak-11; the Yak-9B; the Yak-9 for fighter training; the IL-10B for ground attack training. Theoretical training was conducted only during inclement weather by the pilot instructors. There was no night, all weather, or instrument flying training undertaken at the airfield. There also was no aerial gunnery training. The first phase of the training undertaken at the airfield consists of take-offs and landing practices. Each student has to make at least 30 landings with his instructor. While this phase of training is in progress the student is also taught to make 900 turns. These flights take place in the immediate vicinity of the airfield and last only four to five minutes. After completing the 30th landing successfully the student has to make three landings with the officer directing the training. This officer may be either the squadron, the regiment or the airfield Commanding Officer. Due to shortage of aircraft this phase of training lasts about 40 days for fighter trainees and 25 days for ground attack trainees. After successfully completing the three landings under the observation of the officer directing the training, the student had to make 10 solo landings. After finishing the 10th solo landing, the student had to make two more landings under the supervision of the officer directing the training. This part of training lasted about five days for ground attack students and two weeks for fighter students, due to the fact that the ground attack training aircraft were more numerous and in better condition than the fighter training aircraft. During this phase of training, the landing gears on both the fighter and ground attack training aircraft were never retracted. If a student could not learn the correct takeoff and landing procedures after the 50th landing he was washed out. The second phase of training consisted of local flights about two kilometers radius from the airfield. The instructor flew only twice with the students, practicing different acrobatic maneuvers. These flights were made individually, each lasted about 30 minutes. The flying area was divided in numbered sectors (for example: Sector #s 1, 2, 2A, 3, 4, 5), each aircraft being assigned a certain sector in which to fly. These flights were made at an altitude of approximately 2000 meters. The student had to fly 12 different solo flights, each lasting 25 - 30 minutes. He was instructed before each flight what type of aerial maneuvers he had to make (loops, immelmanns, dives, etc.). There was a test following this phase of training with Yak-ll's and IL-loB's. This test was witnessed by a commission composed of high ranking Hungarian Air Force officers sent by the Ministry of Defense. This test consisted of 30 minutes of individual flying and acrobatic maneuvers, at about 1500 meters altitude. Following the successful completion of the test, the fighter pilot students started training with the Yak-9B aircraft while the ground attack pilot students started training with the IL-10 aircraft. The first phase of training with IL-10 aircraft consisted of 10 successive takeoff and landing practices. The landing wheels are retracted and lowered during

SEGRET SEGRET

this phase of training. The second phase of training with IL-10 aircraft consists of three solo, local individual flights, including acrobatic maneuvers. These flights took place at an altitude of about 1500 meters and lasted 30 minutes each. The third phase of training with IL-10 aircraft consists of eight cross-country formation flights. The formations were of 3+7+ aircraft (distance between aircraft about 20 meters and at different level). These cross-country flights were made at about 1000 meters altitude and lasted about 40 minutes. After finishing the eighth cross-country flight the student had to take an oral and written test and also a flight test. The flight test consisted of both individual acrobatic and formation flights. The first phase of training with the Yak-9B aircraft for fighter pilots consisted of three take-off and landing practices with the instructor. The landing gears are not retracted during this phase of training. On the day the third supervised successful landing takes place, the student makes one take-off and landing practice in a Yak-9 aircraft . The landing gears are not retracted during this practice. These three landing practices in the Yak-9B and one landing practice in the Yak-9 may be completed in one day. The next phase of training consists of 20 take-off and landing practices with the Yak-9 aircraft. The landing gears are not retracted during this phase of training. The next phase of training, with Yak-9 aircraft consists of six local flights. These flights, each lasting 50 minutes, were made at about 3000 meters altitude and included acrobatic maneuvers. The next phase of training, with Yak-9 aircraft consists of formation diving. These three cross-country flights lasted about 45 minutes each, and were made at 2,000 meters altitude. After the third cross-country flight the student had to take an oral and written test and a flight test similar to the one taken by the ground attack student pilots. Upon successful completion of the tests, the student graduates as pilot (fighter or ground attack). The best student is commissioned as a Lieutenant $_{50 exttt{X1}}$ the other students as Lieutenant Jr.

10. During February 1951, nine IL-10B aircraft and three IL-10 aircraft were stationed at Kecskemet. These aircraft were rather old with approximately 200 hours flying time for the frame and 70 hours engine time. They were painted dark green on the upper surface and light-blue on the lower.

The IL-10 and IL-10B are the same type of aircraft. The IL-10 and IL-10B aircraft has retractable landing gears and the tail wheel is half retractable. Tooxi engine is an AM-42, 2,000 H.P. type, with a liquid cooled 12 cylinders V-type engine. It used 95 octane gasoline. The wing span is about 12 meters and the fuselage, including the engine section is about 14 meters long. Both the IL-10 and IL-10B are equipped with two UBS 12.7 mm caliber machine guns and two UBK 24 mm cannons in the wing section. The IL-10 also has a UBT 12.7 mm type machine gun in the rear. It is not automatically stopped when the vertical stabilizer comes within its firing range. Both the IL-10 and IL-10B aircraft are equipped with two internal bomb racks in the wing section containing 50 or 150 kgs bombs. There are also two rocket launchers in the wing section. Ten aerial bombs, designed for dropping with parachutes are contained in the fuselage section behind the cockpit. The entire nose section, including cockpit is of armored glass about five om thick. The aircraft weighs 6,200 kgs. The maximum diving speed is 600 km per hour; the maximum level flight speed was 380 km per hour. There also .. were five Yak-9 and two Yak-9B belonging to the fighter training squadron. The Yak-9B was wood, two seat training aircraft, equipped with one, 20 mm cannon firing through the propeller hub. It had a VK-10T, 12-cylinder, liquid cooled, V-type engine of 1200 HP. Its maximum diving speed was 720 km per hour; level flight maximum speed was 480 km per hour. The maximum propeller RPM was 2500. The Yak-9 is a single seat aircraft, equipped with one Shvak 20 mm cannon fired through the propeller hub. Two UBS 12.7 mm machine guns were installed in the upper part of the engine section and fired through the propeller. It had a VK-107-A, 12-cylinder, liquid cooled, V-type engine of 1650 HP. Its maximum diving speed was 720 kms per hour; its level flight maximum speed was 570 kms per hour; the maximum propeller rpm was 3200. The engine - propeller r.m ratio is one to two. The wing span of Yak-9 and Yak-9B was 10 meters; the fuselage, including the engine, was 11.47 meters long. The landing gear, including the tail wheel, is completely retractable. The oil cooler on the Yak-9B aircraft is in the front of engine section on the lower side. The Yak-9 aircraft has two oil coolers on the lower center section. The oil cooler airscoops on both the



Yak-9 and the Yak-9B are opened manually. The Yak-9 has bullet-proof glass, five om thick, in the front and rear section of the cockpit. The Yak-9B has bullet-proof glass only in the front section of cockpit. The pilot's seat is armored on both the Yak-9 and the Yak-9B in the front section of the cockpit. The pilot's seat is armored on both the Yak-9 and Yak-9B. The Yak-9 aircraft has a gun camera in the right wing. The Yak-9B has the gun camera installed on the lower side of the right wing. The Yak-9 and Yak-9B aircraft used 95 octane gasoline. The fuel for the Yak-9 was contained in one 15 liter tank in the center section two 207.5 liter fuel tanks in the wing sections and two 117.5 liter fuel tanks in the wing sections, near the tip. All fuel tanks are made of self-sealing rubber. The Yak-9B aircraft has one 16 liter fuel tank in the center section and two 207.5 liter fuel tanks in the wing-section. These tanks are made of metal. Under combat conditions the fuel tanks are filled with neutral gas in order to prevent explosion in case the tank is perforated. This natural gas is taken 50X1from one exhaust opening, and sent to the fuel tanks after being cooled. The 50X1 oil capacity for the Yak-9 was 30 liters in the tank, 20 liters in the cooler 50X1 and 18 liters in the engine. The Yak-9B had a 75 liter oil capacity. The cooling fluid capacity for both the Yak-9 and the Yak-9B was 72 liters. The 50X1 Yak-9 aircraft were painted dark green on the upper surface and sky blue on the lower surface.

The Yak-9 aircraft were relatively new, and had arrived at the airfield from USSR in August 1949. In February 1951 these aircraft had an average of about 40 to 50 hours of flight. All these aircraft were grounded because of metal particles found in the cil. This was due to a defective lubrication system since it took about 10 seconds for all the engine parts to be lubricated after sta 50X1 ing. Another difficulty of the Yak aircraft was water seeping in the cylinder 50X1 and causing rust. There were four Yak-11 aircraft at the airfield in February 50X1 1951. These aircraft were relatively new, having arrived from the USSR in 50X1 November 1950. In February 1951 they had on the average of 45 to 50 hours flying and were in good flying condition. There was, however, a shortage of spare parts for these aircraft. They were painted light blue gray

50X' There were also two Zlin type aircraft in good flying condition. In February 1951 they had about 40 hours engine time. They were painted light gray

- 11. In February 1951 civilian workers at the airfield were employed for construction work. There were about 15 civilian women employed as clerks. The maintenance work on aircraft was done entirely by military personnel. The working hours for the administrative personnel were from 0900 to 1800 hours with one hour for lunch. On Saturdays they worked from 0900 to 1300 hours. Sundays were free. During summer the aircraft maintenance personnel worked from 0300 hours until the job was finished, everyday except Saturdays and Sundays. Mondays were reserved for maintenance work since there was no flying that day. Flying usually started at 0700 hours and lasted till 1500 hours during winter; during summer, it started at 0400 hours and lasted till 1100 hours. There was no flying on Saturdays, Sundays and Mondays.
- 12. The building area of the airfield was surrounded by a barbed wire fence two meters high. There were no guard towers or searchlights. The guard unit was composed of a squadron of about 100 men, who wore the regular Hungarian Air Force uniforms. The guards were on duty 24 hours with 25 hours off. While on duty the guards were two hours on post and four hours off. There was one guard posted at gates points 40, 51, and 64 Enclosure (B), armed with a Soviet type sub-machine 7.62 caliber. There was one guard patrolling each of the following areas denoted as point numbers 26, 47, 52, 58, 60, 62, 5, 18, 13C, 9, 6, and 4 Enclosure (B). Training effectiveness, discipline, and morale of the guards seemed only fair. Everybody entering the airfield area had to have a pass and the guards did not always ask for this, being satisfied to see the identification card. The officers and NCO's had one type of pass and the soldiers and civilians different types.

50X1

50X1

SECRET

SECRET

50X1

In order to enter the hangar area, a special pass had to be shown at gate point #57, \overline{E} nclosure (B). This pass was issued only to personnel working in this area. This pass was also signed by the airfield's Commanding Officer. The temporary pass was a piece of white paper, eight by five cm., giving the owner's name, rank, and permission to enter the area. This pass was also signed by Capt Mezolaky. The fire department consisted of 15 military persons, all graduates of the Budapest firemen's course. Five of them were in the firetruck at the garage Point #13A /Enclosure (B)/. Five were resting in the building Point #13C. Enclosure (B) while the other five were off duty. There was only one fire truck at the airfield. It had a 3000 liter container containing a foam type fire extinguisher liquid. During flight operations the fire truck was parked between the concrete strips, Points #59 and 61 Enclosure (B). There were also two, two-wheel push carts with three containers, each of 20 liters capacity, with foam type fire extinguisher liquid. These carts were kept in the hangar area. When flight operations were in progress one of these carts was stationed near the runway. Six 10-liter capacity fire extinguishers (foam type) were located at area shown as Point #5 Enclosure (B). Two buckets of sand were also kept in that area. There were ten five-liter foam type fire extinguishers. The garages were also equipped with five-liter foam type fire extinguishers. One fire hydrant was located in the area Point #15 ZEnclosure (B) and one beside There was no air raid defense training at the aireach of the three hangars. There was no camouflage and there were no air raid field shelters.

 \overline{T} he points hereunder refer to sketch, Enclosure (A) \overline{T}

- Point 1. City of Kecskemet (4653N 1941E): Population was approximately 95 thousand. It is a fruit canning center and important railroad junction.
- Point 2. The Budapest Cegled (4710N 1948E) Kecskemet Szeged (4615N 2008E) Railroad. It was a double track, standard European gauge rail line.
- Point 3. The Budapest Lajosmizse (4702N 1933E) Kecskemet Railroad. It was a double track, standard European gauge rail line.
- Point 4. The Budapest Fulopszallas (4649N 1914E) Kecskemet Railroad. It was a double track standard European gauge rail line.
- Point 5. The Kecskemet Szolnok (4711N 2011E) Railroad. It was a double track, standard European gauge rail line.
- Point 6. The Kecskemet Airfield, known as "Kecskemet Repuloter". It was the only airfield in the Kecskemet area. It was located two kilometers southeast from the center of Kecskemet city and four kilometers by road.
- Point 7. The Kecskemet Rekescsaba (4640N 2105E) highway. It was an excellent concrete road, about ten meters wide.

The points hereunder refer to sketch, Enclosure (B)

- Point 1. Concrete road, about four meters wide, in good condition. It's junction with the Kecskemet Bekes Csaba highway was about 12 kilometers from the airfield's gate.
- Point 2. The airfield's runway northwest southeast direction constructed of cement blocks. It was about 1,000 meters long and 70 meters wide.
- Point 3. Concrete block taxi strip. It was about 20 meters wide. The northwest and northeast sections were constructed during 1948 1949. The taxi strip, from the northwest and of the runway to the northwest corner was 1,500 meters; from the northwest to the southeast corner 1,500 meters; and from the southeast corner to the runway, 500 meters long. It was in good condition in February 1951.

- Point 4. Underground fuel storage installation, under construction in February 1951. Only the excavation was completed at that time. Two fuel tanks of 10 thousand liters and 20 thousand liters capacity were already installed and gasoline stored in them. The excavated area covered about 500 square meters and was about 10 meters deep. It was at about 500 meters distance from the taxi strip.
- Point 5. Parking area for three IL-10's and nine IL-10B's aircraft. They were always parked in a straight line at three-meter intervals between wing tips.
- Point 6. Open air storage area for fuel and oil. There were approximately
 400 barrels of 200 liter capacity each. The barrels were piled in four
 groups; 95 octane, 87 octane, 72 octane gasoline, and the oil barrels.
 The oil was of ms and mk types.
- Point 7. Black cinder-covered road, about two meters wide and 200 meters long.
- Point 8. Concrete road about 50 meters long and four meters wide.
- Point 9. Underground oil storage installation. There was one oil tank with a capacity of 6,000 liters in the excavation. There was no concrete construction. This oil tank was installed there during 1950.
- Point 10. Dirt road, about three meters wide, leading to farm houses.
- Point 10A. Ditch, about three meters deep and two meters wide. It ran along the whole southwest border of the airfield.
- Point 11. The Kecskemet Bekes Csaba highway.
- Point 12. Barbed wire fence enclosing the airfield. It was two meters high and supported by concrete posts spaced at four meter intervals.
- Point 13. Single story building of brick construction, about ten meters long, six meters wide and five meters high, excluding a low gabled red tile roof. It was painted dark yellow. It served as garage for two tow trucks and one tractor.
- Point 13A. Single story, brick building of the same construction, color, and dimensions as building described in Point 13. It was used as a garage for three "Raba" model trucks, and one fire truck.
- Point 13B. Building of the same construction as the building described in Points
 13 and 13A above. It served as garage for two Skoda cars belonging to
 the Security Section, (Deffensiv Osztaly) and three "jeeps".
- Point 13C. Single story "L" shaped brick building. Each wing was 20 meters long and eight meters wide, six meters high, excluding a low, gabled red tile roof. It was dark yellow. The southwestern wing housed one auto repair shop. The southeastern wing housed three offices of the motor-pool and waiting rooms for drivers.
- Point 14. Concrete parking area for two fuel and two oil and water trucks.
- Point 15. Concrete parking and washing area for vehicles, about 20 by 20 meters.
- Point 16. Two black cinder covered roads, about four meters wide.
- Point 17. Black cinder-covered parking area for defective vehicles. This area was about 100 meters long and 30 meters wide.
- Point 18. Single story "L" shaped brick building 10 meters and five meters long, six meters wide and five meters high, excluding a low gabled red tile roof. It was dark yellow. It was used as an aircraft fuel storage. The fuel was stored in 200 liter barrels. Total quantity of fuel stored not known.

- Point 19. Two single story buildings, about 10 meters long, six meters wide and five meters high, excluding the low gabled red tile covered roof, of dark yellow color. Both buildings served as storage places for air oraft oil. The oil was stored in 200 liter barrels.
- Point 20. Obstacle course training area.
- Point 21. Building, damaged during the war. The damage was estimated at 40%. It was not repaired in February 1951. It was used for storing straw. It was a three story, brick building, of dark gray color.
- Point 22. Single story, brick building, about 15 meters long, six meters wide and five meters high, excluding the low, gabled red tile roof. It was dark gray. It was used as a barn for four hourses and one cart.
- Point 23. Building, damaged during the last war. The damage was estimated at 70%. It was still in state of disrepair in February 1951.
- Point 24. Building, damaged during the last war. The damage was estimated at 30%. It was not repaired at the time of observation. It was used for dumping the explosive charges from old bombs.
- Point 25. Concrete road, about four meters wide.
- Point 26. Three story, brick building, about 40 meters long, 15 meters wise and 25 meters high, excluding the low, gabled, red tile roof. It was dark gray. This building housed the fighter training regiment's maintenance personnel, including officers, and the fighter pilot students. The offices of the fighter training squadron and classrooms were also located there. A total of approximately 110 military personnel were quarted in this building.
- Point 27. Building, of exactly the same construction, dimensions and color as building described in Point 26. During the last war it was damaged approximately 40%. Repair work started in 1950 and was still in progress in February 1951. The repairs should be completed by July 1951. The first floor was used as kitchen and mess-hall for aircraft maintenance personnel.
- Point 28. Building, exactly the same as those described in Points 26 and 27. During the last war it was damaged approximately 50%. Repair work started during 1950 and was completed the same year. The whole building was used as a hospital, and capable of accomodating 150-200 patients.
- Point 29. Single story building damaged about 40% during the last war. It had not been repaired and was not used in February 1951.
- Point 30. Single story building, damaged about 30% during the last war. It was still in a state of disrepair, and was used for storage of straw.
- Point 31. Single story, brick building situated on an earth mound about ten meters high. The building was about fifteen meters long, ten meters wide and eight meters high, excluding a low gabled, red tile roof. It was dark gray.
- Point 32. Densely covered area of deciduous trees. The trees averaged about 20 meters in height.
- Point 33. Earth pathway, about three meters wide.
- Point 34. Concrete road, about four meters wide, leading from the gate to the hospital building.
- Point 35. Two story brick building, about 25 meters long, 15 meters wide, and 15 meters high, excluding a low gabled, red tile roof. The building was still being constructed in February 1951. _______it would be used as quarters for married officers. Construction was started in April 1950.

50X1

- Point 35A. Two story, new brick building, about 20 meters long, 15 meters wide, and 15 meters high, excluding the low gabled, red tile roof. The building was still in construction in February 1951. It will be used for the same purpose as building described in Point 35. This construction was started in April 1950.
- Point 36. Two story, brick building, about 20 meters long, 15 meters wide and 15 meters high, excluding the low gabled, red tile roof. It was dark gray. It was used as a guardhouse. This building was connected by a wall with the building described in Point 35A. It was a three story brick building about 30 meters long, 15 meters wide and 22 meters high, excluding the low gabled, red tile roof. It was dark gray. The first floor housed the offices of the Security Section, (Deffensiv Osztaly); the second and third floors housed the offices of the fighter and ground attack training regiments, the office of the airfield Commanding Officer, the Quartermaster offices, (Gazdasag Hivatal) and the engineering offices of the fighter and ground attack training squadrons.
- Point 37. Concrete sidewalk, about three meters wide.
- Point 38. Gravel covered road, leading from the airfield to Kecskemet city, about six meters wide and in poor condition.
- Point 39. Dirt road, about four meters wide, leading to farm houses.
- Point 40. V ehicle and pedestrian gates. The vehicle gate, was of two metal sections. It was about six meters wide and two meters high. The pedestrian gate was also of metal and about two meters wide and two meters high.
- Point 41. Concrete road, about four meters wide.
- Point 42. Single story brick building, about 20 meters long, 10 meters wide and six meters high, excluding the low gabled, red tile covered roof.

 It was dark gray. It was used as mess-hall for officer and student.

 This building was called the "Navigators' mess-hall" (Hajozo Etkezde).
- Point 43. Concrete area, approximately 30 meters in diameter.
- Point 43A. Concrete covered area, approximately 10 meters in diameter.
- Point 44. Brick sidewalk, about three meters wide.
- Point 45. Two story, brick building, about 25 meters long, 15 meters wide and 15 meters high, excluding the low gabled, red tile roof. It was dark gray. It served as quarters for bachelor pilot officers. About 30 officers were quartered there. This building was called the "Navigators' building," (Hajozo Epulet).
- Point 46. Athletic field of sand, about 150 by 50 meters.
- Point 47. Underground fuel storage area, constructed of concrete. The visible concrete surface was about 30 by 15 meters. There was a small construction on top which served as fuel outlet.
- Point 48. Monument, (Obelisk) constructed of white stone, about six meters high.
- Point 49. Concrete road, about four meters wide.
- Point 49A. Concrete covered rectangular area, about 20 by 15 meters.

SEGRET

SECRET

- Point 50 and 50A. Three story, brick building shaped like an "L". The section shown as Point 50, is about 35 meters long, and 15 meters wide. The section shown as Point 50A, is about 20 meters long, 15 meters wide. The whole building was about 24 meters high. It was dark gray. The building has a cellar, covering its whole area. The roof was flat, concrete, and covered with black tar paper. This building was used for quarters for the ground attack training regiment, including students, mechanics (both officers and enlisted helpers). It housed about 110 persons. The offices of the ground attack training squadron were also located there.
- Point 51. Two story, brick building, about 50 meters long, 20 meters wide and 15 meters high. It was dark gray. The roof was flat, concrete and covered with black tar paper. On the first floor in the northeastern half were quarters for enlisted guards. On the first floor, in the southwestern half, were offices of guard section (squadron). An office of the quartermaster section (Gazdasagi Itivatal) and a barber shop were also located there. Quarters for the rest of the squadron guards were located on the second floor.
- Point 52 and 52A. Single story "L" shaped, brick building. The section shown as point 52 was about 20 meters long. The section shown as Point 52A was about 10 meters long. Both sections were about 10 meters wide and seven meters high, excluding the low gabled, red tile roof. The building dark yellow.
- Point 53. Aircraft field repair truck, containing a large lathe for machine work. The truck was German World War II.
- Points 54 (A, B, C), 55, 56. Two story "L" shaped brick buildings. The section shown as Points 54 and 55, was 40 meters long. The section shown as Point 56 was about 10 meters long. The building was about 15 meters wide and 15 meters high, excluding the low gabled, red tile roof. It was dark gray.
- Point 55. Square glass tower, rising 10 meters above the ceiling of the second story of the building. The top of the tower was flat and also of glass. This was the airfields operations tower. The section shown as Point 54A had a battery shop, and aircraft engine and frame repair shop on the first floor. The second floor housed the weather station. The section shown as Point 54B, housed a carpenter shop and on the first floor, the airfield's post-office on the second. Section shown as Point 54C, housed the parachute shop of the first floor, and the photo-laboratory and the teletype (Hugues) installation on the second floor. Section shown as Point 56 of this building housed the aircraft supply shops on both floors. Engine spare parts, instruments, wheels, tires, ailerons, rudders, elevators and aircraft tools were stored there.
- Point 57. Iron gate about four meters wide and two meters high, supported by concrete posts.
- Point 58. "Hangar No 1" constructed of brick and supported by four reinforced concrete columns, one in each corner. Each of these columns was about meter square. The building was about 50 meters long, 30 meters wide and 20 meters high on the northeastern side, and 15 meters high on its southwestern side. The roof was slanted and of corrugated metal, painted dark green. It was supported by two main transversal steel beams, interconnected by diagonal steel beams. The hangar walls were constructed of brick. The hangar floor was of concrete. The hangar had a corrugated metal door, in two sections, running on rails, covering the whole northeastern side up to the roof. The hangar had windows, covering the entire two side walls. The windows were located about two meters below the roof. Eighteen Yak-9 aircraft without engines were stored in this hangar.

-11:

- Foint 58A. Single story brick construction adjacent to the hangar. It was about 30 meters long, five meters wide and eight meters high including a slanted red tile roof. This building was painted dark gray.
- Point 59. Two concrete strips, each about 40 meters long and four meters wide.

 The grass covered area between the strips was about 50 meters wide.

 These concrete strips were known as the "red lines" (Prios Vonal).

 When the hangar was occupied by operational aircraft, these strips were used for pre-flight inspections and engine warm-up.
- Point 60. Hangar No. 2, of the same construction, dimensions and color as hangar No 1. In February 1951, six Arado-96 aircraft were in storage status, (pickled engines), and six Arado-96 dimensional dimensions and wings) were stored there. On top of this hangar was a wind sock, white with red circles.
- Point 60A. Building of the same construction as building described in Point 58A.

 It was used as electrical, radio, armament, instrument, and photography shop.
- Point 61. Concrete strips of the same dimensions as those described in Point 59
- Point 62. Hangar No 3 of the same construction, dimensions and color as Hangars Nos 1 and 2. In February 1951, the following aircraft were kept there: five Yak-9 aircraft with pickled engines, grounded because of bronze particles found in the oil system; two Yak-9B in good condition, complete and in storage status (engines pickled); four Yak-11 aircraft, frounded for lack of tires; two Zlin aircraft belonging to the fighter and ground attack training regiments respectively. They were on flying status and were used for minor errands to other airfields.
- Point 62A. Building of the same construction, size and used for the same purpose as buildings described in Points 58A and 60A.
- Point 63. Concrete strips, of the same dimensions, and used for the same purpose as strips described in Points 59 and 61.
- Point 64. Iron gate, about six meters wide and two meters high.
- Point 65. Site of a hangar destroyed during the last war. The concrete floor, which was about 80 by 40 meters in area was the only remaining part.
- Point 66. Landing area, of sandy composition, covered sparsely with grass. It was used by all aircraft stationed at this airfield. Rainy weather would not impede operations from this area, since the water was rapidly absorbed in the sandy ground; an artificial drainage system was not available and not necessary.
- Point 67. Area used for conducting flight operations. It was called the "Red Square" (Piros Negyszog). When flight operations were in progress, four benches were installed, forming a square. In the middle of the square was a blackboard, a desk with a bulletin board showing the flight schedule for the day, and a political bulletin.
- Foint 68. Location of the radio-truck used during training operations. This radio-truck usually was used instead of the radio-tower installation.
- Point 69. Portable "T" sign, of white canvas during summer and black canvas during winter. Two other rectangular canvas signs were placed there for easier identification from the air.
- Point 70. Site where two fuel trucks and one oil and water truck were parked during flying operations. One carried 95 octane and the other 87 octane gasoline.


-12-

- Point 70A. Location of cart with mechanics' tools and spare parts. A small truck was also parked there, to take personnel and equipment to and from the flight area. A fire extinguisher push cart also was kept there during flight operations.
- Points 71, 71A, 71B, 71C and 71D. Show the usual take-off and landing patterns for training of students. The take-off point on the runway was opposite the "Red Square", where the aircraft were quickly inspected by maintenance personnel prior to take-off. The take-off signalman was stationed there with a white flag in the right hand to signal the take-off, and a red flag in the left hand, to signal standby.
- Point 72. Firing range, used by all military personnel. Personnel practiced firing about once every month, each man firing approximately ten rounds. This firing range was also used to test the aircraft machine guns. No aircraft on the airfield was armed. The aircraft machine guns were kept in storage. They were installed on the Yak-9, Yak-11, and IL-10 every three months for testing. If the machine gun performed satisfactorily it was returned to storage status. The Yak-9 aircraft were armed, during the tests, with two UBShZ, 12.7 m/m machine-guns, one Shvak, 20 m/m cannon. The Yak-11 aircraft were armed, during the tests, with one UBSh2, 12.7 m/m machine gun. The IL-10 aircraft were armed, during the tests, with two UBShZ, 12.7 m/m machine guns, two 24 m/m cannon, and one UBK, 12.7 m/m machine-gun. The aircraft machine-guns and cannons were fired at stationary targets while the aircraft were on the ground, with engines running, the tail section raised and supported on a barrel in order to have the aircraft and the line of fire parallel to the ground. The firing tests took place at about 700 meters from the target, Tracer bullets were used during firing practice. Both the machine-guns and the cannons used three types of bullets: tracer, armor piercing, and K-6 type. Each UBS machine gun took 150 rounds and each Shvak cannon, 200 rounds.
- Point 73. Single story, brick building, about fifteen by fifteen meters and seven meters high, excluding a low gabled, red tile roof. It is dark yellow. It was off limits to most of the personnel and known as the "radio building."


-end-

ENCLOSURE (A): Overlay sketch of Kecskemet Airfield ENCLOSURE (B): Sketch showing Kecskemet Airfield Installations

SFORET



50X1



SECRET