OUT60620

SECR	082216Z CITE	9284
IDEALIST	To any St. 1 John Marier	

1966 DEC 8 22 26 Z

25X1

25X1

25X1

9 DEC 1966

ard Bu

ECS

PG

730

710

PILLER

Advisor con

ATTN:

C216C

SUBJECT: EVALUATION OF MISSION £1266

- 1. CAMERA B-22 WAS USED IN MISSION C216C FLOWN ON 26 NOVEMBER 1966. PROCESSING WAS ACCOMPLISHED IN THE FIELD.
 - 2. ORIGINAL NEGATIVE:
 - A. DENSITY AND RESOLUTION ARE GOOD.
- B. 9R SIDE: EDGE STATIC IS PRESENT ALONG BOTH EDGES OF THE FILM. PLUS DENSITY SPOTS ASSOCIATED WITH ROLLER CHATTER ARE PRESENT THROUGHOUT THE MISSION. PROCESSING STAINS WERE NOTED AT THE OUTBOARD EDGE OF FRAMES 0006 AND 0836. A REFLECTION FROM THE VERTICAL DOT INDICATOR IS PRESENT IN THE FORMAT ON ALL FRAMES AND IS MORE DETECTABLE OVER LOW DENSITY AREAS. A WAVERING PLUS DENSITY LINE IS PRESENT IN FRAMES 1486 AND 1487. HEAT SPLICES ARE NOTED BETWEEN FRAMES 141/142, 414/415, 547/548, 835/836, AND 1233/1234. A MANUFACTURING SPLICE IS LOCATED IN FRAME 884.
- C. 9L SIDE: EDGE STATIC IS PRESENT ALONG BOTH EDGES OF THE FILM. PLUS DENSITY SPOTS ASSOCIATED WITH ROLLER CHATTER LOCATED NEAR MID FORMAT AND THE OUTBOARD EDGE ARE PRESENT THROUGHOUT THE MISSION. REFLECTIONS ASSOCIATED WITH THE VERTICAL DOT INDICATOR LAMP POSITION IS PRESENT ON ALL FRAMES. A PROCESSING STAIN IS PRESENT ON FRAME 401 OUTSIDE THE FORMAT NEAR THE DATA BLOCK EDGE.

 OPAQUE HEAT SPLICES ARE PRESENT BETWEEN FRAMES 151/152, 423/424,

CORRE

consp 1 25X1 Excluded from colorates dominately and -2-

825/826, AND 1223/1224 AND A MANUFACTURERS SPLICE IS PRESENT IN FRAME 668.

- D. BOTH SIDES: STREAKED OR BLURRED IMAGERY ASSOCIATED WITH VEHICLE MANEUVERS WAS OBSERVED ON 11 FRAMES. THE LAST TITLED FRAME IS 1540.
 - E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.
 - 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING WERE GOOD.
- C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 10 PERCENT OF THE MISSION.

SECRET

-END OF MESSAGE-