



-2-

NUMBER OF PARALLEL BANDS, THE MOST PROMINENT AND CONSISTENT OF WHICH IS 4.5 INCHES FROM THE INBOARD EDGE. BECAUSE OF AN IMPROPER PRE-SPLICE CUT IN FRAME 1042, A SMALL PIECE OF THE ORIGINAL NEGATIVE WAS CUT OUT. A HEAT SPLICE ALSO APPEARS BETWEEN FRAMES 0913 AND 0914. THERE IS A CREASE TOWARD THE BASE ALONG THE INBOARD EDGE IN FRAMES 0909 AND 0910. A DIAGONAL CREASE TOWARD THE BASE ACROSS THE MINOR AXIS IS PRESENT AT THE OUTBOARD EDGE OF FRAME 1201. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 0125.

D. SLIGHT FOGGING PROBABLY CAUSED BY INTERNAL REFLECTIONS, IS FOUND IN FRAMES 0001, 0005, 0021 AND 0025. THE MISSION IS TITLED FROM 0001 THROUGH 2117.

E. NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS ARE EVIDENT.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS AND HAZE DEGRADE APPROXIMATELY 35 PERCENT OF THIS MISSION.

S E C R E T

--END OF MESSAGE--