



-2-

C. 9L SIDE: EDGE FOG IS PRESENT ON BOTH INBOARD AND OUTBOARD EDGES THROUGHOUT THE MISSION. A SLIGHT OVERLAPPING OF FRAMES APPEARS AT THE START OF THE MISSION, BUT CLEARS UP IMMEDIATELY. EMULSION LIFTS ARE PRESENT INTERMITTENTLY THROUGHOUT. FOREIGN MATTER IS OCCASIONALLY FOUND ON THE EMULSION SIDE OF THE FILM. ROLLER CHATTER ON THE INBOARD EDGE IS PRESENT INTERMITTENTLY. CAMERA POSITION INDICATORS ARE EITHER VERY LIGHT OR MISSING ENTIRELY THROUGHOUT THE MISSION. TITLE FLAKING AND GHOSTING IS PRESENT IN VARYING DEGREES THROUGHOUT. A MANUFACTURER'S SPLICE WAS FOUND BETWEEN FRAMES 0914 AND 0915.

D. BOTH SIDES: EDGE STATIC IS PRESENT ALONG BOTH SIDES OF THE FILM THROUGHOUT THE MISSION. PINHOLES WERE ALSO NOTED INTERMITTENTLY THROUGHOUT. THE FRAMES ON EACH SIDE OF THE MISSION ARE TITLED FROM 0000 TO 2524.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS APPARENT.

3. POSITIVE:

A. THE PI SUITABILITY IS FAIR.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADED OR OBSCURED APPROXIMATELY 70 PERCENT OF THE MISSION.

S E C R E T

--END OF MESSAGE--