

OUT57524

**SECRET**

S E C R E T 112207Z

1966 JAN 11 22 23Z



12 JAN 1966 25X1

1. CAMERA NUMBER B-7 WAS USED IN MISSION 8066 FLOWN ON 7 JANUARY 1966. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD.

B. 9R SIDE: ROLLER CHATTER IS PRESENT ON THE INBOARD EDGE OF THE FILM THROUGHOUT THE MISSION, AND ALSO ON THE OUTBOARD EDGE OF FRAMES 1 THROUGH 150. THE POSITION INDICATOR LAMPS FOR 1R, 2L, AND 2R ARE VERY WEAK AND ALMOST UNREADABLE ON THE FIRST 600 FRAMES. A WAVERING PLUS DENSITY STREAK, RANGING 1 TO 2 INCHES FROM AND ALMOST PARALLEL TO THE INBOARD EDGE OF THE FILM, IS PRESENT ON FRAMES 1 THROUGH 102. SEVERAL PLUS DENSITY STREAKS PARALLEL TO THE MAJOR AXIS ARE PRESENT IN THE FORMAT OF FRAMES 1137 THROUGH 2212. MINUS DENSITY DOTS ARE LOCATED 1.88 INCHES FROM THE OUTBOARD EDGE AND 1.58 INCHES APART THROUGHOUT THE MISSION. A FINE MINUS DENSITY STREAK, 1.35 INCHES FROM AND PARALLEL TO MAJOR AXIS, IS PRESENT ON FRAMES 840 THROUGH 978. AN EMULSION BLISTER AND ASSOCIATED PROCESSING EFFECT IS ON FRAME 393. A MANUFACTURERS SPLICE WITH ASSOCIATED FOG IS INSIDE THE FORMAT OF FRAMES 106 AND 389. A HEAT SPLICE IS ACROSS THE FORMAT OF FRAME 1114.

No	Action
1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
100	
101	
102	
103	
104	
105	
106	
107	
108	
109	
110	
111	
112	
113	
114	
115	
116	
117	
118	
119	
120	
121	
122	
123	
124	
125	
126	
127	
128	
129	
130	
131	
132	
133	
134	
135	
136	
137	
138	
139	
140	
141	
142	
143	
144	
145	
146	
147	
148	
149	
150	
151	
152	
153	
154	
155	
156	
157	
158	
159	
160	
161	
162	
163	
164	
165	
166	
167	
168	
169	
170	
171	
172	
173	
174	
175	
176	
177	
178	
179	
180	
181	
182	
183	
184	
185	
186	
187	
188	
189	
190	
191	
192	
193	
194	
195	
196	
197	
198	
199	
200	
201	
202	
203	
204	
205	
206	
207	
208	
209	
210	
211	
212	
213	
214	
215	
216	
217	
218	
219	
220	
221	
222	
223	
224	
225	
226	
227	
228	
229	
230	
231	
232	
233	
234	
235	
236	
237	
238	
239	
240	
241	
242	
243	
244	
245	
246	
247	
248	
249	
250	

Advance copy  
Sanitized

**SECRET**



-2-

C. 9L SIDE: ROLLER CHATTER IS PRESENT ON THE INBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. MOST OF THE POSITION INDICATOR LAMPS WERE WEAK AND ALMOST UNREADABLE IN THE FIRST HALF OF THE MISSION. A FINE PLUS DENSITY STREAK LOCATED 2.1 INCHES FROM AND PARALLEL TO THE INBOARD EDGE IS PRESENT ON FRAMES 1 THROUGH 6. SEVERAL INTERMITTENT <sup>N</sup>LOGITUDINAL PLUS DENSITY STREAKS ARE PRESENT IN THE FORMAT OF FRAMES 1215 THROUGH 1780. A HEAT SPLICE WAS MADE INSIDE THE FORMAT OF FRAME 1178, AND BETWEEN FRAMES 99 AND 100.

D. INTERMITTENT EDGE FOG AND EDGE STATIC IS PRESENT THROUGHOUT THE MISSION. THE CLOCK COUNTER REGISTERED NUMBERS WERE 9996, 9998, 9999, 0000 THROUGH 2208. THE FRAMES WERE TITLED 0001 THROUGH 2212.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 10 PERCENT OF THE MISSION.

S E C R E T

-END OF MESSAGE-