

OUT57258

1965 NOV 26 23 45Z

*multi*

P 262320Z  
 FM NPIC WASHDC  
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB  
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAA/2D RTS BARKSDALE AFB LA  
 RUEKDA/DIA WASHDC  
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
 RUEPIA/CIA WASHDC  
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUWGAA/2 AF BARKSDALE AFB LA  
 BT  
 S E C R E T CITE NPIC 5993.

29 NOV 1965  
DISTRIBUTION

Cy No.	Office	Action
1	File	
	CS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PP	
	FSD	
	PSD-ICB	
3, 4	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI)

1. CAMERA B 7 WAS USED IN MISSION 8058 FLOWN ON 24 NOVEMBER 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: SLIGHT EDGE FOG WAS NOTED ON THE INBOARD EDGE OF APPROXIMATELY THE FIRST 20 FRAMES. MINOR ROLLER CHATTER IS PRESENT ALONG BOTH EDGES BUT IS MORE PRONOUNCED ON THE INBOARD EDGE. TWO ROWS OF MINUS DENSITY DOTS ARE PRESENT APPROXIMATELY 2.1" FROM THE OUTBOARD EDGE. THEY ARE 2.3" AND 1.6" APART AND ARE NOTED THROUGHOUT THE MISSION. ANOTHER ROW OF MINUS DENSITY DOTS 0.5" FROM THE INBOARD EDGE AND 1.6" APART WERE NOTED IN THE FIRST 2/3 OF THE MISSION. MANY INCONSISTENT PLUS DENSITY LINES PARALLEL TO THE MAJOR AXIS WERE NOTED FROM FRAME 21 TO THE END. THE MOST PRONOUNCED PLUS DENSITY LINE IS LOCATED 2.1" FROM THE OUTBOARD EDGE. A HEAT SPLICE IS LOCATED BETWEEN FRAMES 259/260.

Advance copy  
Sanitized

Declass Review by NGA

-2-

A BREAKDOWN SPLICE WAS MADE ACROSS THE FORMAT OF FRAME 662. AS A RESULT OF THIS SPLICE CHEMICAL CONTAMINATION WAS NOTED IN FRAME 663/664. IRREGULAR PLUS DENSITY STREAKS WERE LOCATED IN DIFFERENT AREAS OF FRAMES 1002/1003 AND 1006/1007.

C. 9L SIDE: ROLLER CHATTER IS PRESENT ON THE INBOARD EDGE THROUGHOUT THE MISSION. NUMEROUS INCONSISTENT PLUS DENSITY STREAKS, PARALLEL TO THE MAJOR AXIS, ARE PRESENT THROUGHOUT. IN THE EARLY PORTION OF THE MISSION THE MOST PRONOUNCED PLUS DENSITY STREAKS ARE LOCATED 2.1" AND 2.7" FROM THE INBOARD EDGE. DURING THE LATTER PORTION THE MOST PRONOUNCED PLUS DENSITY STREAKS ARE LOCATED 1.7", 4.1" AND 4.7" FROM THE INBOARD EDGE. SEVERAL EMULSION DEFECTS ARE PRESENT THROUGHOUT THE MISSION. EXAMPLES MAY BE SEEN ON FRAMES 528, 572 AND 657. A MANUFACTURERS SPLICE WITH ASSOCIATED FOG AND A BIASED MINUS DENSITY STREAK IS PRESENT ON FRAME 153. A HEAT SPLICE IS LOCATED BETWEEN FRAMES 488/489. A BREAKDOWN SPLICE WAS MADE INSIDE THE FORMAT OF FRAME 660. CHEMICAL CONTAMINATION CAUSED NUMEROUS PLUS DENSITY DOTS AND MINUS DENSITY STREAKS IN FRAMES 660/661.

D. BOTH SIDES: EDGE STATIC IS PRESENT ON BOTH EDGES THROUGHOUT THE MISSION. THE VERTICAL DOT INDICATOR IS BLOOMED. METERING IS IRREGULAR RANGING FROM 0.4" TO 0.7". THE LAST TITLED FRAME IS 1368.

E. THERE WERE NO MAJOR CAMERA AND PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 40 PERCENT

OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-