

OUT57155

1965 NOV 12 22 45Z

15 NOV 1965

multi

P 12223Z
 FM NPIC WASHDC
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECY/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2 AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 5893.

DISTRIBUTION		
Cy No.	Office	Action
1	FFE	
2	OS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PSD	
	PSD-ICB	
3,4	TID	✓
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR Dab).

- CAMERA B 7 WAS USED IN MISSION 8054 FLOWN ON 9 NOVEMBER 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
- ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS FAIR TO GOOD.

B. 9R SIDE: FOG INDUCED BY ROLLER PRESSURE IS CONTINUOUS NEAR BOTH FILM EDGES THROUGHOUT THE MISSION. STATIC DISCHARGES CAUSED INTERMITTENT TRACES OF FOG AT THE OUTBOARD FILM EDGE.

THERE IS A MANUFACTURING SPLICE ON FRAME 1536.

C. 9L SIDE: EDGE FOG IS PRESENT INTERMITTENTLY ALONG BOTH EDGES. FOG DUE TO ROLLER PRESSURE IS CONTINUOUS NEAR THE INBOARD EDGE. THE 1L POSITION INDICATOR RECORDED FAINTLY. THERE IS A MANUFACTURING SPLICE ON FRAME 1992 AND A HEAT SPLICE BETWEEN FRAMES 910/911.

D. BOTH SIDES: THE FIRST TITLED FRAME ON EACH SIDE IS

Advance copy
Sanitized

Declass Review by NGA

-2-

0000 AND THE LAST IS 2354. THE FRAMES EXPOSED IN THE 1L POSITION FOLLOWING THE 2R POSITION ARE USUALLY CONSIDERABLY DEGRADED. THE DEGRADATION APPEARS TO BE THE RESULT OF VIBRATIONS.

E. THERE WERE NO APPARENT CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVES:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS FAIR TO GOOD. THE PHOTO INTERPRETERS COMMENTED THAT IMAGE SMEARING ASSOCIATED WITH VEHICLE MANEUVERS APPEARED EXCESSIVE.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 20 PERCENT OF THE MISSION. GP-1.

S E C R E T

-END OF MESSAGE-