



-2-

IS PRESENT THROUGHOUT THE MISSION. THERE ARE SCRATCHES ACROSS THE  
FORMAT APPROXIMATELY 3.0" FROM DATA BLOCK EDGE IN FRAME 170.

A MANUFACTURING SPLICE IS LOCATED IN FRAME 171.

D. BOTH SIDES: FOG CAUSED BY NON-IMAGE FORMING LIGHT  
OBSCURES APPROXIMATELY 50 PERCENT OF THE DATA BLOCK ON ALL  
FRAMES. A CHANGE IN DENSITY WAS NOTED IN SOME VERTICAL FRAMES.  
THIS IS PROBABLY AN INTERNAL CAMERA REFLECTION. SOME FRAMES  
WERE NOTED TO HAVE SMEAR BUT THIS HAS BEEN ATTRIBUTED TO VEHICLE  
ROLL. THE LAST TITLED FRAME IS 2083.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 20 PERCENT OF  
THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE--