## Proj. 997584 Approved For Release 2002/01/02 : CIA-RDP78B04747A00300060001-2

Reid 13 Way 65

	PROBLEMS	REMEDY
9 Apr	(1) Could not get the magenta dye to plate (2) Spots & Streaks	Cleaned relay switches
12 Apr	<ul><li>(1) Machine would not step automatically</li><li>(2) Spots &amp; Streaks</li></ul>	Cleaned <u>all</u> relay switches
13 Apr	(1) Anode wire broke off Magenta dye tank (2) Spots and Streaks	Replaced Anode wire Anode wire
14 Apr	(1) Paper in 2nd box has \(\frac{1}{4}\)"  Plating edge as compared to \(\frac{1}{2}\)"  in 1st box  (2) Dye layers would  not plate  (3) Spots & Dyes	lined paper up slightly slower than original box  Cleaned anode racket & switch
15 Apr	(1)Unable to get good D min and D max (2) Spots & Streaks	Mixed new chemicals
16 Apr	(1) Spots & Streaks	
19 Apr	Off annual leave	
20 Apr	(1) Spots & Streaks	Eliminated by using auxiliary blower
21 Apr	(1) Unable to raise dye tanks	re-adjusted top limit switch
22 Apr	(1) Spots & Streaks	
23 Apr	Spots & Streaks	Received auxiliary blower from & new wiring diagram. Installed it and spots & streaks eliminated
26 Apr	No problems	Wrote evaluation of the machine and turned in report to Jack
27 Apr	Optical Sled	Called

## **Declass Review by NIMA / DoD**

drive motor worn out

STATINTL

STATINTL