

SECRET
APR 18 11:50
ER

2630

KA014/18

OO YFEAB
DE YFAGNXF 06M
"EXCLUSIVE FOR CIA, WATCH OFFICER"
TOP SECRET //

O 177330Z
FM AFSSO 3TH JF
TO AFSSO HQ USAF
CITE GTS--46-58. (SECTION TWO AND FINAL)
/LIMITED DISTRIBUTION/

THIS IS AN MESSAGE.
0402 SIGNAL WEAKER NOW, HEARD ONLY OCCASIONATLY.
0404 SIGNAL NOW ON RIGHT SIDE, ZEAQWM
0406 SIGNAL DOW.
0407 SIGNAL UP AGAIN

EFT SIDE, FAIRLY STRONG. /R SILL
APPROX 9.6 SEC. (TAPE SPEED VAYING)
0412 1/2 APPROX 4 MED PRF'S UP SUDDENLY LEFT SIDE ALL WEAK.
UNABLE TO SEPARAE FOR S/G.
0418 ONE MED PRF HAS 2.5 SEC S/R. UNABLE TO SEPARATE OTHERS
FOR S/R DUE TO VARYING TAPE SPEED AND SINILAR PRN'S OF SIGNALS.
0422 SIGNALS FAIRLY STROMG.
0425 SIGNALS FADED.
0430 SIGNALS DOWM. (IKC TONE VARYING 900-1100CPS)
0445 NO SIGNALS PRESENT.
045 MED PRF LEFT SIDE, WEAK TAO OF THEM BM ONE 5.2 SEC S/R,
OTHER 9.6 SEC S/G. MORE SIGNALS MAY BE PRESENT.
TAI SPEED FLUCTUATING)
0458 SIGNALS FADED AND CAME BACK UP AND RIGHT SI
0502 MORE THAN TWO SIGNALS PRESENT. UNABLE TO SEPARATE DUE TO
SIMILAR PRF'S AND FLUCTUA58, & 5-03 033\$.
0504 HI PRC LEFT SIDE, WEAK HEARD ONLY OCCASIONALLY.
0505 172 MED PRF RIGHT S

DE 9.6 SEC SBXR STRONVER THAT OTHER
SIGNALS NOW.
0509 9.6 SEC S/R SIGNAL RIGHT SIDE IN ONLY SIGNAL AUDIBLE.
0511 MED
0511 ME PRF RIGHT SIDE FADING IN AND OUT. HI PRF LEFT SIDE,
ONE I
LUM HEARB. (TAPE SPEED VARYING).
0515 NO SIGNATS PRESENT.
0530, 0545; 305&0515

25X1
25X1

ONE IALUM
 0515 NO SIGNALS PRESENT.
 0530, 054 NO SIGNALS PRESENT.
 0556 ME RPF RIGHT SIDE. WEAK, 7.3 SEC S/R. (TAPE SPEED VARYING)
 0600 SIGNAL HEARD OCCASIONALLY.
 0604 TWO MED PRFBJS NOW RIGHT SIDE, SECOND ONE VRY WEAK
 0606 1/2 MED PRF LEFT SIDE, ONE ILLUM.
 0610 1/2 MED PRF LEFT SIDE HAS SR ON 0.3 SEC. TAPE SPED VARYING.
 A SECOND MED IRFNLEFT SIDE HAS A POSSIBLE S/R OF 4.7 SEC.
 0615 SEVERAT SIGNALS LEFT SIDE, MED PRF'S, TOO CLOSE TO SEIARATE.
 SIGNALS AR FAIRLY STRONG. TAPE SPEED VARYING, PRF'S C ANGING AS
 MUCH AS 75-100-PPS ESTIMATED.
 0618 ONE MED PRF LEFT SIDE AUDIBLE FOR 360 DEGREE MOVEMENT OF
 ANTENNAE.
 020 END REL NR 2. START REEL NR 3. NO SIGNALS RIGHT SIDE.
 0622 BOTM SIGNALS LFT SIDE NOW 0 DEGREES OR 180 DEGREES TO
 A/C.
 PYWE SIGNALS NOW BACK TO LEFT SIDE. TAPE SPEED VARTING MAKES IT
 DIFFICULT TO DETERMINE THE NUMBER OF SIGNALS PRESENT.
 0626 SIGNALS FADING.
 063 SIGNALS VERS WEAK.
 0642 SIGNALS DOWN.
 0645 NO SIGNALS PRESENT.
 0700 NO SIGNALS IRESENT. (TAPE SPED VARYING"
 0710 MED IRF LEFT SIDE, TWO ILLUMS HEARD.
 0713 MED PRF LEFT SIDE, SAME SIGNAL: 4.0 SEC S/R BELIEVE SBXR
 IN ERROR.
 0715 INTERCEIT AT 0713. S/R NOW .1 SEC. TWO SIGNAZS APPROV SAME
 PRF AND S/R PRESENT.
 0722 OTHER MED PRFS/ POSSIBLY 8.5 SEC.
 0732 SIGNALS DADING IN AND OUT. SEMED STRO GEST FROM 0727 TO
 0730.
 0740 SIGNALS HEARD OCCASIONALLY.
 0745 SIGNALS DOWN.
 08008 0815 NO SIGNALS PRESENT. (TAPE SPEED VARYINB)
 0830 NO SIGNALS PRESENT.
 0834 MED PRF LEFT SIDE, WEAK, ONE ITLUM HEARD.
 0838 1/2 CHATTERING MED PRF
 0845 MED PRF LEFT S EFT SIDE, 17.1 SEC S/G.

-----H/W RPTNG -----
 0838 1/2 CHATTERING MED PRF LEFT SIDE, 17.1 SEC S/G.
 0845 MED PRF LEFT SIDSSN WEAK, ONE ILLUM. CHATTETNZD PRF STILL
 PRESENT.
 075

-----H/W RPTNG -----
 0845 MED PRF LEFT SIDE WEEAK, ONE ILLUM. CHATTERING PRF STILL
 PRESENT.
 075 LGCHATTERING PRF NOW RIOHTRBSSOA
 0848 CHATTERING TRF NOW LEFT SIDE. (RECORDER SPEED STILL
 VARYING)
 0854 MED PRF RIGHT SIDE, WEAK.
 0856 1/2 HI PRF LSIDE, 5.0 SEC S/R. LOW PRF ALSO EFT SIDE,
 TOO WEAK O ANALYZE.
 0858 ANOTHER MEDPRF LEFT SID 8.4 SEC S/G.
 70859 MULTIPLE SIGNALS LEFT SIDE NOW.
 0903 1/2 ALL SIGNALS DOWN ABRUPTLY.
 ALL TIMES AND SAEP RATES ARE POSSIBLY IN ERROR DUE TO FLUCTUATING
 RECORDER PEED ABOARD A/C. IKC TONE VARIED BETEEN APPROX 900-1100
 PS.
 4600 4600
 17/1625Z APR

NNNN
 TOT: 18/1620Z APR
 TOR: 18/1621Z

TOP SECRET

9