

- 1. WE ACCEPT FULL RESPONSIBILITY FOR ROLL WOUND BACKWARDS REFERENCE PARA 1A. ON RECEIPT OF FILM HERE WILL ISSUE CREDIT.
- 2. 2 ROLLS OF FILM REPORTED AS WATER DAMAGED AND TELESCOPED PER REFERENCE PARAGRAPHS 1B AND C WE FEEL ARE DUE TO TRANSPORTATION AND HANDLING. THESE EMPHASIZE NUMEROUS COMPLAINTS FROM DETS. ON CONDITION OF FILM ON ARRIVAL AND REINFORCE NEED FOR COURIER TYPE HANDLING OF RAW STOCK. ALSO WE KNOW WOODEN BOXES ARE NOT HANDLED OR STORED CAREFULLY BECAUSE OF WEIGHT AND BULK. STRONGLY RECOMMEND CONSIDERATION BE GIVEN TO PURCHASE OF MORE STEEL BOXES. THESE 2 ROLLS OF FILM WOULD HAVE OBTAINED FOR YOU 17 STEEL BOXES.
- 3. AM REEMPHASIZING TO PRODUCTION DEPARTMENT NEED FOR CAREFUL CHECK OF ALL BOLTS. HOWEVER WE FIND BOLTS WORK OUT EASILY DURING SHIPMENT AND HAVE RECOMMENDED TO THAT LOCK WASHERS BE PLACED UNDER HEADS OF BOLTS.

25X1

Copy No.

END OF MESSAGE

SECRET

REFRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.