

T-O-P S-E-C-R-E-T

TO: Project Hqs.

OTIE: ADIC

From:

~~OPER. IMMED.~~  
PRIORITY

25X1

HBJARGON-X

Mission 2009

PRIMARY CAMERAS malfunctioned after 20 minutes of operation due to failure of IMC Report IMC motor. Drive shaft or armature was frozen. Tracker film operated for a total of 6 hours. Operation was satisfactory. Approximately 650 feet of 70mm was exposed. Mission 2010. Post flight inspection revealed right oblique camera malfunctioned due to broken shutter spring. Cause determined as metal fatigue. Tracker worked satisfactory exposing 600 feet of 70mm film.