SECRET

OUT61059

P 280134Z JAN 67
FM NPIC WASHDC
TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAAA/2D RTS BARKSDALE AFB LA
RUEPJS/DIA WASHDC
RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWEKNA/15TH AF MARCH AFB RIVERSIDE CALIF
RUCVAAA/2 AF BARKSDALE AFB LA
BT

1967 JAN 28 01 22Z

2 6 JAN 1967

S E C R E T   CITE NPIC 9723.

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOOR, DM 4)

2D AF (FOR DI).

1.   CAMERA B-15 WAS USED ON MISSION G-944 FLOWN ON 25

JANUARY 1967.   PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH

SUPPCEN.

2.   ORIGINAL NEGATIVE:

A.   DENSITY AND RESOLUTION ARE GOOD.

B.   9R SIDE: ROLLER CHATTER IS PRESENT ON BOTH THE INBOARD

AND OUTBOARD EDGES.   FRAMES 1 TO 55 CONTAIN A SMALL CLUSTER OF FOUR

MINUS DENSITY DOTS 1.8 INCHES FROM THE OUTBOARD EDGE AND 0.3 INCH

FROM THE END OF FRAME OPPOSITE THE DATA BLOCK.   FRAMES 708 AND

2255 HAVE A SMALL CIRCULAR FOGGED AREA APPROXIMATELY 0.5 INCH IN

DIAMETER AND 1.0 INCH FROM THE OUTBOARD EDGE.   A FOGGED AREA 0.5

INCH IN WIDTH AND 2.0 INCHES LONG IS PRESENT NEAR THE OUTBOARD

EDGE OF FRAME 2186.   THE LAST FRAME (2255) CONTAINS FOGGING AND A

PLUS DENSITY BAND 0.5 INCH WIDE LATERALLY ACROSS THE FRAME.   A

HEAT SPLICE IS PRESENT IN FRAME 1048 AND BETWEEN FRAMES 984/985,

1205/1206, 1502/1503, 1803/1804 AND 2103/2104.

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	OS	
	SEC BR	
	TDS	
	CSD	
	IPD	
	PD	
	PSD	
	REG-TCB	
3/4	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	

-2-

C. 9L SIDE: ROLLER CHATTER IS PRESENT ON THE INBOARD SIDE THROUGHOUT THE MISSION. NUMEROUS PINHOLES ARE VISIBLE BETWEEN FRAMES 301 TO 900. FRAMES 2134 TO 2257 CONTAIN CRIMPING ON THE OUTBOARD EDGE. A HEAT SPLICE IS PRESENT IN FRAME 997 AND BETWEEN FRAMES 1248/1249, 1532/1503, 1803/1804, AND 2103/2104.

D. BOTH SIDES: THE LAST TITLED FRAME IS 2256. THE DATA BLOCK FRAME COUNTER MALFUNCTIONED ON THIS MISSION. THE COUNTER ON TITLED FRAME 1 READS 0006 AND ON TITLED FRAME 2256 READS 2260. IMAGE DEGRADATION (CROSS TRACK SMEAR) CAUSED BY VEHICLE MANEUVERING WAS OBSERVED ON 13 FRAMES.

3. POSITIVE:

A. THE PI SUITABILITY IS RATED GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURRED APPROXIMATELY 30 PERCENT OF THE MISSION.

GP-1

S E C R E T

--END OF MESSAGE--