ТО	lease 2000/08/24T CLA-RTP33	INITIALS	DATE
1.		-	
2.			
3.			
4.			
5.			
6.			

REMARKS

ACT ION

COMMENT

FORM 1582

RETURN TO SENDER

Re the third centence in Paragraph 2 wherein it states "no sireraft were available in commission to accomplish the one remaining certic." I should state that we had only two aircreft to pick from -- one of which flow the successful mission on 7 October and immediately thereafter required a periodic inspection, and the second of which flow an unsuccessful mission on 5 October which aborted before penatration because of fuel pump irregularities. This siremake of fuel pump irregularities. This siremake that the statement as it stood was a little too baid.

CONCURRENCE

FILE

INFORMATION

SIGNATURE

thou	the that the	SMICH AP H		2 (1) (2) (3)
徐子李明 67		FROM		
AME AND ADDRESS				PHONE NO.
	ID ADDRESS			# 1 4 4 K
				## # T T T
	TAD	OSA CIA PDP33 0		DATE
or Do	いっっこう つかがかがた	DODOO A	24454	つうしゅうしょう こうしゅうしゅう

25X1A9a