

25X1A6a



18 December 1968

25X1A9a

MEMORANDUM FOR: Chief, Archives and Records Center

ATTENTION : Mr. [REDACTED]

SUBJECT : Temperature and Humidity Control in [REDACTED] 25X1A

REFERENCE : A&RC Memo, dtd 1 November 1968

25X1C

25X1A

1. The [REDACTED] Engineer Maintenance Section has responded on numerous occasions regarding problems concerning temperature or humidity in [REDACTED]. Work performed is limited to normal repairs and maintenance, since we are neither staffed or equipped to perform major system redesign or to effect changes in the system as installed.

25X1C4a

25X1C4a

2. In order to define the problem and determine proper action to be taken, an engineering survey and analysis is suggested. This can be done through [REDACTED] our assigned construction and engineering support.

25X1C4a

3. It is estimated that the cost of an engineering study with recommendations for an improved system would cost approximately \$3,000.00. 25X1A Your office should forward a formal memorandum to the [REDACTED], requesting this engineering service. This memorandum should include a fund citation covering the estimated cost of the study.



25X1C4a

~~SECRET~~