	₹₹ ¹ }}	Approved For Release 2006/12/27 : CIA-RDP75B00159R000400100055-7		
	FEET STATE	A CONTROL AND A PARTY AND A PA	AND THE BUILDING STATES	
	*, ·#··	NOTE: SECOND ROUTE TO SECOND ROUTE	COMMENSATION SEASONS SERVICE SPECIAL PROPERTY SPECIAL	
	date	1610Z 17 FEB 66 SECRET 2 12	and the second s	
	e te distribute di secondo di conserva	5 13		
	° 700 2	3 DIRECTOR 6 14	- Control of the Cont	
	FROM:	25X1	THE PERSON NAMED IN COLUMN 2 I	
	\$ 3.94 F.9** *	The state of the s		
	Mostan	: IMMEDIAT	E	
	mpo s	Description of the second of t		
,	25X1	TOR 1627Z 17 FEB 66 0/5/-1°	IN 88691	
,,,,	TO	IMMEDIATE CITE	- CONTRACTOR OF THE PROPERTY O	
25X1		25.		
113.42	l	A CURPLEMENT OF THE PROPERTY O		
- 1.25年的 - 1.36年的 - 2007年		1. SUPPLEMENTARY REPORT FROM 372 ACCIDENT SCENE. AIRCRAFT		
25X	(1	APPROACHED DOWNWIND FROM NORTH TO SOUTH		
		IN AN ATTEMPTED FLAME OUT LANDING. UNOFFICIAL SURFACE WIND		
		REPORT WAS NORTH 15 TO 18 KNOTS. ONE WITNESS THOUGHT AIRCRAFT		
	1	TOUCHED DOWN IN LAST 200 FEET OF RUNWAY AND THEN PULLED UP		
		STRAIGHT AHEAD OVER A RICE FIELD, CLIPPED A LIGHT OR TELEPHONE		
		WIRE, VEERED SLIGHTLY LEFT, LEFT WIND THEN STRUCK		
10 (A)		HOUSING VILLAGE BRICK WALL SHEERING LEFT WING, MAIN PORTION		
		OF FUSELAGE WITH RIGHT WING STRUCK SECOND BUILDING (SAME VILLAGE)		
		AND CAME TO REST WITH NOSE PROTRUDING FROM FAR SIDE OF BUILDING.		
	ζ,	AIRCRAFT FUSELAGE IS ALMOST ENTIRELY COVERED WITH DEBRIS FROM		
		HOUSE. FUSELAGE IS GENERALLY INTACT WITH NOSE SECTION		
)	BADLY DAMAGED FROM IMPACT. PHOTOGRAPHS TAKEN OF ENTIRE AREA	4.	
		2. WILL RETURN TO ACCIDENT SCENE EARLY MORNING 18 FEB W		
		THE FOLLOWING ACTIONS PLANNED OR CONTEMPLATED:		
		GR CUP 3		
1.		SECRET		
		REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.		

S E C R E T	
IN 88691	PAGE 2
A. DEBRIS WILL BE REMOVED FROM AIRCRAFT TO EN	ABLE PLACING
FUSELAGE ON FLAT BED AND BRINGING TO UNDER	COVER. 25X1
B. FUEL, OIL, OXYGEN, AND HYDRAULIC FLUID SAM	PLES
WILL BE TAKEN FROM AIRCRAFT IF POSSIBLE.	
C. IN VIEW OF INITIAL ENGINE PROBLEM I INTEND	TO SALVAGE
ONLY THE FUSELAGE SECTION AND ALL CLASSIFIED EQUIPM	ENT AND HAVE
DESTROY REMAINING DEBRIS.	25X1
3. SINCE AIRCRAFT IS RESTING IN	AND THE
INHABITANTS REMOVED, I INTEND TO COMPLETE THE ABOVE	ACTIONS
AS QUICKLY AS POSSIBLE TO PERMIT RESTORATION OF NORM	MALCY IN THE
AREA AND NOT WAIT FOR ACCIDENT TEAM TO ARRIVE. ALL	RELEVANT
EVIDENCE WILL BE RECORDED AND PRESERVED.	

END OF MESSAGE

SECRET