	그는 하고 그 경에 그리고 하는 것들은 한 사람들은 그리고 있는 그 그리고 하는 것이 되는 것이 없는 것 같다.	
÷.	Members present:	25)
		ali Nasanja
	용 이 보냈다면 하다 등 이 하다님	
•	Rembers absent:	
	us religions in the later and the first time. The second of the second o	
•	Guests at meeting:	25)
•	meeting. New Business:	
	a. The primary reason for this meeting was to have demonstrate a miniature R.F. radio to the Survival Review Board and Project Pilots. A redesigned version is under consideration for development and use in our future operations. The radio consisted of 5 component parts:	25)
	demonstrate a miniature R.F. radio to the Survival Review Board and Project Pilots. A redesigned version is under consideration for development and use in our future operations. The radio consisted of 5 component parts: (1) Receiver 2 1/2" x 1 1/2" x 3 1/2"	25
	demonstrate a miniature R.F. radio to the Survival Review Board and Project Pilots. A redesigned version is under consideration for development and use in our future operations. The radio consisted of 5 component parts: (1) Receiver 2 1/2" x 1 1/2" x 3 1/2" (2) Transmitter 2 1/2" x 1 1/2" x 3 1/2"	25
	demonstrate a miniature R.F. radio to the Survival Review Board and Project Pilots. A redesigned version is under consideration for development and use in our future operations. The radio consisted of 5 component parts: (1) Receiver 2 1/2" x 1 1/2" x 3 1/2"	25
	demonstrate a miniature R.F. radio to the Survival Review Board and Project Pilots. A redesigned version is under consideration for development and use in our future operations. The radio consisted of 5 component parts: (1) Receiver 2 1/2" x 1 1/2" x 3 1/2" (2) Transmitter 2 1/2" x 1 1/2" x 3 1/2" (3) Antenna, 100 feet of teflon coated wire.	25

b. brought to the attention of the Board that the Directorate of Aero Space Safety suspects that the SR-71 inertia reel does not properly position the pilot for ejection. Life Support Division will investigate

25X1

25X1A

25X1

On file USAF release instructions apply.

this problem.

presented to the Soard several questions 25X1A concerning the face plate heat system: The aircraft electrical system is 28 (1)volts; the nominal face plate heat hattery pack output is 40 volts. Will this 12 volt increase tend to damage the face plate? If the Green Apple is activated in the cockpit, will the face plate heat be energized by both electrical systems? If so, will this damage the visor? 25X1A will investigate this and provide the Project Pilots with this information. 25X1A showed a locally manufactured safety protector for the Red Apple during ground operation. Board recommended that it be accepted for use. 25X1A

MSgt, USAF

Recorder-Member

25X1A

Captain, USAF Acting President

ACTION BY THE CONVENING AUTHORITY:

APPROVED/DISAPPROVED