Approved For Release 2000/08/04-SIA BDP76-04720A000100030039-4

10 March 1953

MEMORANDUM FOR THE RECORD

OFVAACA GIID TOOM

25X1A6a

SOV I WOS SORPECT:	Emergency Planning		
PRESENT:			
25X1A9a			

TIME : 10 a.m., 9 March 1953

PLACE : Room 225 Administration Building

- 1. We reviewed the Security Report and reached an agreement for solution or for tabling of all issues but one, that of the suggestion for a horse patrol. All present agreed that various considerations, including the lack of perimeter fencing, coverage of the power site, reservoir, springs, etc., argued for the necessity of a horse patrol. It was thought that two horses would do it.
 - a. In response to the item regarding improvement of badging procedures, investigation indicates that we will have to invest \$650 for equipment; all concerned feel this is very necessary.
 - b. The automatic warning system for the tower site is under engineering study by the Commo people.

c. The local "gadgeteers" at think they can solve the automatic

- lock for the elevator.
- e. Security commented that generally security conditions 25X1A9a
 - 2. The items reported in the Safety and Fire Inspection Survey were covered. There are several items, some of considerable cost, which must be met.
- 25X1A6a

 The most important and most expensive is the problem of sufficient water at the problem of water for fire protection, but, under full occupancy conditions in the middle of the summer, there may be need for water even for domestic use. My recommendation is that the Assistant Deputy Director (Administration) direct and 25X1A9a

 25X1A6a

 25X1A6a

25X1A6a the to conduct a full staff study and authorize them to employ, if necessary, a geologist or engineer specifically qualified for this problem.

Approved For Release 2000/00/04_CIA-RDP78-04720A000100030039-4

b. An exhaust fan must be installed in the operating room at the dispensary at a cost of \$95. The cost is this high because the motor must be explosion proof.

25X1A

- c. Fire escapes from the top two floors of _____ are essential. They should be outside and constructed of metal at roughly \$700 apiece. This should be authorized.
- d. Construction of an incinerator for the burning of trash and garbage should be immediately authorized. The minimum cost to take care of the present amount of trash and garbage would be approximately \$350. However, it should be constructed to meet capacity needs, which probably would run the price up to \$800. At the present time, trash and garbage are being burned at the edge of the property where the fire hazard is a real one. Open burning is never satisfactory.
- e. Purchase of a rubber floor pad for insulation purposes in front of and around the main switch gear in the emergency generator house should be made immediately at cost of about \$80.
- f. Four back packs for use in fighting brush fires should be purchased immediately at the approximate cost of \$33 each.

It should be noted that the preponderance of the safety problems related to fire. They are all important and should receive immediate attention.

25X1A6a

3. At the completion of the Security and Safety discussions, a second meeting was held to review the present state of emergency planning. Only and myself were present. Generally,

25X1A9a |

emergency planning for can be summarized by saying that within the limita-25X1A6a tions of the definite planning provided by the Agency to date, is ready for business. Many fundamental considerations which have been raised must await 25X1A6a action on the substantive planning issue which is now getting started with a memorandum from the Deputy Director (Administration) to the other Deputies, Director of Training, and Assistant Director for Communications. There remain a few items which will be required under any circumstances, but which will require the expenditure of additional funds and under the general economy pattern these will be raised specifically at the Wednesday (11 March) meeting.

25X1A9a attempt to further revise, at least in any fundamental fashion, their emergency

plan until the substantive determinations have been reached.

25X1A9a