

SECRET

PRIORITY

CIA-2

P 232051Z

FM CIA WASHDC

OUT51910

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

24 SEP 1963

RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA

HFS

RUEAHQ/DIAXX

CJS

RUECYG/NAVY PIC

CPC

RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF

PNS

RUWGAA/2D RTS, BARKSDALE AFB, LA

ACL

RUWGAA/2AF, BARKSDALE AFB, LA

Grace (File)

DA GRNC

BT

S E C R E T

CITE CIA-Z-901

15TH AF (FOR DI); SAC (FOR DIM, BRASS KNOB, DOCR, DM 4); 2D AF (FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 8 WAS USED IN MISSION 3727 FLOWN ON 22 SEPTEMBER 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE. THE RESOLUTION IS GOOD, WHERE NOT ADVERSELY AFFECTED BY CLOUDS AND HAZE.

B. 9R SIDE: INTERMITTENTLY THROUGHOUT THIS SIDE, PARALLEL TO THE MAJOR AXIS OF THE FILM, THERE ARE MINUS DENSITY DOTS 1.55" APART AND 2.9" FROM THE INBOARD EDGE, AND A SCRATCH WITH

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

- 2 -

ASSOCIATED MINUS AND PLUS DENSITIES 3.9" FROM THE OUTBOARD EDGE. THE FILM WAS FOGGED INWARD FROM THE OUTBOARD EDGE ON FRAMES 977 AND 978. BLISTERS ARE APPARENT ON FRAMES 0, 163 TO 177, 738, 2073, 2074, 2077, AND 2083.

C. 9L SIDE: THERE ARE POST PROCESSING CREASES, FOLDS, AND ABRASIONS ON FRAMES 900 TO 907. SMALL CREASES AND HANDLING MARKS APPEAR ON FRAME 1179 ASSOCIATED WITH THE MANUFACTURING SPLICE ON 1178. THE 2L POSITION INDICATOR LAMP WAS INTERMITTENTLY INOPERATIVE DURING THE MISSION.

D. BOTH SIDES: PROCESSING STREAKS ARE PRESENT THROUGHOUT BOTH SIDES OF THE MISSION. THE LAST TITLED FRAME ON EACH SIDE IS 2199.

E. OTHER THEN MENTIONED ABOVE, THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD WHERE WEATHER PERMITS. THE PRINTING AND PROCESSING WAS GOOD.

B. CLOUDS COVERED 90 PER CENT OF THE MISSION. SCP-1

S E C R E T

--END OF MESSAGE

((ABOVE TEXT ALSO PASSED TO CIA WATCH (CGS))