

Enclosed is a modified version of the drawing which you took away with you after your visit here.

STATINTL

The alarm system has been modified in accordance with your wishes to operate in the following way.

1. Transmission Fault

Should the computer fail to reply due to either repeated faulty transmission or failure of the Dataphone or lines, the alarm will sound for a period of about 6 seconds and the "Transmit Fault" lamp will light. The lamp will remain lit until the fault is cleared by pressing the "Reset Logic" button. The lamp may also be extinguished by pressing the "Fault Lamp Reset" button but this will leave the logic in its faulty condition.

2. Digitiser Input Fault

Should one of the basic counters fail due to a faulty input, the alarm will sound for about 6 seconds and the "Digitiser Input Fault" lamp Will light. The lamp will remain lit until the counter in question is reset, and the "Fault Lamp Reset" button is pressed. It should be remembered that there is also a fault lamp on the scales of the counter which will indicate which of the four counters caused the fault.

STATINTL

Yours sincerely.

Declass Review by NIMA/DOD Appro@EDAFDINRElease 2002/07/10 : CIA-RDP78B04747A000900050020-6			, , ,	
	Declass Review by NIMA/DOD			
ADDIOSEMA DII INCICASE ZUUZIUI IU. CIA-INDI I UDUHIHI AUUUSUUZU-U	, i	47A000900	050020-6	

Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050020-6				
	Done Tele	STATINTL		
	Just a very short note to say how pleasant it was to meet up wit you once again, and I hope that you found your stay with us useful from the point of view of discussing aspects of Dataphone.			
	has certain things to put forward to you which are enclosed with this letter.	STATINTL		
	Please pass on my personal regards to the mad Mexican and I hope we can meet again in the not too distant future.			
		STATINTL		

Approved For Release 2002/01/10: CIA-RDP78B04747A000900050020-6 Approved For Release 2002/07/10 : CIA-RDP78B04747A000900050020-6