

TELEPHONE OR VERBAL CONVERSATION RECORD

Subject of Conversation <i>Dataphone Connector</i>	Date <i>10</i> September 1964
[Redacted]	Telephone Number <i>until 1500 hours</i> <i>393-4778</i>

Information or Action Sought

*To give message to John R. Concerning connections to Dataphone interface to Counter.*

STATINTL

STATINTL

STATINTL

Business machine must hold closure between remote release lead RR pin 19 and remote control lead RC pin 20 in order for data set to get into data mode - paragraph 2.241 of the [Redacted] interface specifications. [Redacted] should have a copy. [Redacted] counter does not make that closure and the two leads must be permanently strapped together in the counter. This can be done either at the cable connectors or any convenient place. That would prevent transmission from taking place. It would be desirable to strap those leads together before he comes here.

Information Given or Action Taken

STATINTL

*The above action had already been taken. [Redacted] should be testing the new unit out by the time of my next visit and I requested that they record it on mag tape through the Dataphones. This will show where the problem is - in the Dataphones hook up or our Dataphone hook up here.*

DECLASS REVIEW by NIMA/DOD

Date <i>10 Sept 1964</i>	Time <i>13:45</i>	Signature
-----------------------------	----------------------	-----------