



~~CONFIDENTIAL~~

10601

CIA IMAGERY ANALYSIS DIVISION

|                                                      |               |                               |
|------------------------------------------------------|---------------|-------------------------------|
| NAME                                                 | COUNTRY       | COORDINATES                   |
| Ban Ca Nan Highway Bridge<br>Bridge No. 1 on NE 48-2 | North Vietnam | 19 20N - 104 16E<br>VG 241391 |
| REFERENCES                                           | BRIEF NO:     |                               |
| PHOTO [REDACTED]                                     | PIB - 65010   |                               |
| MAP AMS 1509 NE 48-2                                 |               |                               |

25X1D

LOCATION: 0.5 nm N.W. of Ban Ca Nan on Route 7

DESCRIPTION:

LENGTH 70' (approx.)  
WIDTH 10' (approx.)  
TYPE Half-through Truss

MATERIAL Steel and Concrete  
NO. OF SPANS 1  
LENGTH OF EACH SPAN

STATUS: Severely damaged - unserviceable, western end of span twisted and out of alignment

COMPENSATIVE ACTION: Ford



Declass Review by NIMA/DOD

~~CONFIDENTIAL~~