


## 2 "Victory" Conversion

AGTR 4 (ex-AG 167) BELMONT (ex-Iran Victory)  
AGTR 5 (ex-AG 168) LIBERTY (ex-Simmons Victory)

Displacement: 7,190 tons light (10,680 tons full load)  
Dimensions: 455 (o.a.) $\times$ 62 $\times$ 24 feet  
Machinery: Turbine. S.H.P.: 8,500=18 kts.  
Complement: 280

### General

Modified "Victory" ships. Conversion completed by Willamette Iron & Steel, Portland, Ore., in Sep. and Dec., commissioned 2 Nov. and 30 Dec. 1964, respectively. Mobile bases for research in communications and electromagnetic radiation.



LIBERTY

1965, courtesy J. A. P. Altornoz


STAT

Approved For Release 2006/05/25 : CIA-RDP84B00049R000902350010-7

Next 3 Page(s) In Document Exempt

Approved For Release 2006/05/25 : CIA-RDP84B00049R000902350010-7

6



DIRECTORATE OF  
INTELLIGENCE

# Intelligence Memorandum

*The Israeli Attack on the USS Liberty*

27

13 June 1967

STAT.

Content UNCLASSIFIED

per #058375

date 31 Aug 1977

SANITIZED COPY

CENTRAL INTELLIGENCE AGENCY  
Directorate of Intelligence  
13 June 1967

INTELLIGENCE MEMORANDUM

The Israeli Attack on the USS Liberty

The US Naval technical research ship Liberty was attacked by Israeli aircraft and torpedo boats off the Sinai Peninsula on 8 June. The following account of the circumstances of the attack has been compiled from all available sources.

1. The Liberty reported at 9:50 a.m. (2:50 a.m. Washington time) on 8 June that it had been orbited by two delta-wing jet fighters, presumably Israeli Mirages. At 3:05 p.m. (8:05 a.m.) the Liberty was strafed by unidentified jet aircraft. The Liberty apparently was not able to establish communications with other units of the US Sixth Fleet during the air attack, and the first information available to the US commanders was after the subsequent attack by unidentified torpedo boats, which occurred at 3:25 p.m.

2. At 4:11 p.m. (9:11 a.m.) the US Commander in Chief, Europe, notified the National Military Command Center in Washington that the Liberty was under attack and was listing to starboard after being struck by a torpedo. The Commander of the US Sixth Fleet declared the attacking units hostile and sent attack aircraft from the carriers America and Saratoga to protect the Liberty. A good part of the ship's communications equipment was destroyed by the crew during the attack but emergency communications were soon established with the Saratoga and with the naval communications station in Greece. Because of the tenseness of the situation and the communications delays, the initial reports from the Liberty were sketchy and somewhat confusing.

#### Specifics of the Attack

3. According to these reports, however, the sequence of events took place as follows. The ship was attacked at 3:05 p.m. (8:05 a.m.) by unidentified jet fighters, believed to be Israeli, at position 31-35N, 33-29E. Six strafing runs were made by the jets. Twenty minutes later three torpedo boats closed at high speed and two of them launched torpedoes after first circling the Liberty. One torpedo passed astern, and the other struck

the starboard side of the ship |

One of the boats was later identified as Israeli and the hull number of one unit was noted as 206-T. Some 50 minutes later two Israeli helicopters arrived on the scene.

Israeli Identification of the Ship

4. None of the communications of the attacking aircraft and torpedo boats is available, |

5. |

Although the Liberty is some 200 feet longer than the Egyptian transport El Quesir, it could easily be mistaken for the latter vessel by an overzealous pilot. Both ships have similar hulls and arrangements of masts and stack.

6. The weather was clear in the area of attack, the Liberty's hull number (GTR 5) was prominently displayed, and an American flag was flying.

7. Thus it was not until 4:12 p.m. (9:12 a.m.) that the Israelis became convinced that the Liberty

was American. This was about 44 minutes after the last attack on the ship and the attack had apparently been called off, not because the ship had been identified, but because it seemed to be sinking. (The US Defense Attaché in Tel Aviv reports that Israeli helicopters and the three torpedo boats searched the area until 6:04 p.m. (11:04 a.m.)). The Israeli offer of assistance was declined because of the sensitive mission of the ship. According to US Navy reports, the ship was saved only through the efforts of her crew.

#### Damage and Personnel Losses

8. The ship suffered heavy material and personnel casualties. A hole estimated to be 39 feet wide at the bottom and 24 feet wide at the top near the waterline was opened by a torpedo. The ship is flooded below the second deck between frames 52 and 78 (36-inch frame spacing). The crew carried out emergency destruction of classified communications and radar equipment, but the ship's engineering plant is intact. Several flash fires and cannon holes throughout the superstructure caused some minor damage, and the ship's motor whale boat and



virtually all of its life rafts were lost. Personnel casualties include 10 killed, 90 wounded, and 22 missing, most of whom were probably trapped in the flooded compartments. The wounded and the dead have been removed from the ship and some additional crew members put aboard. The ship is expected to arrive in Malta on 14 June for dry docking and hull repairs. Security precautions are being taken to protect the classified intercept equipment in the flooded spaces. The US Navy has convened a board of inquiry to look into the incident.

The Ship and Its Orders

9. The USS Liberty is/

an electronics research ship which had been diverted to the crisis area to act as a radio relay station for US embassies.

10. The Liberty sailed from Rota, Spain, on 2 June under orders to patrol no closer than 12.5 miles of the UAR coast and 6.5 miles of the Israeli coast. A modification of orders issued by the Commander of the US Sixth Fleet at 12:17 p.m. (5:17 a.m.) on 8 June had not been received aboard the Liberty, according to the ship's commanding officer, before the Israeli attack. This change, together with messages from other commands which ordered the Liberty to approach no closer than 100 miles of the coasts of the UAR and Israel and 25 miles of the coast of Cyprus, was delayed in transmission in part because of a misunderstanding of responsibilities for delivery.

11. At annex is a listing of events in chronological order.

CHRONOLOGY OF EVENTS

(Stated times are local; Washington times in parentheses)

2 June 1967

Liberty departed Rota, Spain en route to position 32-00N, 33-00E, to remain 12.5 miles from Egyptian coast and 6.5 miles from Israeli coast.

8 June 2:50 a.m.  
(7 June 7:50 p.m.)

CINCUSNAVEUR Duty Officer received phone instructions from Joint Reconnaissance Center directing Liberty to comply with COMSIXTHFLEET 100-mile operating area restriction.

8 June 9:50 a.m.  
(2:50 a.m.)

Liberty was orbited by two unidentified delta wing single engine jet fighters, presumably Israeli Mirages.

8 June 12:17 p.m.  
(5:17 a.m.)

COMSIXTHFLEET orders Liberty at least 100 miles away from coast of UAR and Israel and 25 miles from Cyprus. This message apparently not received by Liberty prior to Israeli attack.

8 June 3:05 p.m.  
(8:05 a.m.)

Liberty attacked by unidentified jet fighters which made six strafing runs. Ship at position 31-35.5N 33-29.0E (25 miles north-east of nearest land).

8 June 3:25 p.m.  
(8:25 a.m.)

Three torpedo boats, one identified as Israeli, approach ship. One boat bore number 206-T.

8 June 3:27 p.m.  
(8:27 a.m.)

Liberty fires at torpedo boat at range of 2,000 yards.

8 June 3:28 p.m.  
(8:28 a.m.)

Ship hit by torpedo. Torpedo boats cleared to east about five miles.

8 June 3:30 p.m.  
(8:30 a.m.)

COMSIXTHFLEET reports Liberty hit by torpedo at position 31-23N, 33-25E. Three unidentified gunboats approaching.

8 June 3:50 p.m.  
(8:50 a.m.)

8 June 3:52 p.m.  
(8:52 a.m.)

8 June 3:55 p.m.  
(8:55 a.m.)

8 June 3:55 p.m.  
(8:55 a.m.)

8 June 3:59 p.m.  
(8:59 a.m.)

COMSIXTHFLEET orders carriers to provide  
air cover for Liberty.

Liberty reported under attack to  
COMSIXTHFLEET

Liberty reported hit by torpedo star-  
board side/

Two Israeli helicopters orbited ship at  
range of 500 yards. Israeli torpedo  
boats offered assistance which was re-  
fused.

Liberty still under air attack |

8 June 5:14 p.m.  
(10:14 a.m.)

Tel Aviv reports Israeli aircraft and patrol boats attacked ship at 3:00 p.m. (8:00 a.m.) at position 31-25N, 33-33E. Suspecting a US ship, Israel rendering assistance and expresses deep regret.

8 June 6:04 p.m.  
(11:04 a.m.)

The US Defense Attache in Tel Aviv reports that Israeli helicopters and the three torpedo boats searched the area until 6:04 p.m. (11:04 a.m.). The Israeli offer of assistance was declined because of the sensitive mission of the ship.

COMSIXTHFLEET then recalled the aircraft launched from the carriers America and Saratoga and sent two destroyers to assist Liberty. Liberty proceeding northwest at eight knots.

There was no further contact between Liberty and Israeli forces. Two Soviet ships have trailed the Liberty, which proceeds under escort to Malta.

