

ATTACHMENT C

- A. The GSA Contractor has failed to remove [redacted] residue as needed. There are presently 10,000 lb's of waste backup and the problem has existed for the past 90 days. This creates a extreme fire hazard. See Memo 21 Aug 80, Chief of Supply, NPIC.
- B. Perimeter fence is in disrepair in numerous areas. In some areas persons enter compound through large holes and bypass FPO control points.
- C. [redacted] gate inoperative due to faulty motor for 5 weeks. Gate cannot be closed in accordance with standard operating procedures.
- D. There has been a fire alarm survey every two months and a fire drill on July 1980 revealed significant defects which have not been repaired.
- E. For 5 months there have been two (2) skylights broken over the loading dock. Rain damages is causing safety problems at the loading dock area.

STAT

STATINTL