

ROUTING

DATE 0945Z 08 OCT 63

TOP SECRET

| | |
|---|---|
| 1 | 4 |
| 2 | 5 |
| 3 | 6 |

TO : DIRECTOR
 FROM : [REDACTED] 25X1A
 ACTION: OSA 1-20
 INFO :

FLASH

IN 94525

25X1A TOR: 1004Z 08 OCT 63

25X1A

TO FLASH [REDACTED] INFO IMMEDIATE [REDACTED] CITE [REDACTED] 0142

25X1A

25X1A [REDACTED] THREE

25X1A

1. THE [REDACTED] 3 SHUTTER MALFUNCTIONED ON MSN 3229 APPROX 4 MIN BEYOND POINT F CAUSING THE CIRCUIT BREAKER TO POP. [REDACTED]

25X1A

3 HAD BEEN CYCLED TWICE ENROUTE TO AREA OF INTEREST AND INDICATIONS TO PILOT SHOWED 4 MIN SUCCESSFUL OPERATION WHEN MALFUNCTION WAS OBSERVED. PILOT TURNED AROUND AT POINT G AFTER EFFORTS TO CLEAR THE PROBLEM HAD PROVEN UNSUCCESSFUL.

2. PILOT REPORTED WX IN THE AREA OF INTEREST AS COMPLETELY CLEAR FOR SEVERAL HUNDRED MILES.

25X1A

3. [REDACTED] CAN BE READY TO FLY SAME PLANNED ROUTE ON 9 OCT IF HQ WOULD LIKE TO TAKE ADVANTAGE OF GOOD WX AND PROVIDED [REDACTED] AND [REDACTED] CAN ACCOMPLISH NECESSARY COORDINATION.

25X1A

25X1A

END OF MESSAGE

TOP SECRET

GROUP 1
 Excluded from automatic
 downgrading and
 declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.

4