

0613Z 27 DEC 1962

SECRET

OPERATIONAL IMMEDIATE

DIRECTOR

25X1A

[REDACTED]

OPS (1-2-3-4-5)

S/C (6)⁰³

TOR: 0626Z 27 DEC 1962

OPERATIONAL IMMEDIATE

IN-60429

[REDACTED]

INFO

CONF

[REDACTED] 964

25X1A

25X1A

1963 (IN 60421)

REWIRING OF SYSTEM XII COMPLETED. SYSTEM CHECKED OUT SATISFACTORILY DURING FULL POWER TEST ON GROUND EXCEPT WHEN OPERATING ON ALTERNATOR. WHEN OPERATING ON ALTERNATOR, SAME PHENOMENON AS REPORTED IN REF OCCURED, INDICATING THAT ALTERNATOR CURRENTLY INSTALLED IS CREATING THE DISTURBANCE.

END OF MESSAGE

SECRET