

RECORDS SHELF LIST			JOB NO. <b>75-B-114</b>
NOTE: Prepare in Triplicate and submit original and one to Records Center			TOTAL NO. OF CONTAINERS 1 <i>QFS</i>
OFFICE	DIVISION	BRANCH	SECTION
DD/S&T	OSA	Materiel	Maintenance
CONTAINER NO.	DESCRIPTION AND DATES		
1	<p>Folder "AEC Sensor" containing cable messages.</p> <p>Folder "RRB Folder IRIS II Multiple Fixed slit, Task #157" and also "ECP-017, S/B 351-549" containing cable messages and Engineering Change Proposal No. IT-PA-017.</p> <p>Folder "V/H Sensor Eval Task 156, IRIS II" containing cables and BIF-059-30126-71</p> <p>Folder "IRIS II, ECP 005, S/B 31, V/H Sensor Mod" containing cables and service bulletin</p> <p>Folder "ECP 006 Capacitor, Shuttle Cable/IRIS II (Closed 4-5 May 71), containing cables and Engineering Change Proposal No. IT-PA-006</p> <p>Folder "ECP-82, Window Defrost System, IRIS II, Fore-Aft Photography, ECP 014" containing cables, BIF-059-30018-72 and Service Bulletin</p> <p>Folder "S/B 544, Additional Suit Cooling" containing cables and Service Bulletin</p> <p>Folder "Visor Face Heat, Rheostat/Fuse" containing Service Bulletin 351-465 and IDEA-0005-71</p> <p>Engineering Report, Comparison of Vehicle Motion Flights 1,2,3, and 4, TP6561, Copy 1</p> <p>* Folder "Special Test Flights, 1,2,3,4, IRIS Motion/Mount containing cables, OSA-70-1318, BYE-3039/70, TSG/APSD/IEB-131/70, BYE-3038/70, BYE-12342-70,</p> <p>Folder "Long Range Pinger, 3MR-1-11" containing cables, evaluations, Dual Frequency Pinger Final Report</p> <p>Memo for Record, Subj: Analysis of Consolidated Camera Support Proposals, w/BIF-059-31091-72, Consolidation of Support Services Activities for I Program; BIF-059-31092-72, Consolidation of Support Services Activities for I Program; ACTRON Experience and Capabilities; BIF-005-035-72, Consolidated Budgetary Forecast for Supplies and Service; BIF-007W/P-0007-72</p> <p>Folder "Preconditioning Cart Q-Bay Temps., Field Test Date" containing BIF-005-069-71, BIF-059-30138-71, cables</p> <p>Folder "Preconditioning Cart" containing SP-1715 U-2R, Q-Bay Pre-conditioning Unit Qualification Test cp #1; IDEA-0205-70 cp 1; TP6557 Technical Report; Operation, Maintenance and Service Instructions; Air Conditioning, Refrigeration, Engineering, Manufacturing; HF011 Technical Proposal Preconditioning System Mdl HGS-540; graphs</p> <p>Folder, "3MR-9-4-1 White Cliffs" containing cables, BYE-9190-69, BYE-8997-69, IDEA-1037-69, BYE-8996-69</p> <p>Folder "3MS-1 Support Acft General" containing cables, BYE-8652-70, C-118 Enroute Kit.</p> <p><del>Folder "U-3A 57-5865, U-3A" containing cables</del> <i>RS</i></p> <p><del>Folder "U-3A 57-5859, 3MS-1-2" containing cables</del> <i>RS</i></p> <p>Folder "U-3E 60-6080" containing cables, OSA-0797-70</p>		

RECORDS SHELF LIST			JOB NO.
NOTE: Prepare in Triplicate and submit original and one to Records Center			TOTAL NO. OF CONTAINERS
OFFICE	DIVISION	BRANCH	SECTION
DD/S&T/OSA	Materiel	Matenance	1
CONTAINER NO.	DESCRIPTION AND DATES		
	<p>Folder "<del>Cessna 210/SN 2105B408</del>" containing cables and forms <del>10</del>  <del>Major Repair and Alteration</del>                      Folder "C-130 58-0715" containing cables, OXC 0568-68                      Folder "UH-1F 65-7965" containing cables                      Folder "Chopper" containing cables, OSA-1590-69                      Folder "U-3B 60-6047 containing cables  <del>Folder "56-3513 T-37B 56-3563" containing cables, BYE-9158-72</del> <del>11</del>  <del>Folder "Q-2, S/N 68-6862, Q-2 S/N 68-6867" containing cables,</del> <del>16</del>                      BYE-9161-72                      Folder "3MR-9-15, Preconditioning Unit" containing cables,                      IDEA-0022-70 cp 5; IDEA-0023-70, cp 5; OSA-2765-70, cp 4.                      Technical Memo, BYE-6922-70.                      Folder "COMPASS TRIP IV, &amp; Tamper Upstreet" containing cables,                      ORD 1647/73, TCS 35953/73, ORD 746/73 also additional folder                      entitled " Multispectral Task"                      Folder "COMPASS TRIP III 1973" containing cables                      Folder "COMPASS TRIP 1972" containing cables, BYE-9312-72,                      IDEA-0013-72, <del>ORD 4891-72</del>                      Picture North Base Oct 68, Iris I Camera K+20 10x                      Picture Type II Atf1261 29 Sept 65, Altitude 80,400 M3.16 Area 51                      *TP6556 Engineering Report Comparison of Vehicle Motion                      1 July 1970 and Briefing paper</p>		

*Page 2*

RECORDS SHELF LIST			JOB NO. 75-B-114
NOTE: Prepare in Triplicate and submit original and one to Records Center			TOTAL NO. OF CONTAINERS 2055
OFFICE	DIVISION	BRANCH	SECTION
DD/S&T/OSA	Materiel	Maintenance	
CONTAINER NO.	DESCRIPTION AND DATES		
2	<p>1 Package blueprints H-2  1 Package blueprints B-3  BIF-005-065-71, Test Data from Recent Flights  BIF-005-076-71, Test data from ground &amp; flight tests  BIF-005-088-71, Test data from flights  TP6510-C Summary Report Flight Data Instrumentation Program  15 Oct 1971  TP6510-B Summary Report Flight Data Instrumentation Program  15 Sept 1970  TP6510-A Summary Report Flight Data Instrumentation Program  1 Mar 1970  TP6510 Summary Report Flight Data Instrumentation Program  1 Sept 1969  Collins Instruction Book 718U-7 Lightweight HF Communications System  Collins Instruction Book 514A-3/4/5 Radio Set Control  Collins Instruction Book 548S-3/5/6 Power Amplifier Coupler and 641D-1 Variable Capacitor  Collins Instruction Book 671U-4/4A/4B Receiver-Exciter  Collins 718U-7 HF Communication System  Collins 718U-7 Program Status  718U-7 Implementation Plan and Equipment Specifications  Proposed Retrofit of 718T-6/490R-6/309C-6 HF SSB Radio Equipment  Proposal for 718T-6/490R-6 Replacement, Collins Radio Co.  Collins Radio Co. Equipment Spec for 172H-16 Dummy Antenna, Shunt P/N 792-6608-001</p>		

RECORDS SHELF LIST			JOB NO. 75-B-114
NOTE: Prepare in Triplicate and submit original and one to Records Center			TOTAL NO. OF CONTAINERS 3055
OFFICE	DIVISION	BRANCH	SECTION
DD/SGT/OSA	Materiel	Maintenance	
CONTAINER NO.	DESCRIPTION AND DATES		
3	<p>Folder "AGE 3MR-2-9"</p> <p>Folder "3MR-4-7 IR Supp." containing cables, BYE-12810-70, Series B cy 1, BYE-9052-70, BYE-8953-70, BYE-2973/68, BYE-9214/68, BYE-11199/68 including folder "Reduction of Thermal Infra-red Radiation from IDEALIST Aircraft" and Intelligence Report TCS-1965/68 cy 53 and Vu-graphs, and Signature Reduction Feasibility Study Final Report July 1968</p> <p>Folder "3MR-4-7 (Part II) IR Supp" including IR Presentation 5-11-71 by Pratt &amp; Whitney Aircraft, Countermeasure Feasibility study First Quarterly Report 1 Jul 70, Countermeasure Feasibility Study Second Quarterly Report 1 Oct 70, OSA 9706-71, OSA-1742-71, and cables.</p> <p>Folder "3MR-9-8 IRIS II Camera" containing IDEA-1061-69, IDEA-0663-69, IDEA-0662-69, IDEA-0507-69, IDEA-0515-69, IDEA-0504-69, IDEA-0323-69, IDEA-0366-69, IDEA-0318-69, IDEA-0218-69, IDEA-0214-69, IDEA-0180-69, IDEA-0183-69, IDEA-0182-69, IDEA-0146-69, IDEA-0103-69, IDEA-0856-68, BYE-9178-68, IDEA-0660-68, BYE-9027-68, BYE-9020-68, BYE-12968-68, BYE-8978-68, BYE-8671-68</p> <p>Folder "3MR-9-8 IRIS II Camera 1970 &amp; 1971" containing cables, blueprint, BYE-9070-71, BIF-059-30017-70, BYE-8670-70</p> <p>Folder "3MR-9-8 IRIS II" containing cables</p> <p>Folder "3MR-9-8-1 Msgs IRIS II Service Bulletins"</p> <p>Folder "3MR-9-8-1 TO #34 IRIS II Service Bulletins"</p> <p>Folder "Critical Assets Reports ACTRON 3MR-9-12"</p> <p>Folder "ITEK Management Report 3MR-9-12"</p> <p>Folder "3MR-9-14 FOI" containing BYE-7290-68, BIF-005-059-73, High Oblique Sensor Briefing, House Pictures, BYE-9170-9-73</p> <p>Booklet "Equipment Specifications for HMS-564X Multispectral Scanner by Actron"</p> <p>Technical Proposal Vol I 21 Apr 67 Data Annotation System Model HG-474A, Lycon</p> <p><del>HR 333-2 Mission Planning and Photo Interpretation Aerial Reconnaissance Camera Model HR 3-3</del></p> <p>Operation and Maintenance Instructions</p> <p>Vu-graphs</p> <p>Aircraft pictures</p> <p>Folder "3MR9-4 Baker Camera" containing cables, BYE-10939-71, IDEA-0021-70</p> <p>Major Ground Accident B-3 Configuration S/N 230</p> <p>Internal Motion Study (Environmental) Light Weight Model B2 Camera System</p> <p><del>HR 088-1 Technical manual Maintenance Aerial Reconnaissance Camera Model HR 333</del></p>		

RECORDS SHELF LIST			JOB NO. <b>75-B-114</b>
NOTE: Prepare in Triplicate and submit original and one to Records Center			TOTAL NO. OF CONTAINERS <b>405</b>
OFFICE	DIVISION	BRANCH	SECTION
DD/S&T/OSA	Materiel	Maintenance	
CONTAINER NO.	DESCRIPTION AND DATES		
<b>4</b>	<p>Folder "3MR-9-6-1 2nd APO Lens" containing cables, BYE-7747-73, TCS-36146-72, BYE-9183-12-72, BYE-111326-72, Specifications, Δ -III Modifications</p> <p>Folder "3MR-9-6-1-a APO Lens #1 Delta III-2" containing cables BYE-9091-71, BYE-9253-71, BYE-9252-71, BYE-8964-70</p> <p>BIF-059-31140-72 BIF-059-31008-73 BYE-6703-74 cy 1 w/BIF-059W-30005-74 BIF-059-31101-71 BIF-059-32033-70 BIF-059-32030-70</p> <p>Delta III-2 Master Instrument APO Panitek 001, Final Acceptance Data</p> <p>BIF-059-31124-72, Flight Evaluation of Apochromatic f/3.5 (APO-Panitek) Lens with SO-242 Color film</p> <p>BIF-059-31039-72, Evaluation of Apochromatic f/3.5 Lens (APO-Panitek)</p> <p>Folder "3MR-9-9 Hatches &amp; Windows" containing cables, IDEA-0503-69</p> <p>Folder "3MR-9-11 Film" containing cables, IDEA-0167-71</p> <p>Folder "3MR-9-6 Delta III" containing cables, IDEA-0792-69, IDEA-0320-68, BYE-9020-68, IDEA-0305-69, IDEA-0257-69, IDEA-0201-69, IDEA-0252-69, IDEA-0784-68, IDEA-0783-68</p> <p>Folder "3MR-9-3 Tracker T-35" including cables</p> <p>Folder "Delta III (Revision) 3MR-9-6" containing BYE-9091-71</p> <p>KS-72 Aerial Reconnaissance Camera System</p> <p>TCS-84685-67, cy 36 [redacted]</p> <p>TCS-20292/70, cy 90 [redacted]</p> <p>TCS-22571/70, cy 97 [redacted]</p> <p>TCS-84635/67, cy 36 The KH-4A Camera System</p> <p>TCS-84684/67, cy 36 The KH-4B Camera System</p> <p>TCS-7893/64, cy 91 The 115A Camera System Nov 1964</p> <p>TCS-84737/66, cy 69 The 118-A Camera System Dec 1966</p> <p>TCS-84910/65, cy 89 The 116-A Camera System Sept 1965</p> <p>Perkin-Elmer Optical Group Engineering Report No. 9382, Proposal for the Development and Test of a Novel Light-weight Refractive Lens</p> <p>BYE-2922-66, cy #2, Sensor Systems for a CIA/SR-71 System</p> <p>BYE-2768-67, Subj: U-2R Development Status and Technical Meeting, 9 Nov 67</p> <p>IDEA-0690-67, Lockheed Aircraft Corp Report SP-1274</p> <p>OSA-0053-2-74, Lockheed Aircraft Corp Report No. SP-4114 Standard Operating Procedures Detachment H</p> <p>IDEA-0030-71, Report of Safety Survey [redacted] 25 May 71</p> <p>ATTG Regs</p>		

25X1

25X1

RECORDS SHELF LIST			JOB NO. 75-B-114
NOTE: Prepare in Triplicate and submit original and one to Records Center			TOTAL NO. OF CONTAINERS 4055
OFFICE	DIVISION	BRANCH	SECTION
DD/S&T/OSA	Materiel	Maintenance	
CONTAINER NO.	DESCRIPTION AND DATES		
4	Pictures Safety Survey, 3MR1-6 Pictures 1st "R" 3MR-1 8-MR-4-3, Aircraft Design Proposal Considerations SP-979 3-MR-2-7-5&6, containing IDEA-0205-67, cables, pictures, IDEA-0190-70, IDEA-0159-70, IDEA-0245-69, IDEA-0123-69, Comparison of RQ1020 Converter System (Navy(-10) Configuration) and Proposed (-11) System 3MR-1-2, U-2R WRSP-IV Flight Test Acceptance Schedule (Provisional) NYE-2606-66, Performance Evaluation of the U-2R Model Airplane Folder "3MR-3-3-1 Loran System", containing cables, maps Folder "3MR-16 Blue Gull" containing IBBA 0858-69, IDEA-0847-69, IDEA-0443-69, cables, BLUE GULL Handbook, IDEA-1044-69		

RECORDS SHELF LIST			JOB NO. 75-B-114
NOTE: Prepare in Triplicate and submit original and one to Records Center			TOTAL NO. OF CONTAINERS 5 OF 5
OFFICE	DIVISION	BRANCH	SECTION
DD/S&T/OSA	Materiel	Avionics	
CONTAINER NO.	DESCRIPTION AND DATES		
5	<p>Folder "4ML [redacted] (Study)" containing TCS 3216/74 cp #8, TCS 3216/74 cp #10, BYE-111082/74A, BYE 111082/72 cp 6 (Working paper), STAT</p> <p>Folder "4M-L/S [redacted] Cables 1974 STAT</p> <p>Folder "4M-L/S [redacted] Cables 1973</p> <p>Folder "4M-L/S [redacted] Cables 1971-1972"</p> <p>Folder "4M-L/S [redacted] 1973"</p> <p>Folder "4M-L/S [redacted] 1973" containing BYE-11094-73, BYE-1167/73 w/att, IDEA-0128-73, IDEA-0219-11-73,</p> <p>Folder "4M-L Long Shaft 1972, 73, 74" containing BYE-9162-6-73, BYE-9177-72, BYE-9092-71, BYE-11239/71, BYE-11228/71, BYE-10859/71, BYE-11090/71, <del>BYE-10983-71</del> BYE-10983-71, BYE-10957-71, BYE-10923-71, BYE-9304/71, BYE-11108/70</p> <p>Proposal for Project [redacted] REFURBISHMENT REPORT STAT</p> <p>[redacted] - Vol II STAT</p> <p>[redacted] Manual, Vol I: Technical Manual and Wire Lists Refurbishment Report, Jan 1972 STAT</p> <p>[redacted] (A high sensitivity system designed to receive narrow-beam microwave links) BYE-9384/73 STAT</p> <p>Schematic Diagrams</p> <p>[redacted] Sweep Modification Manual 6 Aug 71 STAT</p> <p>Folder [redacted] containing IDEA-0128-73, BYE-10942/70, STAT</p> <p>disc cables, maps, etc.</p> <p>1 package photographs pertaining to [redacted] STAT</p> <p>1 package [redacted] overlays STAT</p> <p>Folder "4M-LP Lead Pipe Cables" and "4M-LP Lead Pipe" IDEA-0252-72 cy 2, RX 474 Antenna for use with the "Lead Pipe" System</p> <p>Folder "Lead Pipe" containing TCS 34931/72 Series B</p> <p>Folder "4M-MG Mercury Glass Cables"</p> <p>Folder "4M-OH Old Head Cables"</p> <p>Folder "4M-OH Old Head (Glass Lamp)" containing BYE-9049-69, BYE-11318/69</p> <p>Folder "4M-OH Old Head Cables"</p> <p>Folder "Scope Seal" Cables</p> <p>Folder "Mission S-014-E"</p> <p>Folder "Mission SO-33-E" "S-033E"</p> <p>Folder "Scope Shield" containing BYE-2965/73, BYE-10950/73</p>		