Sanitized Approved For Release GARDB33-02415A000500180004-2

					,	PERIOD	COVERE	5
PROJECT PROGRESS REPORT					PROM		THRU	
					13 Nov 5	59	19 No	♥ 59
1. REPORTING ABENC	Y		* NAME OF CONT	ACT	relitific relitiri. Imani, crimi di ancazione di residi	3.	TELEPH	NNF VO.
LAC						İ		
4. PROGRAM TITLE		entres that a section of section of section of the	- Militaria communication - August again					
		m 1832	25X1 <i>A</i>	.5a1				
Auto	pilot Program	n A						
And the second s		STA	TUS OF PROGRAM	BOTO - TAIR - O'C. BARRIES AND MARKET THE AND ASSESSMENT ASSESSMEN	ation of American property of the property of	e namen de	to the test which will	
	OGR AM	6.	TESTING					
7. OBJECTIVE OF TE	ACTIVE	PLANNING	ASTIVE	8087	ENDED		CANCEL	FAL
	rove A/P ins	tallation to ob-	tain more consist	ent oper	ation.			
	P. Date PROGRES	AM INITIATED	tain more consist		ation.		IMATED	ቸኮች™ <b>២</b> ዕለ
Imp	B. Date PROGRA	AM INITIATED 1959			11. DATE		IMATED	†የቁ፣ <b>ይ</b> ዕለ
8. PRIORITY	9. pate Program	AM INITIATED 1959	10. DATE TESTING INIT	ATED RUNS	11. DATE PLETI	ON OTAL H	OURS ON	
S. PRIORITY	9. pate Program	AM INITIATED 1959	TO. DATE TESTING INIT	ATED RUNS	11. DATE PLETI	ON OTAL H	ours or	
S. PRIORITY	9. pate Program	AM INITIATED 1959	TO. DATE TESTING INIT	ATED RUNS	11. DATE PLETI	ON OTAL H	ours or	
S. PRIORITY	9. pate Program	AM INITIATED 1959	TO. DATE TESTING INIT	ATED RUNS	11. DATE PLETI	ON OTAL H	ours or	
S. PRIORITY	9. pate Program	AM INITIATED 1959	TO. DATE TESTING INIT	ATED RUNS	11. DATE PLETI	ON OTAL H	ours or	

Three flights were made on U=2A's with the pitch and roll rate knobs in the cockpit. These two knobs appear to improve the pilots control of the U=2A. If subsequent flying shows that two knobs are adequate an ECP will be issued proposing their installation in FOG U=2A's

C. 2341