

50X1

CLASSIFIED MESSAGE

DATE : [] 1 MAR 57

S-E-C-R-E-T

ROUTING	
1	A/M [] 4
2	[] 5
3	[] 6

TO : DIRECTOR

MAR 1 10 01Z 57

50X1

FROM :

ACTION:

INFO :

[]

PRIORITY
PRECEDENCE

50X1

TO (PRIORITY) [] DIR

CITE

[]

NO NIGHT ACTION

RE A

[]

B FCT 4863

50X1

A. EAGLE 44

50X1

B. B 17

50X1

C. 2⁸ FEB 57 / Mar

D. 4,483 POUNDS 7,303,350 LEAFLETS.

E.

TO	HSINCHU /	1300	2100	OCST	1
TP	2335-11935 /	5	1333	2133 IFR /	0
CIP	2350-11737 /	15	1407	2307 HI OCST LO BKN	2
TP	2411-11713 /	60	1432	2332 IFR /	0
TP	2418-11646 /	60	1458	2358 IFR /	0
TP	2405-11537 /	65	1511	0011 IFR /	0
TP	2427-11455 /	60	1528	0078 HO OSCT LO BKN /	2
TP	2510-11500 /	65	1544	0044 IFR /	0
TP	2508-11418 /	70	1605	0105 IFR /	0

1 MAR 57 K

S-E-C-R-E-T

IT IS FORBIDDEN TO MAKE A COPY OF THIS MESSAGE

Copy No.

CLASSIFIED MESSAGE

DATE :

S-E-C-R-E-T

ROUTING

1		4	
2		5	
3		6	

TO :

FROM :

ACTION:

INFO :

PAGE 2



50X1

							PRECEDENCE
TP	2533-11341 ✓	80	1615	0115	IFR ✓		0
TP	2625-11251 ✓	80	1645	0145	IFR ✓		0
TP	2700-11320 ✓	70	1659	0159	IFR ✓		0
TP	2647-11453 ✓	71	1727	0227	IFR ✓		0
TP	2620-11430 ✓	71	1738	0238	IFR ✓		0
TP	2540-11444 ✓	70	1750	0250	IFR ✓		0
TP	2558-11524 ✓	71	1753	0253	IFR ✓		0
TP	2538-11620 ✓	72	1810	0310	IFR ✓		0
TP	2621-11711 ✓	75	1832	0332	TURBULENT IFR ✓		0
TP	2617-11737 ✓	74	1839	0339	BKN LO OCST ✓		0
TP	2611-11811 ✓	75	1848	0348	SC LO OCST ✓		0
TP	2637-11847 ✓	72	1901	0401	IFR ✓		0
TP	2552-11855 ✓	72	1913	0413	IFR ✓		0
TP	2522-11841 ✓	71	1925	0425	IFR ✓		0
OP	2508-11909 ✓	40	1930	0430	IFR ✓		0
TP	2430-12000 ✓	5	1955	0455	HI OCST RAIN ✓		0
LAND	HSINCHU ✓		2028	0528	HI OCST RAIN ✓		1

F. LORAN, RADIO ALT. 4HF TRANS.

S-E-C-R-E-T

IT IS FORBIDDEN TO MAKE A COPY OF THIS MESSAGE

CLASSIFIED MESSAGE

DATE :	S-E-C-R-E-T	ROUTING	
		1	4
		2	5
		3	6

TO :

FROM :

ACTION:

INFO :

PAGE 3

50X1

50X1

PRECEDENCE

G. NO VISUAL OBSERVATIONS. NO AAA.

[Redacted]

[Redacted]

LORAN INOPERATIVE PRIOR CIP. ACFT CMDR DECIDED TO COAST IN AND DROP LEAFLETS OVER MAINLAND. LORAN FIXED AT APPROXIMATELY POINT 3. LEAFLETS DROPPED 17 BOXES AT 2 MINUTE INTERVALS AFTER CIP. LORAN OUT AGAIN FROM POINT 1 (PORTION GARBLED - BEING SERVICED) REPAIRED IN FLIGHT. LEAFLETS DROPPED POINT 10, 11, 12, 13, 14, 15, AND 17. FLUXGATE VARIED WITH MAGNETIC COMPASS FROM 2 TO 10 DEGREES. PILOT FLEW ENTIRE ROUTE ON MAGNETIC HEADING.

50X1

END OF MESSAGE

S-E-C-R-E-T

IT IS FORBIDDEN TO MAKE A COPY OF THIS MESSAGE