

IDEA-0643-68
Copy 9 of 9

13 September 1968

MEMORANDUM FOR: Deputy for Operations, OSA

SUBJECT: "H" Camera Disposition

REFERENCE: 8845 dated 12 September 1968

1. Reference message states that Customer 2 does not have a requirement for the "H" configuration now located at McCoy AFB.

2. It is recommended that this camera be transferred to Detachment G where it will be used to establish compatibility with U-2R and be available as an operationally ready back-up for S/N 001 and 002 currently at Detachment G and H, respectively. It is further recommended Hycon ECP 008 Heater Blanket revision for the "H" camera be authorized for S/N 001 and 003 to improve camera performance. This improvement has already been incorporated in S/N 002 at Detachment H. No additional funds are required.

SSD/R&D/OSA/

SSD/R&D/OSA/
Distribution.

- Cy 1 - D/O/OSA
- 2 - IDEA/O/OSA
- 3 - D/M/OSA
- 4 - INTEL/O/OSA
- 5 - DD/SA
- 6 - D/R&D/OSA
- 7 - SSD/R&D/OSA
- 8 - SSD/R&D Chrono
- 9 - RB/OSA

GROUP 1
Excluded from automatic
downgrading and
declassification

IDEALIST
SECRET