# Approved For Release 2000/08/27-16-A-RDP78-02820A000400040051-7

#### Information on Recommended Equipment

1. The following information and attachments should be used for a survey report formulated by 25X1A2d3

#### 2. Teletype Equipment

- a. The equipment shown in the brochure will provide radioteletype and single-sideband radiotelephone.
- the photographs are: (1) a complete field station;
   (2) headquarters receiving equipment for 4 circuits;
   (3) a headquarters transmitter (4 each for entire requirement).
- List prices of the individual items of equipment follow:

PAL-350 \$ 1150 SBE-2 1764 CFA 530 FFR-2 530 MSR-4 530 GFR-90 515 KFK 818 FFR-DFH 86 PSP-1 130 TIS 568 AMC-6 582 GPT-750(c) 4702 TAC-1 562 patch panel 140 tuning unit 110 cabinet equipment rack 350	(Power Amplifier, Linear) (Made Selector, Transmitting) (Frequency Shift Converter) (Communications Receiver) (Made Selector, Receiving) (Communications Receiver) (Frequency Shift Keyer) (Tuning Drawer Rack) (Power Supply (Tone Intelligence System) (Antenna Multicoupler) (Radio Transmitter) (Antenna Tuning Unit)
---	---

d. Availability - approximately 5 months

25X1A5a1

e. The can furnish technician for installation. Cost - vicinity of \$1500 per month.

25X1A5a1

- f. can also procure the Model 19 Teletypewriter Printers. Cost \$2400.
- 3. Telephone Answering and Recording Device
  - a. The attached brochure describes a recommended unit.

## Approved For Release 2000/08/27 2014 PDP78-02820A000400040051-7

### Information on Recommended Equipment (Con't)

### 4. <u>Direction-finding Equipment</u>

- a. The attached brochures describe two types of equipment that can be adopted to mobile use.
- b. Cost: DFM-2 approximately \$6400 Telegon III/s - no price quoted
- c. Availability: DFM-2 60 days Telegon III/s - not quoted

25X1A6a NOTE: A 40 per cent customs duty will be required on equipment sent