Approved For Release 2000/05/17 CHAIR TO CORRECT NATIONALS

The Files - Contract RD-103, Task Order 12

30 December 1958

25X1A9a

Trip Report - RS-16 Antenna Tuners

25X1A9a

to the monitor progress on Contract RD-103, Task Order 12, the development 25X1A5a1 and fabrication of 16 antenna tuners.

2. Work has been slowed down on the RS-16 antenna tuner in order for the contractor to devote more effort to the rework of the RS-16A/AS-4 equipment and to complete the AS-6 development. A decision is to be made whether to cut off the tuner development in the light of the RS-18 tuner and other existing tuners.

25X1A9a

OC-E/R&D-EP/PCV:wlj (30 December 1958)
cc: R&D Subject File
 Menthly Report (2)
 R&D Lab
 R&D Chrono
 EP Chrono