



SUBJECT: RR-44 Receiver with [REDACTED]

25X1A5a1

The contractor has been made aware of these problems and will correct them before starting fabrication of the remaining 95 units.

[REDACTED] 25X1A9a

**Distribution:**

R&D Subject File  
Inspection Branch/PD/OL  
R&D Lab  
OC-OS  
ESB  
Monthly (2)  
EP Chrono