Approved For Release 2008/01/30: CIA-RDP78B04558A000700100018-5

CIA-2 SECRET

OUT-51499 FM CIA WASHDC TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB RUEAHQ/DIAXX RUECYG/NAVY PIC RUWGAA/HQS 2ND AF BARKSDALE, LA RUWGSM/4080TH STRAT WG, OL 19, BARKSDALE, LA DA GRNC BT SECRET FOR DI, BRASS KNOB, DOCR, DM 4, DIM, SAC HQS,

	15
1963	17 JUL 1963
JIII 8	HFS 4
. 17	cJS
16	CEO
0	BHS
ဝိ	A.G.Ti

FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER. OMAHA.

- CAMERA B 11 WAS USED IN MISSION 3660 FLOWN ON 11 JULY 1963; Grace (File) 1. PROCESSING WAS ACCOMPLISHED BY NAVY PIC.
 - 2. ORIGINAL NEGATIVE:

Declassification Review by NGA/DoD

- THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.
- 9R SIDE: THE VERTICAL POSITION INDICATOR LAMP DOES NOT В. FUNCTION AFTER FRAME 0025. THERE ARE 2 CIRCULAR PLUS DENSITY AREAS, 0.75" IN DIAMETER, ALONG THE INBOARD EDGE IN FRAMES 2512, 2514, 2517, 2522, 2525, 2528, 2530, 2533, 2536, AND 2538.
- C. 9L SIDE: THERE IS A TEAR, ASSOCIATED WITH A HEAT SPLICE, IN FRAME 285 FROM EDGE TO EDGE. THERE IS ANOTHER SMALL TEAR AND MINOR INBOARD EDGE CRIMPING IN FRAME 670. A FEW BLISTERS AND PINHOLES WERE NOTED THROUGHOUT THE SIDE. (EXAMPLES IN FRAMES 2226. 2275).
- D. THE PLUS DENSITY AREAS ENUMERATED IN PARAGRAPH 2 COULD BE CAMERA LIGHT LEAKS. ASIDE FROM THIS THERE ARE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.
 - 3. POSITIVE:
- A. THE PI SUITABILITY IS GOOD. PRINTING AND PROCESSING ARE GOOD.
- B. CLOUDS COVER 55-60 PERCENT OF THE MISSION.