

~~CONFIDENTIAL~~

OUT59392

1

Multi

1966 AUG 10 02 46Z

P 100230Z AUG 66
FM NPIC WASH DC
TO AIG NINE SEVEN SIX
RUEKDA/DIA PRODCEN
RUEKDA/NIC
BT

10 AUG 1966

CONFIDENTIAL CITE NPIC 8055.

DISTRIBUTION

INITIAL SCAN BY NPIC OF MISSION [REDACTED]

Cy/No.	Office	Action
1	25X1	
2	OS	
	ADINT	
	SEC BR	
	P & DS 25X1	
3	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
	TID	
4,5	IAD	
6	PAG	
	DIAXX-4	
7	SPAD	
	NSA-LO	
	DIA-AP	

1966 REVEALS THE FOLLOWING INFORMATION ON THE HA NOI/THANH HOA RAIL LINE. THE DONG PHONG THUONG RAIL BRIDGE [REDACTED] AT 1958N 10550E IS UNSERVICEABLE. THE RAIL BY-PASS BRIDGE AT UTM WH892090 IS UNSERVICEABLE DUE TO ONE MISSION SPAN. THE BY-PASS RAIL LINE LEADING TO THIS BRIDGE HAS BEEN INTERDICTED AT LEAST AT ONE POINT. THE BY-PASS RAIL BRIDGE AT UTM WH885090 HAS BEEN ABANDONED WITH MOST OF THE SPANS MISSING. HOWEVER, A SERVICEABLE BY-PASS EXTENDS FROM THE MAIN LINE AT UTM WH887097 TO A SERVICEABLE BRIDGE AT UTM WH863078 TO UTM WH873065 WHERE IT REJOINS THE MAIN RAIL LINE. SERVICEABLE VEHICLE PONTOON BRIDGE LOCATED AT UTM WH884089 AND PERSONNEL/LIGHT VEHICLE PONTOON BRIDGE LOCATED AT UTM WH876084 ARE ALSO OBSERVED.

advance copy
*itized

*seen by D/D, 4/2/98
etc*

[REDACTED] 25X1

23 AUG 1966 25X1

MAP REF: AMS SERIES L701 SHEET 6170I
USATC SERIES 200 SHEET 0617-4HL

GP-1

CONFIDENTIAL --END OF MESSAGE--

S/C NOTE: ALSO PASSED PRIORITY SAIGON INFO [REDACTED] VIENTIANE, UDORN, CLARK FIELD CITE NPIC 8055.

DIRECTOR,

25X1

~~CONFIDENTIAL~~

1