COMPUENTAL

OUT60486

P 252312Z NOV 66 FM NPIC WASH DC TO AIG NINE SEVEN SIX RUEKDA/DIA PRODCEN RUEKDA/NIC BT C O N F I D E N T I A L CITE NPIC 9150. REF A NPIC 8603, DTG 280001Z, SEPT 1966	1966 NOV 25	28 INUV 1966 23 30 Z  DISTRIBUTION  OF Co.   Cifica   Action    File   CS    SEC BR   TDS
B NPIC 8904, DTG 290007Z, OCT 1966		GSD
INITIAL SCAN BY NPIC OF MISSION		25X1_
REVEALS THE PREVIOUSLY REPORTED SERVICEABLE DA	P CAU RAILR	OAD PAG 25X1
AND HIGHWAY BRIDGE OVER THE SONG CAU	AT 2112N	7 SPAD 25X1-
		DIA-AP
10605E (REF A) TO BE UNSERVICEABLE. TWO SPANS HAVE	BEEN DESTR	JYED.
ONE SPAN HAS BEEN DISLOCATED, AND THE NORTHERN APPR	OACH HAS BE	
INTERDICTED. THE RAIL BY-PASS BRIDGE AT XJ131457 H	AS NEVER BE	Sanilizad 🗱
OBSERVED OPERATIONAL BECAUSE OF REMOVED SPANS, A TE	CHNIOUE PRE	VIOUSI Y
DESCRIBED (REF B) TO MAINTAIN THE DECEPTION OF UNSE	RVICEABILIT	Y •
THE MISSING SPANS ON THE BY-PASS BRIDGE ARE IN THE	PROCESS OF	BEING
EMPLACED. ONLY ONCE SPAN IS NOW MISSING AND IT IS	LOCATED ON	A
LARGE AFI NORTH OF THE BRIDGE AT UTM XJ132459. ON	PHOTOGRAPH	Y OF
, TWO SPANS WERE MISSING THEY WERE		
SOUTH BANK OF THE RIVER AT UTM'S XJ132459 AND XJ130	461 AND A L	ARGE
RAFT WAS LOCATED AT UTM XJ129463. (BB)		
		25X1
MAD DEE. AMC CEDIEC 1701A CHEET COS! III		
MAP REF: AMS SERIES L7014 SHEET 6251 III		
USATC SERIES 200 SHEET 0616-20HL GP-1		

CONFIDENTIAL CENDOFFESSAGE-S/C NOTE: ALSO PASSED PRIORITY SAIGON INFO DIRECTOR, VIENTIANE,
UDORN CITE NP Approved For Release 2008/03/12: CIA-RDP78B04558A001500010018-6