

SECRET

PRIORITY

1

OUT60586

1966 DEC 6 16 06Z

P 061541Z DEC 66
 FM NPIC WASHDC
 TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
 RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAAA/2D RTS BARKSDALE AFB LA
 RUEKDA/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF
 RUCVAAA/2 AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 9250.

Declassification Review by NGA/DoD

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)
 2D AF (FOR DI).

1. CAMERA B-15 WAS USED IN MISSION G-931 FLOWN ON 2 DECEMBER 1966. PROCESSING WAS ACCOMPLISHED BY BARKSDALE AFB.

2. ORIGINAL NEGATIVE:

A. DENSITY AND RESOLUTION OF THE MISSION ARE GOOD.

B. 9R SIDE: EDGE STATIC AND ROLLER CHATTER WERE NOTED INTERMITTENTLY THROUGHOUT THE MISSION. A ROW OF MINUS DENSITY DOTS 1.7 INCHES APART IS LOCATED ONE INCH FROM THE OUTBOARD EDGE AND IS PRESENT FROM THE START TO THE END OF THE MISSION. THERE IS AN ULTRA-

SONIC SPLICE BETWEEN FRAMES 1215/1216. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1359 AND IS ACCOMPANIED BY THE NORMAL FOG PATTERN.

C. 9L SIDE: ROLLER CHATTER WAS NOTED THROUGHOUT THE MISSION. EDGE STATIC PRESENT ON BOTH EDGES IS NOT DETECTED AFTER FRAME 1200. IN FRAMES 0001 THROUGH 0010 THERE IS A ROW OF MINUS DENSITY DOTS 1.7 INCHES APART AND 0.9 INCH FROM THE INBOARD EDGE. EMULSION BLISTERS ARE PRESENT IN FRAMES 0010 AND 0011. FRAMES 0235, 0570 AND 0571 CONTAIN EUMULSION GOUGES. MANUFACTURING SPLICES ARE LOCATED BETWEEN

6 DEC 1966

DISTRIBUTION		
Cy No.	Office	Action
1	FRS	
	CS	
	SEC BR	
	TDS	
	GSD	
	IPD	
	PD	
	FSD	
	WFO/CS	
345	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPRO	
	DOTS-0	
	DIA-AP	

1

SECRET

GROUP 1
 Excluded from automatic
 downgrading and
 declassification

-2-

FRAME 0231/0232 AND IN FRAME 1569. BOTH ARE ACCOMPANIED BY ASSOCIATED FOG AND HANDLING MARKS.

D. BOTH SIDES: A FEW FRAMES WERE NOTED AS BEING SMEARED. THIS IS PROBABLY CAUSED BY THE ATTITUDE OF THE VEHICLE. THE LAST TITLED FRAME IS 1704.

E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 50 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-