

STATINTL
STATINTL

SPEED LETTER

REPLY REQUESTED

DATE

18 MAY 1970

YES

NO

LETTER NO.

TO : DESIGN & CONSTRUCTION DIVISION
PSS REGION 3, GSA

FROM:

ATTN: [redacted] / DESIGN BRANCH

SUBJECT: ADDITIONAL SPRINKLER SYSTEM REQUIREMENTS

STAT

1. THE FOLLOWING DECISIONS HAVE BEEN MADE RELATIVE TO THE REQUIREMENT FOR ADDITIONAL SPRINKLER SYSTEMS [redacted]
 - a. [redacted] INSTALLATION - COMMO CENTER (RMS 25451 & 25317) [redacted] SPRINKLER SYSTEMS [redacted] COMPUTER CENTER (RM 25645) [redacted] ARE REQUIRED IN THESE THREE AREAS UTILIZING:
 - (1) HIGH TEMPERATURE SPRINKLER DEFLECTORS, 212°F.
 - (2) CUTOFF VALVES OR SWITCHES ADJACENT TO THE RESPECTIVE AREA ENTRANCE DOORS WITH A TAMPER ALARM CONNECTED TO THE ANNUNCIATOR IN THE SECURITY OFFICE, RM 1N427.
 - b. [redacted] COMPARATON INSTALLATION: NO SPRINKLER SYSTEM WILL BE INSTALLED; HOWEVER, THE INSTALLATION OF SPRINKLER SYSTEMS IN THE ADJACENT GSA SPACES IS HIGHLY DESIRABLE.

STAT
STAT

STAT

STAT

STATINTL

2. FOR ANY FURTHER INFORMATION PLEASE CONTACT THE WRITER [redacted]

[redacted]

REPLY

DATE

STATINTL

STATINTL

STATINTL

STATINTL

Declass Review by NIMA/DOD

ILLEGIB

[redacted]

SIGNATURE