

CENTRAL INTELLIGENCE AGENCY
INFORMATION REPORT

REPORT [redacted]

CD NO. 25X1

COUNTRY Poland

DATE DISTR 23 February 1954

Reference to file # S. POKOJ

NO. OF PAGES

PLACE ACQUIRED

[redacted]

NO. OF ENCLS. LISTED BELOW 25X1

DATE OF INFO.

SUPPLEMENT TO REPORT NO.

THIS REPORT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF TITLE 18, SECTION 793 AND 794 OF THE U.S. CODE AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE DESTRUCTION OF THIS FORM IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

25X1

[redacted]

In April 1952, Polish M/S POKOJ was undergoing her annual refit [redacted] 25X1

[redacted] Among other things, she received a new coat of paint and about 100 new rivets were put into her starboard bilge keel. 25X1

On 20 September 1952, M/S POKOJ was placed into floating dock No 2 in Danzig because water had penetrated into the propeller tube. She left dock on 26 September 1952.

On 30 December 1953, M/S POKOJ was docked [redacted] Three cracks in the raider were welded. The ship left dock on 6 January 1954. 25X1

[redacted]

25X1

CLASSIFICATION		SECRET	
1	2	DISTRIBUTION	
3	4	5	6

CLASSIFICATION SECRET

CENTRAL INTELLIGENCE AGENCY
INFORMATION REPORT

REPORT [REDACTED]

CD NO. 25X1

COUNTRY Poland

DATE DISTR. 23 February 1955

SUBJECT Repairs to the M.S. POKOJ

NO. OF PAGES 1
25X1

PLACE ACQUIRED [REDACTED]
DATE OF INFO. [REDACTED]

NO. OF ENCLS. (LISTED BELOW) 25X1

SUPPLEMENT TO REPORT NO.

[REDACTED]

THIS DOCUMENT CONTAINS INFORMATION ACQUISITIVE TO THE NATIONAL DEFENSE OF THE UNITED STATES. WITHIN THE MEANING OF TITLE 18, SECTION 793 AND 794, OF THE U. S. CODE, AS AMENDED, NO TRANSMISSION OR COMMUNICATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE REPRODUCTION OF THIS FORM IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

25X1

[REDACTED]

- 1. In April 1952, Polish M/S POKOJ was undergoing her annual refit [REDACTED]. Among other things she received a new coat of paint and about 100 new rivets were put into [REDACTED] starboard bilge keel.
- 2. On 20 September 1952, M/S POKOJ was placed into floating [REDACTED] because water had penetrated into the propeller tube. [REDACTED] 26 September 1952.
- 3. On 30 December 1953, M/S POKOJ [REDACTED] Three cracks in the rudder were welded. The ship [REDACTED] 26 January 1954.

25X1

25X1

[REDACTED]

25X1

25X1

STATE		NAVY							
ARMY		AIR							

25X1