

~~TOP SECRET~~
OXCART

EO 12958
3.3(b)(1)>25Yrs
EO 12958 6.2(c)
(N)


Job #69B00404R
Box #1 Folder 25

OXC-1112-67
Copy 6 of 7
6 November 1967

MEMORANDUM FOR THE RECORD

SUBJECT: BX6734 (Incident Concerning)

1. Subject mission was flown successfully on 30 October 1967. An examination of the mission vehicle upon its return to the Kadena Detachment revealed the presence of a single hole, approximately the size which would have been made by a 30.06 shell. This hole was located in a fillet just aft of the starboard landing gear. The pellet which caused the hole penetrated the outer skin, a metallic support which is utilized to stiffen same and also another metallic support for one of the fuel tanks.
2. Attached are two photographs of the aforementioned holes. Exhibit A is a view of the skin fillet from the inner side. Exhibit B is a view of the tank support from the outer side.
3. The aforementioned pellet was previously returned by courier for analysis.



C/OXC/SS/OSA

Attachments
Exhibits A & B

APPROVED FOR RELEASE
DATE: AUG 2007

OXCART
~~TOP SECRET~~

GROUP 1
Excluded from automatic
downgrading and
declassification

~~TOP SECRET~~

OXC-1112-67
Page 2

OSA(6 Nov 67)

Distribution:

- 1-SS/OSA, w/o atts
- 2-D/SA, w/atts
- 3-DD/SA, w/o atts
- 4-D/OPS/OSA, w/o atts
- 5-D/MAT/OSA, w/o atts
- 6-C/OXC/OPS/OSA, w/o atts ✓
- 7-RB/OSA, w/o atts

TOP SECRET