


Top Secret



DIRECTORATE OF
INTELLIGENCE

**Ground Force
Facilities**


Basic Imagery Interpretation Report

Kai-yuan Army Barracks West AL-1

China



25X1



25X1

Top Secret

RCS 07/0035/72
25X1

DATE September 1971

COPY
PAGES 6 **110**

Page Denied

TOP SECRET RUFF

25X1

CENTRAL INTELLIGENCE AGENCY

RCS 07/0035/72

Directorate of Intelligence
Imagery Analysis Service

INSTALLATION NAME AND MILITARY REGION

COUNTRY

Kai-yuan Army Barracks West AL-I, Kun-ming

CH

UTM COORDINATES

GEOGRAPHIC COORDINATES

25X1

N/A

23-43-00N 103-14-40E

MAP REFERENCE

548 RTG. USATC, Series 200, Sheet M0616-2HL, 4th ed, Sep 68, Scale 1:200,000

(SECRET)

25X1

LATEST IMAGERY USED

NEGATION DATE

N/A

25X1

REFERENCE DATA

25X1

REQUIREMENT:

Departmental Requirement Cite: C-SR0-86,301

COMIREX Basic Requirement Cite: G04

Support Number: 422939

NOTE: This report is published as an interim Basic Report with the concurrence of DIA.

25X1

TOP SECRET RUFF

TOP SECRET RUFF

25X1

Location: Kai-yuan Army Barracks West AL-I is located in the center of Kai-yuan.

General: This report is based on a chronological study utilizing the earliest coverage and all subsequent high-resolution photography of the installation. Square footage is shown for barracks, quarters, messhalls and storage facilities.

25X1

25X1

FUNCTIONAL AREAS AND FACILITIES*	DIMENSIONS (FT)**	SUBTOTAL	TOTAL SQUARE FEET
Aa. Billeting Area			
12 Barracks (1-12)			25X1
3 Latrines (13-15)			
Ab. Associated Housing Area			
11 Quarters (21-23,25)	4-100 x 28	10,000	25X1
(18,19)	2-	4,970	25X1
(20)			
(24)			
(16,17)	2-		25X1
(29)		1,820.....	
1 Messhall (27)			25X1
1 Administration bldg (26)			
1 Support bldg (28)			
Ac. Quarters/Administration Area			
7 Quarters (38)			25X1
(31,32,34,36,40,41)	6-		
1 Administration/support bldg (30)			
2 Support bldgs (35,37)			
1 Unidentified bldg (39)			
1 Latrine (33)			
Ad. Administration/Support Area			
1 Multifunctioning administration bldg (49)			
14 Support bldgs (48,50-52,54,55,61,62,64,65,67,68,70,75)			
1 Outdoor theater (63)			
1 Swimming pool (66)			
9 Animal sheds (53,56,57,69,71-74,76)			
1 Parade field (60)			
2 Basketball courts (58,59)			

*All of the buildings identified as barracks may not be used as living quarters.
**The messhall dimensions include only the dining areas.

25X1

25X1

TOP SECRET RUFF


TOP SECRET RUFF

25X1

FUNCTIONAL AREAS AND FACILITIES*	DIMENSIONS (FT)**	SUBTOTAL	TOTAL SQUARE FEET
----------------------------------	-------------------	----------	-------------------

Ae Administration/Billeting Area

- 12 Barracks (77-88)
- 2 Quarters (101,102)
- 1 Messhall (91)
- 1 Storage/support bldg (99)
- 1 Administration bldg (96)
- 1 Administration/support bldg (94)
- 5 Support bldgs (92,93,97,98,100)
- 1 Latrine (89)
- 1 Animal shed (90)
- 1 Basketball court (95)



6,080


25X1
25X1

Af Billeting Area

- 12 Quarters/barracks (116-126,135)
- 1 Quarters/support bldg (131)
- 1 Messhall (134)
- 1 Storage/support bldg (132)
- 4 Support bldgs (127-129,133)
- 1 Latrine (130)



1,920



25X1

25X1

C General Storage Area

- 3 Storage/support bldgs (44,45)
(42)
- 1 Water tower (47)
- 2 Support bldgs (43,46)



25X1

H Support Area

- 1 Auditorium (103)
- 11 Support bldgs (104-113,115)
- 1 Animal shed (114)

*All of the buildings identified as barracks may not be used as living quarters.
**The messhall dimensions include only the dining areas.

TOP SECRET RUFF

25X1

Chronological Listing of Facilities*, Vehicles and Equipment**, and Activity

25X1

Facilities:

Total square footage:

Barracks 50,004

Quarters 37,170

Quarters/barracks [redacted]

Messhalls [redacted]

Storage/support [redacted]

Vehicles and Equipment:

None

Activity:

Area Aa,Ab,Af

Probably occupied; active foot trails and heavy ground scarring in front of the messhalls.

Area Ac

Probably occupied; trees obscure most of the area. Foot trails can be seen in front of a few of the bldgs not blocked by trees.

Area Ad

Active; Basketball courts 58 and 59 are active. A heavily used trail extends across the parade field to Area Af. Entire open area under cultivation.

Area Ae

Probably occupied; foot trails in front of the barracks appear active. Messhall 91 appears to have very little ground scarring in front of it, unlike the rest of the messhalls in the installation.

Area C

Probably active; heavy ground scarring in front of Storage/support bldg 44. The paved road running into the installation ends at Storage/support bldg 44.

Area H

Possibly active; light ground scarring in front of Support bldg III.

Facilities:

Area Ae

1 Admin/support bldg (94)

This bldg is connected by a passageway to Messhall 91.

Vehicles and Equipment:

Area Ae

4 Probable cargo trucks parked in back of Barracks 79 (c)

Activity:

Area Aa,Ab,Ac,Af

No change

Area Ad

Active; the outdoor theater (63) appears to be cluttered with U/I material.

Area Ae

Occupied; heavy ground scarring and clutter surround Admin/support bldg 94, indicating it was recently built.

Areas C,H

No change

No change in facilities. Poor photo quality precluded identification of vehicles and equipment, or determination of the level of activity.

25X1
25X1
25X1

*After initial coverage, facilities are newly constructed unless otherwise indicated.

** (a) Vehicles stored in buildings

(b) Vehicles stored in open

(c) Vehicle storage locations undetermined

25X1

TOP SECRET RUFF

25X1

Chronological Listing of Facilities*, Vehicles and Equipment**, and Activity

25X1

<p><u>Facilities:</u></p> <p>Area Ae 1 Basketball court (95)</p> <p><u>Vehicles and Equipment:</u></p> <p>None</p> <p><u>Activity:</u></p> <p>Areas Aa,Ab,Ac,Ad,Af,C,H No change</p> <p>Area Ae Occupied; the clutter surrounding Admin/support building 94 has been removed. Area in front of Administration bldg 96 is landscaped and well maintained.</p>	<p><u>Facilities:</u></p> <p>Area Ad 1 Support bldg (54)</p> <p>Photography over Areas Aa and Ab was unusable.</p> <p><u>Vehicles and Equipment:</u></p> <p>Area Ae 1 Cargo truck parked in back of Barracks 79 (c)</p> <p><u>Activity:</u></p> <p>Area Ac,Ae No change</p> <p>Area Ad Active; numerous personnel trenches have been dug along the entire length of the south side of the parade field.</p> <p>Area Af Active; a few personnel trenches have been dug along the south edge of the area.</p>	<p><u>Facilities:</u></p> <p>Area Ad 3 Animal sheds (72-74) 1 Support bldg (75)</p> <p>Area Ae 1 Storage/support bldg (99) 6,080</p> <p>Area Af 1 Quarter/support bldg (131) 6,552</p> <p>New Square Footage Total: Storage/support [] Quarters/suppor []</p> <p>Poor photo quality precluded identification of vehicles and equipment or determination of the level of activity.</p>
--	---	---

25X1

*After initial coverage, facilities are newly constructed unless otherwise indicated.

- ** (a) Vehicles stored in buildings
- (b) Vehicles stored in open
- (c) Vehicle storage locations undetermined

TOP SECRET RUFF

25X1

Page Denied

Top Secret



Top Secret