## INFORMATION REPORT INFORMATION REPORT

## CENTRAL INTELLIGENCE AGENCY

OUNTRY		S-E-C-R-E-T					
OUNTRY							
	Czechoslowakia		REPORT				
SUBJECT	Observations at Aircraft Factor	the Rudy Letov II	DATE DISTR.	17 June 1955			
			NO. OF PAGES	2 ,			
DATE OF I	NFO.		REQUIREMENT NO.	RD			
PLACE ACC	QUIRED		REFERENCES				
DATE ACQ	UIRED	This is UNEVALUA	TED Information				
	SOURCE EVALUATIONS	ARE DEFINITIVE. APPRAI	SAL OF CONTENT IS TE	NTATIVE.			
1.	The site of the Rudy Letov Aircraft Factory at Vodochody was observed 18,2C, and 2h January 1955. The following observations were made:  12 (sic) January  1 MIG-15, type unidentified, on the runway opposite the control tower.  1 line of 8 MIGs in front of the revetments; type unidentified.  1 MIG, single seat, covered with canvas, and 1 MIG, two-seater, at the extreme east of the revetments.  3 MIG two-seaters under a sort of portico, at the eastern extremity behind the revetments; then again in back of these, 1 MIG two-seater.  2 MIG single-seaters and 1 MIG of which the back of the fuselage had been removed, making visible the back part of the engine.  The total number of aircraft seen outside the buildings that day was 17 (sic).						
	20 January		the buildings tha				
		fied, on the runway MIGs, type not iden to of these. 5 MIG two-seaters, ad the workshop 2 MI	opposite the cont tified, in front o then 3 MIGs, type Gs, type not ident	rol tower.  f the revetments,  not identified.			
	20 January  1 MIG, type not identi A line of more than 5 then 3 MIGs at the end In back of the hangars Between the hangars ar	fied, on the runway MIGs, type not iden to of these. 5 MIG two-seaters, ad the workshop 2 MI	opposite the cont tified, in front o then 3 MIGs, type Gs, type not ident	rol tower.  f the revetments,  not identified.			
	20 January  1 MIG, type not identi A line of more than 5 then 3 MIGs at the end In back of the hangars Between the hangars ar A total of at least 19  2h January  2 MIGs, type unidentif A line of MIGs, type u	fied, on the runway MIGs, type not iden l of these. 5 MIG two-seaters, d the workshop 2 MI aircraft seen outs fied, on the runway midentified reraft in front of MIGs, two-seater, a ray, being tested;	opposite the contitified, in front of them 3 MIGs, type Gs, type not identified.  opposite the contrate the revetments; at and one one-seater, n back of the revet	rol tower.  If the revetments,  not identified.  If the eastern  Four two-seater			

INFORMATION REPORT INFORMATION REPORT

7, pprovide 1 of 10, locally 2000/07/21 . Girt 10, 10 of 000 to 10, 1000 to 00000 to 0	25 <b>X</b> 1	
S-E-C-R-E-T	:	
	25 <b>X</b> 1	

## General Remarks

2. Certain buildings of the factory have been painted a light green color all over. This is certainly a color for camouflage, because since about the middle of December 1954 a number of buildings, barracks or factories have been painted the same color.

Approved For Release 2008/07/24 : CIA-RDP80-00810A006700690010-5

3. A pipeline is being laid in the east of the field. It cuts the main Prague-Teresin road at right angles 750 meters north of the village of Klicany.

- 2 -

- 4. A new road has been laid out connecting the factory directly with the northwest. The work is temporarily interrupted and the road leads nowhere. The purpose of the establishment of this new route of access is unknown.
- 5. The production of the factory at Vodochody, which at the moment appears to consist only of two-seater MIGs for pilot training, seems less compared with the spring of 1954, when it was not unusual to see 60 or 70 aircraft outside the hangars.

25X1

5-E-C-R-E-T