



U.S. Officials Only

CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY  
**INFORMATION REPORT**

50X1-HUM


COUNTRY Poland  
SUBJECT Port Information: Swinemunde



DATE DISTR. / 8 Mar 1954  
NO. OF PAGES 3  
NO. OF ENCLS.  
SUPP. TO 50X1-HUM  
REPORT NO.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793 AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE REPRODUCTION OF THIS REPORT IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION



THE OFFICE OF NAVAL INTELLIGENCE FURNISHED THE FOLLOWING INFORMATION TO CIA FOR IAC DISSEMINATION IN ACCORDANCE WITH PARAGRAPH 3 c OF NSCID #7 (DIO, 8ND No 6-54).7


50X1-HUM



2. Alphabetical Designators Coordinated with information reported herein, specific points are located on overlay to BA Chart No 185 and identified by the following alphabetical designators:

- A - Approach line
- B - Pilot Boarding point
- C - Polish Police Patrol Station
- D - Anchorage
- E - Antiaircraft Battery
- F - Soviet Naval Facility
- G - Polish Naval Facility

50X1-HUM



U.S. Officials Only

CONFIDENTIAL

DISTRIBUTION →	STATE	ARMY	NAVY	AIR	FBI					
----------------	-------	------	------	-----	-----	--	--	--	--	--

This report is for the use within the USA of the Intelligence components of the Departments or Agencies indicated above. It is not to be transmitted overseas without the concurrence of the originating office through the Assistant Director of the Office of Collection and Dissemination, CIA.

50X1-HUM

65

CONFIDENTIAL/US OFFICIALS ONLY

- 2 -

50X1-HUM

6. [REDACTED]
7. Anchorage An anchorage point is located about 500 yards off the entrance to the port at designator B. Another anchorage is situated at point D [REDACTED] 50X1-HUM  
[REDACTED] The anchorage at Point D was small in area, had good holding ground in about 24' of water. 50X1-HUM
8. [REDACTED]
9. Channel depth Average depth of water [REDACTED] was 24'.
10. Traffic Restrictions When tankers are underway in the channel out of Stettin all incoming shipping is halted at Swinemunde. 50X1-HUM
11. Shipping Observed Three merchant vessels were observed standing out of port [REDACTED] 10 more were sighted waiting to enter. 50X1-HUM
12. Patrol Station A Polish harbor police patrol station is located at point C.
13. Coastal Defense Battery [REDACTED] 50X1-HUM  
[REDACTED] a radar controlled coastal defense battery is located at designator E. This battery, thought to be an old German installation, is arranged in single mounts with slit trenches connecting. Ordnance consisted of four guns of 8.8 cm barrel diameter and three guns of 21 cm barrel diameter. 50X1-HUM
14. Fire Control Radar The coastal defense battery described in paragraph 13 was accompanied by fire control radar with antennas mounted on each gun. The antenna consisted of parabolic reflectors with diapoles in the center.
15. Naval Facilities A naval facility and docking area is located on either side of the channel near the entrance to the port. At designator F is located a berthing area for Soviet naval vessels and designator G a berthing area for Polish naval vessels.
16. Soviet Naval Vessels Sighted Berthed at designator F were three Soviet destroyers. They were described as small, one funnel, single-mast craft, having a mattress type radar reflector antenna and two 12.7 cm main battery guns mounted in single enclosures fore and aft. They [REDACTED] appeared to resemble AMC No 105, the KRONSTADT class, more than other types. Also berthed at designator F were about 20 Soviet PT boats described as having two torpedo tubes, flying bridge and two small caliber automatic guns aft. They were identified as members of the VOSPER class. 50X1-HUM
17. Polish Naval Vessels Sighted At designator G a very old Polish AMS type vessel was berthed. This was believed to be an ex-German craft.
18. Status of Naval Units Both Polish and Soviet vessels were observed to be fully operational and were believed to be frequently employed. Their general condition was fair, though some hull plates showed minor signs of wear and buckling. Personnel aboard were thought to be in excess of normal complements and appeared to superabound on vessels sighted.

CONFIDENTIAL/US OFFICIALS ONLY

CONFIDENTIAL/US OFFICIALS ONLY

50X1-HUM

- 3 -

19. New Construction and Repair [redacted] the three existing German air raid shelters at the naval facility appeared to have been repaired and in good usable condition and that two new shelters had been erected and completed recently. 50X1-HUM



50X1-HUM

CONFIDENTIAL/US OFFICIALS ONLY

**Page Denied**




A




B

C



D

B



E  
F  
G



SWINEMUNDE  
BA-185

