

K-7087  
UE 517A/1

NPIC/CSD-43/66  
23 JANUARY 1966  
PAGE 3

Declassification Review by NGA/DoD

BRIDGE BY-PASSES  
ROUTE 1A, NORTH VIETNAM

SIGNIFICANCE:

THIS BRIEFING BOARD DEPICTS TWO DESTROYED HIGHWAY BRIDGES WHICH ARE BEING BY-PASSED.

REMARKS:

IN AN EFFORT TO KEEP ROUTE 1A OPEN TO CONVOY TRAFFIC, MANY OF THE DESTROYED OR DAMAGED BRIDGES ALONG THIS ROUTE ARE BEING BY-PASSED BY TEMPORARY BRIDGES AND FORDS.

MISSION READOUT:

MAC KHE  
1810N 10613E

UE 517A/1, 12 JANUARY 1966, REVEALS THAT THE DESTROYED MAC KHE HIGHWAY BRIDGE OVER THE KHE CAU NU  IS 25X1 BEING BY-PASSED BY A TEMPORARY BRIDGE LOCATED JUST TO THE NORTH. THIS TEMPORARY BRIDGE HAS AGGREGATE APPROACHES AND A WOODEN CENTER SPAN. A BY-PASS FORD IS NOTED JUST NORTH OF THE TEMPORARY BRIDGE.

SON KINH  
1811N 10611E

UE 517A/1, 12 JANUARY 1966, REVEALS A SERVICEABLE, TEMPORARY WOODEN DECK BRIDGE JUST SOUTH OF THE DESTROYED SON KINH HIGHWAY BRIDGE. A SECOND BRIDGE IS NOTED JUST NORTH OF THE

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

**CONFIDENTIAL**

K-7087  
UE 517A/1

NPIC/CSD-43/66  
23 JANUARY 1966  
PAGE 4

DESTROYED BRIDGE AND APPEARS TO HAVE AGGREGATE APPROACHES  
AND A WOODEN CENTER SPAN.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

**CONFIDENTIAL**

CONFIDENTIAL



NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

# BRIDGE BY-PASSES ROUTE 1A, NORTH VIETNAM



25X11



25X11