COLING RY	Cermany (Soviet Zone) (Soviet Zone)
TOPIC on an annual and an annual and an	Soviet 100th Motor Vehicle Repair Shop in Dresden
Company on a construction of the supplemental and t	
WALUATION	
DATE OF CONT	25X1A 25X1A
DATE OBTAINE	DATE PREPARED
	2 ENCLOSURES (NO. & TYPE)
REMARKS	
Newton () white excellentation to horizontage attention to the ending of the con-	
destination in the selection of the sele	
COLLEGE OF SECURE SECURE (FINANCIA SECURE)	-25X1X
SOURCE	
25X1C	Between 15 and 18 April 1951, the Soviet 100th Motor Vehicle Repair Shop, was located in the northwestern section of the Koenig Georg Kaserne on Hammerweg, Dresden. The repair shop was operated by about 450 troops, mostly of the 1915 through 1918 classes, who were organized into three companies. All of the troops were skilled workmen, The repair shop, which had the cover designation XI/2 in correspondence with German firms, had its own ration supply point. *
2.	The repair shop, which was assigned exclusively to the repair of wheeled vehicles, was made up of a fitting shop, a body shop, a varnishing shop, a spray-painting shop, a leather-working shop, a carpenter shop, a cylinder-grinding shop and a test stand. Most of the spare parts which could not be produced on the spot were dedivered by the Phaenomen Firm in Zittau and the BLW Firm in Eisenach.
3.	Towns from which the repair shop received vehicles for overhauling included Dresden, Heissen, Grossenhain, Oschatz, Lomatzsch, Koenigsbrueck, Kamenz, Freiberg, Pirna, Bischofswerda, Annaberg, Sebnitz, Bad Schandau and Rechenberg-Bienen muehle. The repair slips on the vehicles bore only cover designations, such as XV, XXII, IX/2 and X/4,
Ą.	
25X1B	

Approved For Release 2001/03/06 · CIA-RDP82-00457R008100830004-1

Approved For Release 2001/03/06: CIA-RDP82-00457R008100830004-1



25X1C

Comment. The repair shop was last identified at 5 Hammerweg, Dresden, in March 1949. The was also mentioned in connection with a shipment of motor vehicles which went from Eberswalde to Dresden in August 1949.

Comment.

as they are usually given for security reasons to vehicles under repair.

25X1A[™]

as they 25X1C repair.